Table of Contents

Dedication iii
Preface xxi

Chapter 1: Introduction

Introduction to Autodesk Inventor 2015 1-2
Part Module 1-2
Assembly Module 1-2
Presentation Module 1-3
Drawing Module 1-3
Sheet Metal Module 1-3
Mold Design Module 1-3
Getting Started with Autodesk Inventor 1-3
Quick Access Toolbar 1-6
Ribbon and Tabs 1-7
Sketch Tab 1-8
3D Model Tab 1-9
Sheet Metal Tab 1-9
Assemble Tab 1-9
Place Views Tab 1-9
Presentation Tab 1-10
Tools Tab 1-10
View Tab 1-10
Navigation Bar 1-11
Browser Bar 1-11
Units for Dimensions 1-12
Important Terms and Their Definitions 1-12
Feature-based Modeling 1-12
Parametric Modeling 1-12
Bidirectional Associativity 1-12
Adaptive 1-12
Design Doctor 1-13
Constraints 1-13
Joints 1-15
Consumed Sketch 1-16
Stress Analysis Environment 1-16
Select Other Behavior 1-17
Hotkeys 1-17
Part Module 1-17
Assembly Module 1-18
Drawing Module 1-19
Customizing Hotkeys 1-19
Creating the Sketch 1-21
Marking Menu 1-21

Enhanced

Color Scheme 1-22
Self-Evaluation Test 1-23
Review Questions 1-24

Chapter 2: Drawing Sketches for Solid Models

The Sketching Environment 2-2
The Initial Screen of Autodesk Inventor Enhanced 2-2
Starting a New File 2-4
The Open Dialog Box 2-5
Setting a New Project 2-7
Import DWG 2-8
Invoking the Sketching Environment 2-8
Introduction to the Sketching Environment 2-8
Setting Up the Sketching Environment 2-9
Modifying the Document Settings of a Sketch 2-9
Sketching Entities 2-11
Positioning Entities by Using Dynamic Input 2-11
Drawing Lines 2-12
Drawing Circles 2-16
Drawing Ellipses 2-17
Drawing Arcs 2-17
Drawing Rectangles 2-19
Drawing Polygons 2-22
Drawing Slots 2-23
Placing Points 2-25
Creating Fillets 2-26
Creating Chamfers 2-27
Drawing Splines 2-28
Deleting Sketched Entities 2-31
Finishing a Sketch 2-32
Understanding the Drawing Display Tools 2-32
Zoom All 2-32
Zoom 2-32
Zoom Window 2-33
Zoom Selected 2-33
Pan 2-33
Orbit 2-33
Constrained Orbit 2-34
Tutorial 1 2-35
Tutorial 2 2-40
Tutorial 3 2-44
Tutorial 4 2-49
Self-Evaluation Test 2-52
Review Questions 2-53
Exercise 1 2-54

Exercise 2 2-54
Exercise 3 2-55
Exercise 4 2-55

Chapter 3: Adding Constraints and Dimensions to Sketches

Adding Geometric Constraints to a Sketch 3-2
Perpendicular Constraint 3-2
Parallel Constraint 3-2
Tangent Constraint 3-3
Coincident Constraint 3-3
Concentric Constraint 3-3
Collinear Constraint 3-4
Horizontal Constraint 3-4
Vertical Constraint 3-5
Equal Constraint 3-5
Fix Constraint 3-5
Symmetric Constraint 3-5
Smooth Constraint 3-6
Viewing the Constraints Applied to a Sketched Entity 3-6
Controlling Constraints and Applying them Automatically while Sketching 3-7
Constraints Settings Dialog Box Enhanced 3-7
Scope of Constraint Inference New 3-8
Deleting Geometric Constraints 3-9
Adding Dimensions to Sketches 3-9
Linear Dimensioning 3-10
Aligned Dimensioning 3-11
Angular Dimensioning 3-12
Diameter Dimensioning 3-14
Radius Dimensioning 3-15
Linear Diameter Dimensioning 3-16
Setting the Scale of a Sketch 3-17
Creating Driven Dimensions 3-18
Understanding the Concept of Fully-Constrained Sketches 3-18
Measuring Sketched Entities 3-19
Measuring Distances 3-19
Measuring Angles 3-21
Measuring Loops 3-22
Measuring the Area 3-22
Adding Linear Measurements 3-23
Clearing Accumulated Dimensions 3-23
Evaluating Region Properties 3-23
Tutorial 1 3-24
Tutorial 2 3-29
Tutorial 3 3-34
Tutorial 4 3-40
Self-Evaluation Test 3-43

Review Questions 3-44
Exercise 1 3-45
Exercise 2 3-45
Exercise 3 3-46
Exercise 4 3-46
Exercise 5 3-47
Exercise 6 3-47

Chapter 4: Editing, Extruding, and Revolving the Sketches

Editing Sketched Entities 4-2
Extending Sketched Entities 4-2
Trimming Sketched Entities 4-2
Splitting Sketched Entities 4-3
Offsetting Sketched Entities 4-4
Mirroring Sketched Entities 4-5
Moving Sketched Entities 4-7
Rotating Sketched Entities 4-9
Creating Patterns 4-11
Creating Rectangular Patterns 4-11
Creating Circular Patterns 4-15
Writing Text in the Sketching Environment 4-17
Writing Regular Text 4-17
Writing Text Aligned to a Geometry 4-20
Inserting Images and Documents in Sketches 4-21
Editing Sketched Entities by Dragging 4-22
Tolerances 4-23
Converting the Base Sketch into a Base Feature 4-24
Extruding the Sketch 4-25
Revolving the Sketch 4-29
Direct Manipulation of Features by Using the Mini Toolbar 4-32
Command Options 4-32
Manipulators 4-32
Rotating the View of a Model in 3D Space 4-33
Rotating the View of a Model Using the Orbit 4-34
Changing the View Using the ViewCube 4-35
Navigating the Model 4-38
Controlling the Display of Models 4-39
Setting the Visual Styles 4-39
Setting the Shadow Options 4-41
Setting the Camera Type 4-42
Creating Freeform Shapes New 4-42
Tutorial 1 4-46
Tutorial 2 4-50
Tutorial 3 4-53
Tutorial 4 4-58
Self-Evaluation Test 4-60

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Review Questions 4-61
Exercise 1 4-63
Exercise 2 4-63
Exercise 3 4-64
Exercise 4 4-64
Exercise 5 4-65
Exercise 6 4-65
Exercise 7 4-66

Chapter 5: Other Sketching and Modeling Options

Need for other Sketching Planes 5-2
Work Features 5-3
    Creating Work Planes 5-3
    Creating Work Axes 5-13
    Creating Work Points 5-17
Other Extrusion Options 5-22
Other Revolution Options 5-28
The Concept of Sketch Sharing 5-30
Tutorial 1 5-31
Tutorial 2 5-37
Tutorial 3 5-41
Self-Evaluation Test 5-46
Review Questions 5-46
Exercise 1 5-48
Exercise 2 5-48
Exercise 3 5-50
Exercise 4 5-51

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools 6-2
    Creating Holes 6-2
    Creating Fillets 6-12
    Creating Chamfers 6-23
    Mirroring Features and Models 6-26
    Creating Rectangular Patterns 6-29
    Creating Circular Patterns 6-32
    Creating Rib Features 6-34
    Thickening or Offsetting the Faces of Features 6-38
    Creating the Embossed and Engraved Features 6-42
    Applying Images on a Feature 6-44
Assigning Different Colors/Styles to a Model 6-45
Assigning Material to a Model 6-46
    Modifying the Properties of an Existing Material 6-46
Tutorial 1 6-48
Tutorial 2 6-54

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Tutorial 3 6-60
Tutorial 4 6-67
Tutorial 5 6-71
Self-Evaluation Test 6-78
Review Questions 6-78
Exercise 1 6-80
Exercise 2 6-81
Exercise 3 6-82

Chapter 7: Editing Features and Adding Automatic Dimensions to Sketches

Concept of Editing Features 7-2
Editing Features of a Model 7-2
Updating Edited Features 7-4
Editing Features Dynamically by Using 3D Grips 7-4
Editing the Sketches of Features 7-6
Redefining the Sketching Plane of a Sketched Feature 7-8
Suppressing and Unsuppressing the Features 7-9
Editing of a feature using the Direct Tool New 7-10
Deleting Features 7-12
Copying and Pasting Features 7-12
Manipulating Features by EOP 7-15
Adding Automatic Dimensions to Sketches 7-16
Projecting Entities in the Sketching Environment 7-17
Projecting Edges or Faces 7-17
Projecting Cutting Edges 7-18
Projecting 2D Sketch on 3D Face 7-19
Tutorial 1 7-20
Tutorial 2 7-27
Tutorial 3 7-32
Self-Evaluation Test 7-38
Review Questions 7-39
Exercise 1 7-40
Exercise 2 7-41
Exercise 3 7-42
Exercise 4 7-43
Exercise 5 7-44

Chapter 8: Advanced Modeling Tools-II

Advanced Modeling Tools 8-2
Creating Sweep Features Enhanced 8-2
Creating Lofted Features 8-10
Creating Coil Features 8-21

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Creating Threads 8-25
Creating Shell Features 8-28
Applying Drafts 8-30
Creating Split Features 8-34
Trimming Surfaces 8-36
Extending Surfaces 8-38
Deleting Faces 8-39
Replacing Faces with Surfaces 8-41
Creating Planar Boundary Patches 8-42
Stitching Surfaces 8-44
Working with the Sculpt Tool 8-45
Working with the Bend Part Tool 8-47
Reordering the Features 8-49
Using the Sketch Doctor 8-51
Using the Design Doctor 8-52
Tutorial 1 8-53
Tutorial 2 8-57
Tutorial 3 8-60
Tutorial 4 8-62
Tutorial 5 8-65
Self-Evaluation Test 8-69
Review Questions 8-69
Exercise 1 8-71
Exercise 2 8-72

Chapter 9: Assembly Modeling-I

Assembly Modeling 9-2
Types of Assemblies 9-2
Top-down Assemblies 9-3
Bottom-up Assemblies 9-3
Creating Top-down Assemblies 9-4
Creating Components in the Assembly Module 9-4
Creating Bottom-Up Assemblies 9-7
Placing Components in the Assembly File 9-7
Assembling Components by Using the Constrain Tool 9-8
Assembly Tab 9-9
Motion Tab 9-17
Transitional Tab 9-19
Constraint Set Tab 9-20
Specifying the Limits for Constraining 9-20
Assembling Parts by Using the Assemble Tool 9-21
Using ALT+Drag to Apply Assembly Constraints 9-23
Applying Joints to the Assembly 9-23
Joint Tab 9-23
Limits Tab 9-28

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Showing and Hiding Relationships 9-28
Show Relationship 9-29
Hide Relationship 9-29
Show Sick Relationship 9-29
Moving Individual Components 9-29
Rotating Individual Components in 3D Space 9-30
Tutorial 1 9-30
Tutorial 2 9-46
Tutorial 3 9-53
Self-Evaluation Test 9-63
Review Questions 9-64
Exercise 1 9-65

Chapter 10: Assembly Modeling-II

Editing Assembly Constraints 10-2
Editing Components 10-3
Editing Components in the Assembly File 10-3
Editing Components by Opening their Part Files 10-5
Creating Subassemblies 10-5
Creating a Subassembly Using the Bottom-up Design Approach 10-6
Creating a Subassembly Using the Top-down Design Approach 10-6
Checking Degrees of Freedom of a Component 10-6
Creating the Pattern of Components in an Assembly 10-7
Component 10-7
Associative Tab 10-8
Rectangular Tab 10-9
Circular Tab 10-9
Replacing a Component from the Assembly File with another Component 10-10
Replacing a Single Instance of the Selected Component 10-10
Replacing all Instances of the Selected Component 10-11
Mirroring Subassemblies or Components of an Assembly 10-12
Copying Subassemblies or Components of an Assembly 10-15
Deleting Components 10-16
Editing the Pattern of Components 10-16
Making a Pattern Instance Independent 10-17
Deleting Assembly Constraints 10-17
Creating Assembly Section Views in the Assembly File 10-18
Analyzing Assemblies for Interference 10-19
Creating Design View Representations 10-20
Design View Representation Area 10-21
Positional Representation Area 10-22
Level of Detail Representation 10-22
Simulating the Motion of Components of an Assembly by Driving Assembly Constraints 10-22
Creating Positional Representations 10-25
Viewing the Bill of Material of the Current Assembly 10-26

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Working with Assembly Features 10-28
Tutorial 1 10-28
Tutorial 2 10-31
Tutorial 3 10-32
Self-Evaluation Test 10-38
Review Questions 10-39
Exercise 1 10-40

Chapter 11: Working with Drawing Views-I

The Drawing Module 11-2
Types of Views 11-3
Generating Drawing Views 11-5
    Generating the Base View 11-5
    Generating Projected Views 11-10
    Generating Auxiliary Views 11-12
    Generating Section Views 11-13
    Generating Detail Views 11-15
    Generating Broken Views 11-17
    Generating Break Out Views 11-19
    Generating Overlay Views 11-21
    Generating Slice Views 11-23
Drafting Drawing Views 11-24
Editing Drawing Views 11-24
Deleting Drawing Views 11-25
Moving Drawing Views 11-27
Copying Drawing Views 11-27
Rotating Drawing Views 11-27
Changing the Orientation of Drawing Views 11-29
Assigning Different Hatch Patterns to Components in Assembly Section Views 11-29
Editing the Default Hatch Style of the Sectioned Objects 11-32
Excluding Components from Assembly Section Views 11-33
Tutorial 1 11-35
Tutorial 2 11-40
Self-Evaluation Test 11-46
Review Questions 11-46
Exercise 1 11-48

Chapter 12: Working with Drawing Views-II

Modifying Drawing Standards 12-2
Inserting Additional Sheets into Drawing 12-3
Activating a Drawing Sheet 12-3
Displaying Dimensions in Drawing Views 12-3
    Retrieving Parametric Dimensions in Drawing Views 12-4
    Adding Reference Dimensions 12-5
Modifying the Model Dimensions 12-5

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Editing Drawing Sheets 12-5
Creating Dimension Styles 12-7
Applying Dimension Styles 12-8
Modifying a Dimension and its Appearance Using the Shortcut Menu 12-8
Adding the Parts List 12-9
Source Area 12-9
BOM Settings and Properties Area 12-10
Table Wrapping Area 12-10
Editing the Parts List 12-11
Column Chooser 12-12
Group Settings 12-12
Filter Settings 12-13
Sort 12-13
Export 12-13
Table Layout 12-13
Renumber Item 12-14
Save Item Overrides to BOM 12-14
Member Selection 12-14
Adding/Removing Custom Parts 12-14
Shortcut Menu Options 12-14
Setting the Standard for the Parts List 12-15
Adding Balloons to Assembly Drawing Views 12-15
Adding Balloons to Selected Components 12-16
Adding Automatic Balloons 12-17
Adding Text to a Drawing Sheet 12-19
Adding Multiline Text without a Leader 12-19
Adding Multiline Text with Leader 12-20
Tutorial 1 12-21
Tutorial 2 12-26
Tutorial 3 12-31
Self-Evaluation Test 12-36
Review Questions 12-36
Exercise 1 12-37

Chapter 13: Presentation Module

The Presentation Module 13-2
Creating the Presentation View 13-3
Assembly Area 13-3
Explosion Method Area 13-4
Defining Units for Presentation Files 13-6
Tweaking Components in the Presentation View 13-6
Create Tweak Area 13-6
Transformations Area 13-8
Animating an Assembly 13-9
Rotating the Presentation View Precisely 13-15
Tutorial 1 13-16

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Tutorial 2 13-23
Self-Evaluation Test 13-29
Review Questions 13-30
Exercise 1 13-31

Chapter 14: Working with Special Design Tools

Adaptive Parts 14-2
Defining Parameters Enhanced 14-2
Working with iParts 14-7
Types of iPart Factories 14-7
Creating iPart Factories 14-7
Procedure to Create an iPart 14-13
Inserting an iPart into an Assembly 14-14
Changing the iParts in the Assembly File 14-17
Creating 3D Sketches 14-18
Line 14-18
Spline 14-19
Bend 14-19
Include Geometry 14-19
Intersection Curve 14-19
Helical Curve 14-20
Tutorial 1 14-21
Tutorial 2 14-25
Tutorial 3 14-31
Tutorial 4 14-34
Tutorial 5 14-38
Self-Evaluation Test 14-45
Review Questions 14-46
Exercise 1 14-47

Chapter 15: Working with Sheet Metal Components

The Sheet Metal Module 15-2
Setting Sheet Metal Component Parameters 15-4
Setting the Sheet Metal Rule 15-4
Setting the Material Style 15-12
Setting the Unfolding Rule 15-12
Creating Sheet Metal Components 15-14
Folding Sheet Metal Components 15-18
Adding Flanges to Sheet Metal Components 15-20
Creating Cuts in Sheet Metal Components 15-25
Creating Seams at the Corners of Sheet Metal Components 15-26
Bending the Faces of a Sheet Metal Component 15-31
Rounding the Corners of Sheet Metal Components 15-33
Chamfering the Corners of Sheet Metal Components 15-35
Punching 3D Shapes into Sheet Metal Components 15-36

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Creating Hems 15-39
Creating Contour Flanges 15-41
Creating the Flat Patterns of Sheet Metal Components 15-44
Adding or Removing Material from the Flat Pattern 15-44
Tutorial 1 15-45
Tutorial 2 15-52
Self-Evaluation Test 15-58
Review Questions 15-59
Exercise 1 15-60

Chapter 16: Introduction to Weldments

Understanding Weldment Assemblies 16-2
Main Types of Welds in Autodesk Inventor 16-3
Cosmetic Welds 16-3
Fillet Welds 16-4
Groove Welds 16-4
Adding Welds to Assemblies 16-5
Assembling the Components of Weldment Assemblies 16-5
Preparing Assemblies for Weldments 16-6
Adding Welds 16-6
Creating Fillet Welds 16-6
Creating Cosmetic Welds 16-8
Creating Groove Welds 16-10
Creating Symbols 16-11
Creating Report 16-11
Tutorial 1 16-12
Tutorial 2 16-17
Self-Evaluation Test 16-21
Review Questions 16-22
Exercise 1 16-23

Chapter 17: Miscellaneous Tools

Introduction 17-2
Copying the Sketches 17-2
Scaling the Sketches 17-3
Finding the Center of Gravity 17-3
Extracting the iFeature 17-4
Inserting the iFeature 17-6
Creating iMates 17-7
Applying iMates in the Assembly Environment 17-9
Interactively place with iMates 17-9
Automatically generate iMates on place 17-9
Viewing the iProperties 17-9
Creating User-Defined Drawing Sheets 17-11
Importing AutoCAD Blocks into Inventor 17-18

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Tutorial 1 17-21
Tutorial 2 17-26
Self-Evaluation Test 17-30
Review Questions 17-30
Exercise 1 17-32

Chapter 18: Introduction to Stress Analysis

Introduction to FEA 18-2
Types of Engineering Analysis 18-3
Structural Analysis 18-3
Thermal Analysis 18-4
Fluid Flow Analysis 18-5
Electromagnetic Field Analysis 18-5
Coupled Field Analysis 18-5
General Procedure to Conduct Finite Element Analysis 18-5
FEA Through Software 18-6
Important Terms and Definition 18-7
Strength 18-7
Load 18-7
Stress 18-7
Strain 18-8
Elastic Limit 18-8
Ultimate Strength 18-8
Factor of Safety 18-9
Lateral Strain 18-9
Poisson' Ratio 18-9
Bulk Modulus 18-9
Stress Concentration 18-9
Bending 18-9
Bending Stress 18-9
Creep 18-10
Degrees of Freedom 18-10
Stress Analysis in Autodesk Inventor 2015 18-10
Creating Simulation 18-11
Using the Guide Tool 18-14
Applying Stress Analysis Settings 18-14
Stress Analysis Browser Bar 18-15
Assigning Material 18-16
Assign Material 18-16
Applying Constraints 18-18
Fixed 18-18
Pin 18-19
Frictionless 18-20
Applying Loads 18-20
Force 18-20
Pressure 18-22

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Bearing Load 18-23
Moment 18-23
Gravity 18-24
Remote Force 18-24
Body 18-25
Meshing the Component 18-26
Mesh View 18-26
Mesh Setting 18-26
Local Mesh Control 18-28
Convergence Setting 18-29
Solution Phase of Analysis 18-30
Postprocessing the Solutions 18-30
Generating Report 18-31
Animating the Result 18-32
Tutorial 1 18-33
Tutorial 2 18-38
Tutorial 3 18-43
Self-Evaluation Test 18-54
Review Questions 18-54
Exercise 1 18-55
Exercise 2 18-56

Chapter 19: Introduction to Plastic Mold Design

Introduction to Plastic Mold Design 19-2
Invoking the Mold Design Environment 19-2
Methods of Designing Core and Cavity 19-2
Importing Plastic Part in Mold Environment 19-3
Adding Core and Cavity 19-4
Adjusting Orientation and Position of the Part 19-5
Adjusting Orientation of the Part 19-5
Adjusting Position of the Part 19-6
Selecting Material 19-8
Commonly Used Material 19-8
Specific Material 19-8
Details 19-9
Report 19-10
Creating Core and Cavity for the Part 19-11
Adjusting Orientation 19-11

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Specifying Gate Location 19-11
Settings for the Process 19-15
Analyzing Part for Filling 19-17
Specifying Shrinkage Allowance 19-17
Defining Workpiece 19-19
Creating Patching Surface 19-21
Creating Planar Patches 19-22
Creating Runoff Surface 19-22
Generating Core and Cavity 19-23
Creating Pattern of the Mold 19-26
Creating a Rectangular Pattern 19-26
Creating a Circular Pattern 19-26
Creating a Variable Pattern 19-27
Creating Runner of the Mold 19-28
Creating Runner Sketch 19-28
Creating Runner 19-30
Creating Gates for the Molds 19-31
Placement 19-33
Copy of all Pockets 19-33
Adding Cold Wells 19-33
Adding Mold Base to the Assembly 19-33
Standard Area 19-34
Placement Area 19-35
Layout Information Area 19-36
Adding Sprue Bushing 19-36
Adding Cooling Channel 19-37
Generating Drawing Views 19-38
Tutorial 1 19-39
Self-Evaluation Test 19-59
Review Questions 19-59
Exercise 1 19-60

Index **I-1**

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com