

Table of Contents

| | |
|-------------------|------|
| Dedication | iii |
| Preface | xvii |

Chapter 1: Introduction to CATIA V5-6R2014

| | |
|---|------|
| Introduction to CATIA V5-6R2014 | 1-2 |
| CATIA V5 Workbenches | 1-2 |
| System Requirements | 1-4 |
| Getting Started with CATIA V5-6R2014 | 1-4 |
| Important Terms and Definitions | 1-6 |
| Understanding the Functions of the Mouse Buttons in CATIA | 1-12 |
| Toolbars | 1-13 |
| Hot Keys | 1-26 |
| Color Scheme | 1-27 |
| Self-Evaluation Test | 1-29 |
| Review Questions | 1-30 |

Chapter 2: Drawing Sketches in the Sketcher Workbench-I

| | |
|--|------|
| The Sketcher Workbench | 2-2 |
| Starting a New File | 2-2 |
| Invoking the Sketcher Workbench | 2-5 |
| Invoking the Sketcher Workbench Using the Sketch Tool | 2-5 |
| Invoking the Sketcher Workbench Using the Positioned Sketch Tool | 2-6 |
| Setting the Sketcher Workbench | 2-6 |
| Modifying Units | 2-6 |
| Modifying the Grid Settings | 2-7 |
| Understanding Sketcher Terms | 2-8 |
| Specification Tree | 2-8 |
| Grid | 2-10 |
| Snap to Point | 2-10 |
| Construction/Standard Element | 2-10 |
| Select Toolbar | 2-10 |
| Inferencing Lines | 2-12 |
| Drawing Sketches Using Sketcher Tools | 2-13 |
| Drawing Lines | 2-13 |
| Drawing Center Lines | 2-17 |
| Drawing Rectangles, Oriented Rectangles, and Parallelograms | 2-17 |
| Drawing Rectangles | 2-18 |
| Creating Points | 2-20 |
| Drawing Circles | 2-21 |
| Drawing Arcs | 2-23 |
| Drawing Profiles | 2-25 |
| Drawing Display Tools | 2-27 |
| Fit All In | 2-27 |
| Pan | 2-28 |

| | |
|--|------|
| Zoom In | 2-28 |
| Zoom Out | 2-28 |
| Zoom Area | 2-29 |
| Normal View | 2-29 |
| Splitting the Drawing Area into Multiple Viewports | 2-29 |
| Hiding and Showing Geometric Elements | 2-29 |
| Swapping Visible Space | 2-30 |
| Tutorial 1 | 2-30 |
| Tutorial 2 | 2-34 |
| Tutorial 3 | 2-38 |
| Tutorial 4 | 2-43 |
| Self-Evaluation Test | 2-47 |
| Review Questions | 2-47 |
| Exercise 1 | 2-48 |
| Exercise 2 | 2-49 |
| Exercise 3 | 2-50 |
| Exercise 4 | 2-50 |
| Exercise 5 | 2-51 |
| Exercise 6 | 2-51 |

Chapter 3: Drawing Sketches in the Sketcher Workbench-II

| | |
|---|------|
| Other Sketching Tools in the Sketcher Workbench | 3-2 |
| Drawing Conics | 3-2 |
| Drawing Splines | 3-6 |
| Connecting Two Elements by a Spline or an Arc | 3-6 |
| Drawing Elongated Holes | 3-8 |
| Drawing Cylindrical Elongated Holes | 3-8 |
| Drawing Keyhole Profiles | 3-9 |
| Drawing Hexagons | 3-10 |
| Drawing Centered Rectangles | 3-10 |
| Drawing Centered Parallelograms | 3-11 |
| Editing and Modifying Sketches | 3-11 |
| Trimming Unwanted Sketched Elements | 3-12 |
| Extending Sketched Elements | 3-13 |
| Trimming by Using the Quick Trim Tool | 3-14 |
| Filleting Sketched Elements | 3-15 |
| Chamfering Sketched Elements | 3-16 |
| Mirroring Sketched Elements | 3-17 |
| Mirroring Elements without Duplication | 3-18 |
| Translating Sketched Elements | 3-18 |
| Rotating Sketched Elements | 3-19 |
| Scaling Sketched Elements | 3-20 |
| Offsetting Sketched Elements | 3-20 |
| Modifying Sketched Elements | 3-21 |
| Deleting Sketched Elements | 3-24 |
| Tutorial 1 | 3-24 |
| Tutorial 2 | 3-29 |

| | |
|----------------------|------|
| Tutorial 3 | 3-33 |
| Self-Evaluation Test | 3-36 |
| Review Questions | 3-37 |
| Exercise 1 | 3-38 |
| Exercise 2 | 3-38 |
| Exercise 3 | 3-39 |
| Exercise 4 | 3-39 |
| Exercise 5 | 3-40 |

Chapter 4: Constraining Sketches and Creating Base Features

| | |
|--|------|
| Constraining Sketches | 4-2 |
| Concept of Constrained Sketches | 4-2 |
| Iso-Constraint | 4-2 |
| Under-Constraint | 4-2 |
| Over-Constrained | 4-3 |
| Inconsistent | 4-3 |
| Not Changed | 4-3 |
| Applying Constraints | 4-3 |
| Applying Geometrical Constraints Automatically | 4-3 |
| Applying Additional Constraints to the Sketch | 4-4 |
| Applying Dimensional Constraints | 4-7 |
| Applying Contact Constraints | 4-12 |
| Applying Fix Together Constraints | 4-13 |
| Applying Auto Constraints | 4-14 |
| Editing Multiple Dimensions | 4-15 |
| Analyzing and Deleting Over-Defined Constraints | 4-16 |
| Analyzing Sketch Using the Sketch Analysis Tool | 4-16 |
| Exiting the Sketcher Workbench | 4-17 |
| Creating Base Features by Extrusion | 4-18 |
| Creating a Thin Extruded Feature | 4-19 |
| Extruding the Sketch Using the Profile Definition Dialog Box | 4-21 |
| Extruding the Sketch along a Directional Reference | 4-22 |
| Creating Base Features by Revolving Sketches | 4-23 |
| Creating Thin Shaft Features | 4-24 |
| Dynamically Rotating the View of the Model | 4-25 |
| Rotating the View Using the Rotate Tool | 4-25 |
| Rotating the View Using the Compass | 4-26 |
| Modifying the View Orientation | 4-26 |
| Display Modes of the Model | 4-28 |
| Shading (SHD) | 4-28 |
| Shading with Edges | 4-28 |
| Shading with Edges without Smooth Edges | 4-28 |
| Shading with Edges and Hidden Edges | 4-28 |
| Shading with Material | 4-29 |
| Wireframe (NHR) | 4-29 |
| Customize View Parameters | 4-29 |
| Creating Sections Dynamically | 4-29 |

Enhanced

| | |
|-----------------------------------|------|
| Maneuvering the Section Plane | 4-30 |
| Position of Section Planes | 4-30 |
| Assigning a Material to the Model | 4-31 |
| Tutorial 1 | 4-33 |
| Tutorial 2 | 4-38 |
| Self-Evaluation Test | 4-45 |
| Review Questions | 4-45 |
| Exercise 1 | 4-47 |
| Exercise 2 | 4-47 |
| Exercise 3 | 4-48 |
| Exercise 4 | 4-49 |

Chapter 5: Reference Elements and Sketch-Based Features

| | |
|---|------|
| Importance of Sketching Planes | 5-2 |
| Reference Elements | 5-3 |
| Reference Planes | 5-3 |
| Creating New Planes | 5-4 |
| Creating Points | 5-9 |
| Creating Reference Lines | 5-10 |
| Other Sketch-Based Features | 5-11 |
| Creating Drafted Filleted Pad Features | 5-11 |
| Creating Multi-Pad Features | 5-11 |
| Feature Termination Options | 5-13 |
| Creating Pocket Features | 5-15 |
| Creating Drafted Filleted Pocket Features | 5-16 |
| Creating Multi-Pocket Features | 5-16 |
| Creating Groove Features | 5-17 |
| Extruding and Revolving Planar and Non-planar Faces | 5-18 |
| Projecting 3D Elements | 5-18 |
| Tutorial 1 | 5-19 |
| Tutorial 2 | 5-23 |
| Tutorial 3 | 5-27 |
| Tutorial 4 | 5-34 |
| Tutorial 5 | 5-39 |
| Self-Evaluation Test | 5-43 |
| Review Questions | 5-44 |
| Exercise 1 | 5-45 |
| Exercise 2 | 5-46 |
| Exercise 3 | 5-47 |
| Exercise 4 | 5-48 |

Chapter 6: Creating Dress-Up and Hole Features

| | | |
|-------------------------|----------|------|
| Advanced Modeling Tools | Enhanced | 6-2 |
| Creating Hole Features | | 6-2 |
| Creating Fillets | | 6-10 |
| Creating Chamfers | | 6-23 |

| | |
|--|------|
| Adding a Draft to the Faces of the Model | 6-25 |
| Creating a Shell Feature | 6-30 |
| Tutorial 1 | 6-32 |
| Tutorial 2 | 6-38 |
| Self-Evaluation Test | 6-44 |
| Review Questions | 6-45 |
| Exercise 1 | 6-46 |
| Exercise 2 | 6-47 |
| Exercise 3 | 6-48 |

Chapter 7: Editing Features

| | |
|---|------|
| Editing Features of a Model | 7-2 |
| Editing Using the Definition Option | 7-2 |
| Editing by Double-Clicking | 7-3 |
| Editing the Sketch of a Sketch-Based Feature | 7-3 |
| Redefining the Sketch Plane of Sketches | 7-3 |
| Deleting Unwanted Features | 7-4 |
| Managing Features and Sketches by using the Cut, Copy, and Paste Functionalities | 7-5 |
| Understanding the Concept of Update Diagnosis | 7-6 |
| Cut, Copy, and Paste Features and Sketches | 7-7 |
| Copying Features Using Drag and Drop | 7-7 |
| Copying and Pasting PartBodies | 7-8 |
| Deactivating Features | 7-9 |
| Activating Deactivated Features | 7-10 |
| Defining Features in Work Object | 7-10 |
| Reordering Features | 7-10 |
| Understanding the Parent-Child Relationships | 7-12 |
| Measuring Elements | 7-12 |
| Measuring between Elements | 7-12 |
| Measuring Items | 7-14 |
| Measuring Inertia | 7-14 |
| Tutorial 1 | 7-16 |
| Tutorial 2 | 7-21 |
| Tutorial 3 | 7-27 |
| Self-Evaluation Test | 7-32 |
| Review Questions | 7-32 |
| Exercise 1 | 7-33 |
| Exercise 2 | 7-34 |
| Exercise 3 | 7-36 |

Enhanced

Chapter 8: Transformation Features and Advanced Modeling Tools-I

| | |
|------------------------------|-----|
| Transformation Features | 8-2 |
| Translating the Bodies | 8-2 |
| Rotating the Bodies | 8-3 |
| Creating Symmetry Features | 8-5 |
| Transforming the Axis System | 8-5 |

| | | |
|---------------------------------------|----------|------|
| Mirroring the Features and Bodies | | 8-6 |
| Creating Rectangular Patterns | Enhanced | 8-8 |
| Creating Circular Patterns | | 8-13 |
| Creating User Patterns | | 8-16 |
| Uniform Scaling of Models | | 8-17 |
| Non-uniform Scaling of Models | | 8-18 |
| Working With Additional Bodies | | 8-18 |
| Inserting a New Body | | 8-19 |
| Inserting Features in the New Body | | 8-19 |
| Applying Boolean Operations to Bodies | | 8-19 |
| Adding Stiffeners to a Model | | 8-25 |
| Generating Solid Combine | | 8-27 |
| Tutorial 1 | | 8-28 |
| Tutorial 2 | | 8-34 |
| Self-Evaluation Test | | 8-39 |
| Review Questions | | 8-39 |
| Exercise 1 | | 8-41 |
| Exercise 2 | | 8-42 |
| Exercise 3 | | 8-43 |

Chapter 9: Advanced Modeling Tools-II

| | | |
|--|--|------|
| Advanced Modeling Tools | | 9-2 |
| Creating Rib Features | | 9-2 |
| Creating Slot Features | | 9-7 |
| Creating Multi-Sections Solid Features | | 9-8 |
| Creating Multi-Sections Solid Cut Features | | 9-16 |
| Tutorial 1 | | 9-17 |
| Tutorial 2 | | 9-23 |
| Tutorial 3 | | 9-29 |
| Tutorial 4 | | 9-34 |
| Self-Evaluation Test | | 9-37 |
| Review Questions | | 9-37 |
| Exercise 1 | | 9-39 |
| Exercise 2 | | 9-40 |

Chapter 10: Working with the Wireframe and Surface Design Workbench

| | | |
|---|----------|------|
| Need of Surface Modeling | | 10-2 |
| Wireframe and Surface Design Workbench | | 10-2 |
| Starting the Wireframe and Surface Design Workbench | | 10-2 |
| Creating Wireframe Elements | | 10-2 |
| Creating Circles | | 10-2 |
| Creating Splines | | 10-3 |
| Creating a Helix | Enhanced | 10-4 |
| Creating Surfaces | | 10-7 |
| Creating Extruded Surfaces | | 10-7 |
| Creating Revolved Surfaces | | 10-8 |
| Creating Spherical Surfaces | | 10-9 |

| | |
|---------------------------------|-------|
| Creating Cylindrical Surfaces | 10-10 |
| Creating Offset Surfaces | 10-11 |
| Creating Sweep Surfaces | 10-12 |
| Creating Fill Surfaces | 10-18 |
| Creating Multi-Section Surfaces | 10-19 |
| Creating Blended Surfaces | 10-20 |
| Operations on Shape Geometry | 10-21 |
| Joining Surfaces | 10-21 |
| Splitting Surfaces | 10-22 |
| Trimming Surfaces | 10-23 |
| Tutorial 1 | 10-24 |
| Tutorial 2 | 10-31 |
| Self-Evaluation Test | 10-41 |
| Review Questions | 10-41 |
| Exercise 1 | 10-42 |
| Exercise 2 | 10-43 |

Chapter 11: Editing and Modifying Surfaces

| | |
|--|-------|
| Surface Operations | 11-2 |
| Creating Projection Curves | 11-2 |
| Creating Intersection Elements | 11-3 |
| Healing Geometries | 11-5 |
| Disassembling Elements | 11-8 |
| Untrimming a Surface or a Curve | 11-8 |
| Creating Boundary Curves | 11-9 |
| Extracting Geometry | 11-11 |
| Transformation | 11-11 |
| Extrapolating Surfaces and Curves | 11-18 |
| Splitting a Solid Body with a Surface | 11-20 |
| Solidifying Surface Models | 11-21 |
| Adding Thickness to a Surface | 11-21 |
| Creating a Solid Body from a Closed Surface Body | 11-22 |
| Sewing a Surface to a Solid Body | 11-23 |
| Tutorial 1 | 11-24 |
| Tutorial 2 | 11-32 |
| Self-Evaluation Test | 11-40 |
| Review Questions | 11-40 |
| Exercise 1 | 11-41 |

Enhanced

Chapter 12: Assembly Modeling

| | |
|--|-------|
| Assembly Modeling | 12-2 |
| Types of Assembly Design Approaches | 12-2 |
| Creating Bottom-up Assemblies | 12-3 |
| Inserting Components in a Product File | 12-4 |
| Moving Individual Components | 12-6 |
| Applying Constraints | 12-12 |
| Creating Top-down Assemblies | 12-22 |

| | |
|---|-------|
| Creating Base Part in the Top-Down Assembly | 12-22 |
| Creating Subsequent Components in the Top-Down Assembly | 12-23 |
| Creating Subassemblies in the Top-Down Assembly | 12-24 |
| Editing Assemblies | 12-25 |
| Deleting Components | 12-25 |
| Replacing Components | 12-26 |
| Editing Components Inside an Assembly | 12-27 |
| Editing Subassemblies Inside an Assembly | 12-27 |
| Editing Assembly Constraints | 12-28 |
| Simplifying the Assembly | 12-29 |
| Interference Detection | 12-31 |
| Sectioning an Assembly | 12-32 |
| Exploding an Assembly | 12-33 |
| Tutorial 1 | 12-36 |
| Tutorial 2 | 12-50 |
| Self-Evaluation Test | 12-57 |
| Review Questions | 12-58 |
| Exercise 1 | 12-59 |

Chapter 13: Working with the Drafting Workbench-I

| | |
|--|-------|
| The Drafting Workbench | 13-2 |
| Starting a New File in the Drafting Workbench | 13-2 |
| Type of Views | 13-4 |
| Generating Drawing Views | 13-6 |
| Generating Views Automatically | 13-6 |
| Generating Individual Drawing Views | 13-10 |
| Generating the Exploded View | 13-25 |
| Working with Interactive Drafting in CATIA V5 | 13-26 |
| Editing and Modifying Drawing Views | 13-27 |
| Changing the Scale of Drawing Views | 13-27 |
| Modifying the Project Plane of the Parent View | 13-27 |
| Deleting Drawing Views | 13-27 |
| Rotating Drawing Views | 13-27 |
| Hiding Drawing Views | 13-28 |
| Modifying the Hatch Pattern of Section Views | 13-28 |
| Tutorial 1 | 13-29 |
| Tutorial 2 | 13-35 |
| Self-Evaluation Test | 13-41 |
| Review Questions | 13-41 |
| Exercise 1 | 13-42 |

Chapter 14: Working with the Drafting Workbench-II

| | |
|--|------|
| Inserting Sheets in the Current File | 14-2 |
| Inserting the Frame and the Title Block | 14-3 |
| Automatic Insertion of the Frame and the Title Block | 14-3 |
| Creating the Frame and the Title Block Manually | 14-5 |
| Adding Annotations to the Drawing Views | 14-7 |

| | |
|---|-------|
| Generating Dimensions | 14-7 |
| Adding Reference Dimensions | 14-10 |
| Adding Datum Features | 14-12 |
| Adding Geometric Tolerance to the Drawing Views | 14-13 |
| Adding Surface Finish Symbols | 14-14 |
| Adding Welding Symbols | 14-15 |
| Applying Weld | 14-17 |
| Editing Annotations | 14-18 |
| Generating the Bill of Material (BOM) | 14-18 |
| Generating Balloons | 14-19 |
| Tutorial 1 | 14-20 |
| Tutorial 2 | 14-29 |
| Self-Evaluation Test | 14-34 |
| Review Questions | 14-34 |
| Exercise 1 | 14-35 |

Chapter 15: Working with Sheet Metal Components

| | |
|---|-------|
| The Sheet Metal Component | 15-2 |
| Starting a New File in Generative Sheet Metal Workbench | 15-2 |
| Setting Sheet Metal Parameters | 15-3 |
| Parameters Tab | 15-3 |
| Bend Extremities Tab | 15-4 |
| Bend Allowance Tab | 15-6 |
| Introduction to Sheet Metal Walls | 15-6 |
| Creating the Base Wall | 15-6 |
| Creating the Wall On Edge | 15-7 |
| Creating Extrusions | 15-12 |
| Creating Swept Walls | 15-14 |
| Creating Flanges on the Sheet Metal Component | 15-14 |
| Creating Hems on the Sheet Metal Component | 15-17 |
| Creating a Tear Drop on the Sheet Metal Component | 15-17 |
| Creating a User Flange on the Sheet Metal Component | 15-18 |
| Creating a Bend | 15-19 |
| Creating a Conical Bend | 15-20 |
| Bend From Flat | 15-21 |
| Creating Rolled Walls | 15-24 |
| Creating a Hopper Wall | 15-24 |
| Creating a Rolled Wall | 15-26 |
| Folding and Unfolding Sheet Metal Parts | 15-27 |
| Unfolding Sheet Metal Parts | 15-27 |
| Folding Unfolded Parts | 15-28 |
| Mapping the Geometry | 15-29 |
| Creating Flat Patterns of Sheet Metal Components | 15-30 |
| Viewing a Sheet Metal Component in Multiple Windows | 15-31 |
| Using Views Management | 15-31 |
| Stamping | 15-32 |
| Creating a Surface Stamp | 15-32 |

| | |
|----------------------------------|-------|
| Creating a Bead Stamp | 15-35 |
| Creating a Curve Stamp | 15-36 |
| Creating a Flanged Cut Out Stamp | 15-38 |
| Creating a Louver Stamp | 15-39 |
| Creating a Bridge Stamp | 15-40 |
| Creating a Flanged Hole Stamp | 15-42 |
| Creating a Circular Stamp | 15-44 |
| Creating a Stiffening Rib Stamp | 15-45 |
| Creating a Dowel Stamp | 15-46 |
| Tutorial 1 | 15-46 |
| Tutorial 2 | 15-53 |
| Tutorial 3 | 15-58 |
| Tutorial 4 | 15-62 |
| Self-Evaluation Test | 15-68 |
| Review Questions | 15-69 |
| Exercise 1 | 15-69 |

Chapter 16: DMU Kinematics

| | |
|---|-------|
| Introduction to DMU Kinematics | 16-2 |
| Designing a Mechanism | 16-2 |
| Creating the Revolute Joint | 16-3 |
| Creating the Prismatic Joint | 16-8 |
| Creating the Cylindrical Joint | 16-9 |
| Creating the Screw Joint | 16-10 |
| Creating the Rigid Joint | 16-12 |
| Creating the Spherical Joint | 16-12 |
| Creating the Planar Joint | 16-15 |
| Creating the Point Curve Joint | 16-16 |
| Creating the Slide Curve Joint | 16-17 |
| Creating the Roll Curve Joint | 16-18 |
| Creating the Point Surface Joint | 16-19 |
| Creating the Universal Joint | 16-20 |
| Creating the CV Joint | 16-21 |
| Creating the Gear Joint | 16-22 |
| Creating the Rack Joint | 16-24 |
| Creating the Cable Joint | 16-26 |
| Converting Assembly Constraints into Joints | 16-27 |
| Tutorial 1 | 16-29 |
| Tutorial 2 | 16-34 |
| Tutorial 3 | 16-40 |
| Tutorial 4 | 16-47 |
| Tutorial 5 | 16-52 |
| Self-Evaluation Test | 16-57 |
| Review Questions | 16-57 |
| Exercise 1 | 16-58 |
| Exercise 2 | 16-59 |

Chapter 17: Working with the FreeStyle Workbench

| | |
|---------------------------------|----------|
| The FreeStyle Workbench | 17-2 |
| Starting a New FreeStyle File | 17-2 |
| Setting the FreeStyle Workbench | 17-3 |
| Creating Surfaces | 17-5 |
| Patches Sub-toolbar | 17-5 |
| Extrude Surface | 17-8 |
| Revolve | 17-9 |
| Offset | 17-9 |
| Styling Extrapolate | 17-10 |
| FreeStyle Blend Surface | 17-11 |
| Styling Fillet | 17-13 |
| Fills Sub-toolbar | 17-14 |
| Net Surface | 17-15 |
| Styling Sweep | 17-15 |
| Modifying Surfaces | 17-16 |
| Symmetry | 17-17 |
| Control Points | 17-17 |
| Match | 17-21 |
| Tutorial 1 | 17-27 |
| Self-Evaluation Test | 17-34 |
| Review Questions | 17-34 |
| Exercise 1 | 17-35 |
| Student Projects | SP-1 |
| Index | I-1 |