

Table of Contents

Dedication	iii
Preface	xvii

Chapter 1: Introduction to NX 9.0

Introduction to NX 9.0	1-2
System Requirements	1-4
Getting Started with NX	1-4
Important Terms and Definitions	1-6
Understanding the Functions of the Mouse Buttons	1-10
Quick Access Toolbar	1-11
Ribbon <small>New</small>	1-11
Status Bar	1-16
Hot Keys	1-17
Color Scheme	1-17
Dialog Boxes in NX	1-17
Selecting Objects	1-18
Deselecting Objects	1-19
Selecting Objects Using the QuickPick Dialog Box	1-19
Self-Evaluation Test	1-19

Chapter 2: Drawing Sketches for Solid Models

Introduction	2-2
Starting NX 9.0	2-3
Starting a New Document in NX 9.0	2-4
Invoking Different NX Environments	2-7
Creating Three Fixed Datum Planes (XC-YC, YC-ZC, XC-ZC)	2-7
Displaying the WCS (Work Coordinate System)	2-8
Creating Sketches	2-9
Creating Sketches in the Modeling Environment	2-9
Creating Sketches in the Sketching Environment	2-15
Sketching Tools	2-15
Drawing Sketches Using the Profile Tool	2-15
Using Help Lines to Locate Points	2-19
Drawing Individual Lines	2-19
Drawing Arcs	2-20
Drawing Circles	2-21
Drawing Rectangles	2-23
Placing Points	2-24
Drawing Ellipses or Elliptical Arcs	2-28

Drawing Conics	2-29
Drawing Studio Splines	2-31
Filleting Sketched Entities	2-33
The Drawing Display Tools	2-35
Fitting Entities in the Current Display	2-35
Zooming an Area	2-35
Dynamic Zooming	2-36
Panning Drawings	2-36
Fitting View to Selection	2-37
Restoring the Original Orientation of the Sketching Plane	2-37
Setting Selection Filters in the Sketch in Task Environment	2-37
Selecting Objects	2-39
Deselecting Objects	2-39
Using Snap Points Options While Sketching	2-39
Deleting Sketched Entities	2-40
Exiting the Sketch Environment	2-40
Tutorial 1	2-41
Tutorial 2	2-44
Tutorial 3	2-50
Self-Evaluation Test	2-54
Review Questions	2-54
Exercise 1	2-55
Exercise 2	2-56

Chapter 3: Adding Geometric and Dimensional Constraints to Sketches

Constraining Sketches	3-2
Concept of Constrained Sketches	3-2
Under-Constrain	3-2
Fully-Constrain	3-2
Over-Constrain	3-2
Degree of Freedom Arrows	3-3
Dimensioning Sketches <i>Enhanced</i>	3-4
Locking the Automatically Applied Dimensions	3-5
Applying Dimensions by Using the Rapid Dimensions Tool	3-5
Applying Linear Dimensions <i>New</i>	3-6
Applying Radial Dimensions	3-8
Applying Angular Dimensions	3-9
Applying Perimeter Dimensions	3-9
Editing the Dimension Value and Other Parameters	3-10
Animating a Fully-Constrained Sketch	3-10
Measuring the Distance Value between Objects in a Sketch	3-11
Measuring the Distance between Two Objects in a Sketch	3-12
Measuring the Projected Distance between Two Objects	3-13
Measuring the Screen Distance between Two Objects	3-13
Measuring the Length of an Arc or a Line	3-14

Measuring the Angle between Entities	3-14
Measuring the Angle Value Using the By Objects Option	3-14
Measuring the Angle Value Using the By 3 Points Option	3-16
Measuring the Angle Value Using the By Screen Points Option	3-16
Geometric Constraints	3-16
Applying Additional Constraints Individually	3-17
Applying Symmetry Constraint	3-23
Applying Automatic Constraints to a Sketch	3-23
Controlling Inferred Constraints Settings	3-25
Showing All Constraints in a Sketch	3-26
Showing/Removing Constraints	3-27
Converting a Sketch Entity or Dimension into a Reference Entity or Reference Dimension	3-29
Tutorial 1	3-30
Tutorial 2	3-36
Tutorial 3	3-39
Self-Evaluation Test	3-43
Review Questions	3-44
Exercise 1	3-45
Exercise 2	3-45

Chapter 4: Editing, Extruding, and Revolving Sketches

Editing Sketches	4-2
Trimming Sketched Entities	4-2
Extending Sketched Entities	4-3
Creating a Corner between Sketched Entities	4-4
Moving Sketched Entities by Using the Move Curve Tool	New 4-5
Offsetting Sketched Entities by Using Offset Move Curve	New 4-11
Modifying Entities by Using the Resize Curve Tool	New 4-12
Deleting Sketched Entities by Using Delete Curve Tool	New 4-14
Offsetting Sketched Entities	4-15
Mirroring Sketched Entities	4-17
Creating a Linear Sketch Pattern	4-19
Creating a Circular Sketch Pattern	4-20
Creating a General Sketch Pattern	4-21
Transforming Sketched Entities	4-21
Editing Sketched Entities by Dragging	4-25
Exiting the Sketch Environment	4-26
Changing the View of the Sketch	4-26
Creating Base Features by Extruding	4-26
Extrude Dialog Box Options	4-27
Creating Solid Revolved Bodies	4-35
Copying, Moving, and Rotating Objects	Enhanced 4-40
Hiding Entities	4-45
Showing Hidden Entities	4-45

Hiding All Entities Using a Single Tool	4-46
Rotating the View of a Model in 3D Space	4-47
Setting Display Modes	4-47
Tutorial 1	4-48
Tutorial 2	4-51
Tutorial 3	4-55
Self-Evaluation Test	4-58
Review Questions	4-58
Exercise 1	4-59
Exercise 2	4-60

Chapter 5: Working with Datum Planes, Coordinate Systems, and Datum Axes

Additional Sketching and Reference Planes	5-2
Types of Datum Planes	5-3
Creating Three Fixed (Principle) Datum Planes	5-3
Creating Relative Datum Planes	5-3
Creating Datum Coordinate Systems	5-9
Creating Fixed and Relative Datum Axes	5-14
Other Extrusion Options	5-17
Specifying the Boolean Operation	5-17
Specifying Other Extrusion Termination Options	5-20
Projecting External Elements	5-22
Tutorial 1	5-24
Tutorial 2	5-29
Tutorial 3	5-33
Self-Evaluation Test	5-37
Review Questions	5-38
Exercise 1	5-39
Exercise 2	5-40
Exercise 3	5-41

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools	6-2
Creating Holes by Using the Hole Tool	6-2
Creating General Holes	6-3
Creating Drill Size Hole	6-4
Creating Screw Clearance Hole	6-5
Creating Threaded Hole	6-6
Creating Hole Series	6-6
Creating Grooves	6-8
Creating Rectangular Grooves	6-8
Creating Ball End Grooves	6-10
Creating U Grooves	6-11
Creating Slots	6-13
Creating Rectangular Slots	6-13

Creating Ball-End Slots	6-15
Creating U-Slots	6-17
Creating T-Slots	6-19
Creating Dove-Tail Slots	6-20
Creating Ribs <i>New</i>	6-22
Creating Chamfers	6-25
Creating a Chamfer Feature Using the Symmetric Method	6-26
Creating a Chamfer Feature Using the Asymmetric Method	6-28
Creating a Chamfer Feature Using the Offset and Angle Method	6-28
Creating an Edge Blend <i>Enhanced</i>	6-29
Tutorial 1	6-35
Tutorial 2	6-43
Self-Evaluation Test	6-50
Review Questions	6-51
Exercise 1	6-52
Exercise 2	6-53
Exercise 3	6-54

Chapter 7: Advanced Modeling Tools-II

Advanced Modeling Tools	7-2
Pattern Feature Tool <i>Enhanced</i>	7-2
Creating Linear Pattern	7-2
Creating Circular Pattern	7-8
Creating Polygon Pattern	7-12
Creating Spiral Pattern	7-13
Creating a Pattern Along a Curve	7-15
Creating a General Pattern	7-16
Creating a Reference Pattern	7-17
Creating a Helix Pattern	7-17
Creating a Fill Pattern	7-20
Mirror Feature Tool	7-22
Mirror Face Tool <i>New</i>	7-24
Mirror Geometry Tool <i>New</i>	7-25
Sweeping Sketches Along the Guide Curves	7-25
Creating Swept Features	7-27
Creating Tubes or Cables	7-30
Creating Threads	7-31
Creating Symbolic Threads	7-32
Creating Detailed Threads	7-35
Creating Shell Features	7-36
Shelling the Entire Solid Body	7-38

Tutorial 1	7-38
Tutorial 2	7-42
Tutorial 3	7-45
Tutorial 4	7-50
Self-Evaluation Test	7-56
Review Questions	7-57
Exercise 1	7-58
Exercise 2	7-59

Chapter 8: Editing Features and Advanced Modeling Tools-III

Editing Features	8-2
Editing a Hole Feature	8-2
Editing the Positioning of a Groove Feature	8-2
Editing the Positioning of a Slot Feature	8-3
Editing the Parameters of Features	8-3
Editing the Parameters of Features with Rollback	8-3
Editing Sketches of the Sketch-based Features	8-4
Reordering Features	8-4
Advanced Modeling Tools	8-4
Creating Boss Features	8-4
Creating Pocket Features	8-5
Creating Pad Features	8-9
Creating Drafts	8-12
Tutorial 1	8-15
Tutorial 2	8-20
Tutorial 3	8-27
Self-Evaluation Test	8-35
Review Questions	8-36
Exercise 1	8-37
Exercise 2	8-38
Exercise 3	8-39

Chapter 9: Assembly Modeling-I

The Assembly Environment	9-2
Invoking the Assembly Environment	9-2
Invoking the Assembly Environment Using the New Dialog Box	9-2
Invoking the Assembly Environment in the Current Part File	9-3
Types of Assembly Design Approaches	9-3
Creating Bottom-up Assemblies	9-4
Placing Components in the Assembly Environment	9-4
Changing the Reference Set of a Component	9-7
Applying Assembly Constraints to Components	9-7
Points to Remember while Assembling Components	9-18
Creating a Pattern Component in an Assembly	9-18
Replacing a Component in an Assembly	9-20

Enhanced

Moving a Component in an Assembly	9-22
Mirroring a Component in an Assembly	9-26
Modifying a Component in the Assembly File	9-29
Tutorial 1	9-30
Tutorial 2	9-44
Self-Evaluation Test	9-56
Review Questions	9-57
Exercise 1	9-58
Exercise 2	9-60
Exercise 3	9-63
Exercise 4	9-66

Chapter 10: Assembly Modeling-II

The Top-down Assembly Design Approach	10-2
Creating Components Using the Top-down Assembly Design Approach	10-2
Creating Subassemblies	10-4
Editing Assembly Constraints	10-5
Checking the Interference between the Components of an Assembly	10-6
Checking Interference Using the Simple Interference Tool	10-6
Checking Interference Between the Assembly Components <i>Enhanced</i>	10-8
Checking Interference and Clearance, and Analyzing Cross-sections of Components Using the View Section Tool	10-13
Creating Exploded Views of an Assembly	10-18
Exploding Views Automatically	10-19
Exploding Views Manually	10-21
Tutorial 1	10-23
Tutorial 2	10-26
Tutorial 3	10-31
Tutorial 4	10-37
Self-Evaluation Test	10-42
Review Questions	10-43
Exercise 1	10-43
Exercise 2	10-48
Exercise 3	10-55

Chapter 11: Surface Modeling

Introduction to Surface Modeling	11-2
Invoking the Shape Studio Environment	11-2
Creating an Extruded Surface	11-3
Creating a Revolved Surface	11-3
Creating a Ruled Surface	11-4
Creating a Surface Using the Through Curves Tool	11-6
Creating a Surface Using the Through Curve Mesh Tool	11-7
Creating a Surface Using the Four Point Surface Tool	11-10
Creating a Swoop Surface	11-11
Creating Planar Surfaces from 2D Sketches and Edges of Solid or Surface	11-13
Creating a Transition Surface Using the Transition Tool	11-14

Creating an N-Sided Surface	11-16
Creating a Silhouette Flange Surface	11-19
Extending a Surface Using the Law Extension Tool	11-23
Creating a Surface Offset Using the Offset Surface Tool	11-27
Trimming and Extending a Surface Using the Trim and Extend Tool	11-28
Trimming a Sheet by Using the Trimmed Sheet Tool	11-29
Creating a Surface Using the Studio Surface Tool	11-31
Creating a Surface between Two Walls Using the Styled Blend Tool	11-34
Creating Surfaces Using the Styled Sweep Tool	11-39
Sewing Individual Surfaces into a Single Surface	11-40
Adding Thickness to a Surface	11-41
Adding Drafts	11-42
Tutorial 1	11-44
Tutorial 2	11-49
Self-Evaluation Test	11-57
Review Questions	11-58
Exercise 1	11-59
Exercise 2	11-60

Chapter 12: Advanced Surface Modeling

Creating Curves from Bodies	12-2
Creating Intersection Curves	12-2
Creating Section Curves	12-3
Creating Extract Curves	12-8
Creating Isoparametric Curves	12-10
Projecting Curves	12-11
Advanced Surface Modeling Tools	12-15
Creating Dart Features	12-15
Creating Emboss Body on a Sheet or Solid Body	12-17
Creating Face Blend Features	12-18
Creating Soft Blend Features	12-22
Creating Bridge Features	12-25
Tutorial 1	12-27
Tutorial 2	12-38
Tutorial 3	12-48
Self-Evaluation Test	12-59
Review Questions	12-60
Exercise 1	12-61
Exercise 2	12-62

Chapter 13: Generating, Editing, and Dimensioning the Drawing Views

The Drafting Environment	13-2
Invoking the Drafting Environment	13-2
Invoking the Drafting Environment Using the Drawing Template from the New Dialog Box	13-2
Invoking the Drafting Environment in the Current Part File	13-4

Editing the Drawing Sheet Parameters in the Drafting Environment	13-6
Invoking the Drafting Tools	13-6
Types of Drawing Views in NX	13-6
Base View	13-6
Projected View	13-7
Detail View	13-7
Section View	13-7
Auxiliary View	13-7
Half-Section View	13-7
Revolved Section View	13-7
Break-Out Section View	13-7
Broken View	13-7
Generating Drawing Views	13-8
Generating Views Using the View Creation Wizard Tool	13-8
Generating the Base View	13-13
Generating the Orthographic Drawing Views Using the Projected View Tool	13-16
Generating the Detail View Using the Detail View Tool	13-17
Generating Section Views Using the Section View Tool	13-20
Generating the Half Section View Using the Half Section View Tool	13-25
Generating the Revolved Section View	13-26
Generating the Break-Out Section View	Enhanced 13-27
Generating the Broken View	13-28
Manipulating the Drawing Views	13-30
Moving the Drawing Views Using the Move/Copy View Tool	New 13-30
Aligning the Drawing Views Using the Align View Tool	13-31
View Boundary	13-34
Editing the Section Line Using the Edit Section Line Tool	New 13-35
Section in View Tool	New 13-35
Displaying the Model Using the Display Sheet Tool	13-37
Inserting a Drawing Sheet Using the New Sheet Tool	13-37
Modifying the Properties of a Generated Drawing View	13-38
Modifying the Scale Value of the Drawing View	13-38
Adding Dimensions to the Drawing Views	Enhanced 13-40
Retrieving Dimensions from the Model	13-40
Adding Dimensions to the Drawing View	13-40
Generating Exploded Views of an Assembly	13-44
Creating Parts List and Associative Balloons	13-45
Creating a Parts List for an Assembly	13-45
Creating Associative Balloons	13-45
Creating a Tabular Note (Title Block)	13-47
Adding Multiline Text to a Drawing Sheet	13-49
Printing Tools	13-49
Print	13-50
Plot	13-51
Tutorial 1	13-51
Tutorial 2	13-57

Tutorial 3	13-62
Self-Evaluation Test	13-69
Review Questions	13-70
Exercise 1	13-71
Exercise 2	13-71

Chapter 14: Synchronous Modeling

Introduction		14-2
Move Face		14-2
Move Edge	New	14-5
Pull Face		14-7
Offset Region		14-9
Offset Edge	New	14-10
Replace Face		14-11
Resize Blend		14-12
Reorder Blend		14-13
Resize Chamfer		14-14
Label Chamfer		14-14
Label Notch Blend		14-15
Resize Face		14-15
Delete Face		14-16
Copy Face		14-18
Cut Face		14-19
Paste Face		14-20
Mirror Face		14-21
Pattern Face		14-21
Make Coplanar		14-22
Make Coaxial		14-23
Make Tangent		14-24
Make Symmetric		14-25
Make Parallel		14-26
Make Perpendicular		14-27
Make Fixed		14-29
Make Offset		14-29
Show Related Face		14-30
Linear Dimension		14-31
Angular Dimension		14-33
Radial Dimension		14-34
Shell Body		14-36
Shell Face		14-37
Change Shell Thickness		14-38
Group Face		14-39
Edit Cross Section in History Free Mode		14-40
Edit Cross Section in History Mode		14-41
Tutorial 1		14-42

Tutorial 2	14-48
Self-Evaluation Test	14-57
Review Questions	14-58
Exercise 1	14-59
Exercise 2	14-60

Chapter 15: Sheet Metal Design

The Sheet Metal Module	15-2
Setting the Sheet Metal Part Properties	15-4
Creating the Base Feature	15-8
Adding Flanges to a Sheet Metal Part	15-9
Creating Contour Flanges	15-15
Creating Lofted Flanges	15-16
Adding a Jog to the Sheet	15-17
Bending the Sheet Metal Part	15-18
Unbending the Sheet Metal Part	15-19
Rebending the Sheet Metal Part	15-19
Filleting or Chamfering Corners	15-20
Closing the Corners of a Sheet Metal Part	15-20
Creating Dimples in a Sheet Metal Part	15-24
Creating Louvers in a Sheet Metal Part	15-27
Creating Drawn Cutouts in a Sheet Metal Part	15-29
Creating Beads in a Sheet Metal Part	15-29
Adding Gussets to a Sheet Metal part	15-32
Adding Hems	15-36
Creating a Sheet Metal Part Using Solid Body	15-39
Converting a Solid Part into a Sheet Metal Part	15-40
Ripping the Corners of a Solid Part	15-41
Creating the Flat Pattern of a Sheet Metal Part	15-41
Creating the Flat Pattern	15-41
Creating the Flat Solid	15-42
Exporting a Flat Pattern	15-43
Tutorial 1	15-43
Tutorial 2	15-53
Self-Evaluation Test	15-58
Review Questions	15-59
Exercise 1	15-60
Exercise 2	15-61