

Table of Contents

Dedication	iii
Preface	xxi

Chapter 1: Introduction to AutoCAD Electrical 2013

Introduction	1-2
Installing and Configuring AutoCAD Electrical 2013	1-2
Getting Started with AutoCAD Electrical 2013	1-8
AutoCAD Electrical Screen Components	1-8
Drawing Area	1-8
Command Window	1-9
Application Status Bar	1-9
Navigation Bar	1-12
Annotation Scale	1-12
Annotation Visibility	1-12
Automatically Add Scale	1-13
Workspace Switching	1-13
Drawing Status Bar	1-13
Status Bar Tray Options	1-13
Invoking Commands in AutoCAD Electrical	1-14
Keyboard	1-15
Ribbon	1-15
Application Menu	1-16
Menu Bar	1-17
Toolbar	1-17
Marking Menu	Enhanced 1-19
Shortcut Menu	1-20
Tool Palettes	1-21
Project Manager	1-22
Components of AutoCAD Electrical Dialog Boxes	1-22
Saving the Work	Enhanced 1-23
Save Drawing As Dialog Box	1-24
Views	1-25
Create New Folder	1-26
Up One Level	1-26
Search the Web	1-26
Tools	1-26

Auto Save		1-26
Creating Backup Files		1-27
Using the Drawing Recovery Manager to Recover Files		1-27
Closing a Drawing		1-27
Quitting AutoCAD Electrical		1-27
Dynamic Input Mode		1-29
Enable Pointer Input		1-29
Creating and Managing Workspaces		1-30
Creating a New Workspace		1-31
Modifying Workspace Settings		1-31
WD_M Block		1-32
AutoCAD Electrical Help	Enhanced	1-33
Help Menu		1-33
InfoCenter Bar	Enhanced	1-36
Additional Help Resources		1-39
Other Online Options		1-39
Online Options		1-39
Open On Mobile		1-39
Upload Multiple		1-40
Choose Settings		1-40
Sync My Settings		1-40
Share Document and Collaborate Now		1-40
Self-Evaluation Test		1-40
Review Questions		1-41

Chapter 2: Working with Projects and Drawings

Introduction		2-2
Project Manager	Enhanced	2-2
Opening a Project		2-4
Creating a New Project		2-4
Name		2-4
Location		2-4
Create Folder with Project Name		2-4
Copy Settings from Project File		2-5
Descriptions		2-5
Working with Drawings		2-6
Creating a New Drawing		2-7
Adding a New Drawing to the Current Project		2-10
Adding Existing Drawings to the Current Project		2-11
Working with Project Drawings		2-11
Grouping Drawings within a Project		2-12
Changing the Order of Drawings in a Project		2-13
Removing a Drawing from a Project		2-14
Assigning a Description to a Drawing		2-16
Switching between the Drawings of an Active Project		2-17
Configuring the Drawing List Display		2-18

Copying a Project	2-20
Deleting a project	2-23
Delete “.wdp” Project List File	2-23
Delete project’s AutoCAD Drawing Files	2-24
List	2-24
Other Options in the Project Manager	2-24
Buttons	2-24
Project Selection Drop-down List	2-27
Projects Rollout	2-28
Project Drawing List	2-32
Details/Preview Rollout	2-36
Tutorial 1	2-38
Tutorial 2	2-43
Tutorial 3	2-45
Self-Evaluation Test	2-46
Review Questions	2-47
Exercise 1	2-48
Exercise 2	2-48
Exercise 3	2-48

Chapter 3: Working with Wires

Introduction	3-2
Wires	3-2
Inserting Wires into a Drawing	3-2
Inserting Wires at Angles	3-4
Inserting Multiple Bus Wiring	3-7
Modifying Wires	3-10
Trimming a Wire	3-10
Stretching Wires	3-11
Working with Wire Types	3-12
Creating Wire Types	3-13
Changing and Converting Wire Types	3-22
Setting Wire Types	3-24
Working with Wire Numbers	3-25
Types of Wire Number	3-25
Inserting Wire Numbers	3-26
Copying Wire Numbers	3-31
Positioning Wire Numbers In-line with a Wire	3-32
Deleting Wire Numbers	3-32
Editing Wire Numbers	3-33
Fixing Wire Numbers	3-35
Hiding Wire Numbers	3-35
Unhiding Wire Numbers	3-36
Swapping Wire Numbers	3-36
Finding/Replacing Wire Numbers	3-37
Moving a Wire Number	3-38

Scooting a Wire Number	3-38
Flipping a Wire Number	3-39
Toggling the Wire Number Position	3-39
Repositioning the Wire Number Text with the Attached Leader	3-39
Inserting In-Line Wire Markers	3-40
Inserting Wire Color/Gauge Labels in a Drawing	3-43
Inserting the Special Wire Numbering in a Drawing	3-43
Adding Source and Destination Signal Arrows	3-45
Adding Source Signal Arrows	3-45
Adding Destination Signal Arrows	3-48
Inserting Cable Markers	3-49
Showing Source and Destination Markers on Cable Wires	3-51
Troubleshooting Wires	3-56
Bending Wires at Right Angle	3-56
Checking Line Entities	3-57
Checking, Repairing, and Tracing Wires and Gap pointers	3-58
Checking and Repairing Gap Pointers	3-59
Checking/Tracing a Wire	3-59
Manipulating Wire Gaps	3-60
Inserting Wire Gaps	3-60
Removing Wire Gaps	3-61
Flipping Wire Gaps/Loops	3-61
Tutorial 1	3-63
Tutorial 2	3-67
Tutorial 3	3-70
Self-Evaluation Test	3-72
Review Questions	3-73
Exercise 1	3-74

Chapter 4: Creating Ladders

Introduction	4-2
Ladders	4-2
Inserting a New Ladder	4-3
Modifying an Existing Ladder	4-7
Renumbering an Existing Ladder	4-7
Changing the Size of a Ladder	4-9
Repositioning a Ladder	4-11
Changing the Rung Spacing	4-11
Adding Rungs	4-12
Converting Line Reference Numbers	4-12
Renumbering the Ladder Line Reference	4-13
Formatting the Reference Number of a Ladder	4-14
X Zones Setup	4-14
XY Grid Setup	4-16
Tutorial 1	4-19
Tutorial 2	4-23

Tutorial 3	4-26
Self-Evaluation Test	4-29
Review Questions	4-30
Exercise 1	4-31
Exercise 2	4-31

Chapter 5: Schematic Components

Introduction	5-2
Inserting Schematic Components	5-2
Menu Area	5-2
JIC: Schematic Symbols Area	5-3
Menu	5-3
Up One Level	5-3
Views	5-4
Recently Used Area	5-4
Display	5-5
Vertical	5-5
No Edit Dialog	5-5
No Tag	5-5
Scale Schematic	5-5
Scale Panel	5-5
Type it	5-5
Always Display Previously used Menu	5-6
Annotating and Editing the Symbols	5-8
Component Tag Area	5-8
Catalog Data Area	5-10
Ratings Area	5-13
Description Area	5-13
Cross-Reference Area	5-14
Show/Edit Miscellaneous	5-16
Pins Area	5-17
Switch Positions Area	5-17
Selecting an Existing Part Number	5-18
View Web Link	5-18
Clear All Filters	5-19
Add Catalog Entry	5-19
Edit Catalog Entry	5-19
Database	5-19
Table	5-19
Manufacture	5-20
Type	5-20
Style	5-20
Show BOM Details	5-20
Filter by WDBLKNAM value: XX	5-20
Use MISC_CAT table	5-21
Display Subassembly Entries only for Editing	5-21

Creating a Project Specific Catalog Database	5-21
Creating Parent-Child Relationships	5-23
Component Tag Area	5-24
Inserting Components from the Equipment List	5-27
Default Settings	5-29
Read Settings	5-29
View/Edit Settings Area	5-29
Inserting Components from the Catalog List	5-32
Sort by	5-33
Adding a New Record in the Schematic Component or Circuit Dialog Box	5-34
Editing an Existing Record in the Schematic Component or Circuit Dialog Box	5-37
Inserting Components from Panel Lists	5-38
Extract Component List for Area	5-38
Installation Codes to Extract Area	5-40
Location Codes to Extract Area	5-40
Swapping and Updating Blocks	5-45
Option A: Swap Block (swap to different block name) Area	5-46
Option B: Update Block (revised or different version of same block name) Area	5-47
Attribute Mapping Area	5-50
Tutorial 1	5-51
Tutorial 2	5-57
Tutorial 3	5-59
Tutorial 4	5-62
Self-Evaluation Test	5-65
Review Questions	5-66
Exercise 1	5-67

Chapter 6: Schematic Editing

Introduction	6-2
Changing the Component Location with Scoot Tool	6-2
Changing Component Locations using the Move Component Tool	6-4
Copying a Component	6-5
Aligning Components	6-6
Deleting Components	6-7
Updating Components from Catalog Database	6-9
Update Components on Area	6-9
View Previous Report Area	6-11
Settings Area	6-11
Updating a Schematic Component from a One-Line Component	6-12
Surfing a Reference	6-13
Type	6-13
Sheet, Reference	6-14
Installation	6-14
Location	6-14

Category	6-14
Show More	6-14
Freshen	6-14
Edit	6-15
Catalog Check	6-15
Pick New List	6-15
Toggling between the Normally Open and Normally Closed Contacts	6-16
Copying the Catalog Assignment	6-17
Manufacturer	6-18
Catalog	6-18
Assembly	6-18
Catalog Lookup	6-18
Find: Drawing Only	6-18
Multiple Catalog	6-18
Catalog Check	6-19
Copying Installation/Location Code Values	6-20
Pick Master	6-20
Select Installation/Location codes to Copy Area	6-20
Auditing Drawings	6-21
Electrical Auditing	6-22
Auditing a Drawing	6-26
Retagging Drawings	6-30
Component Retag	6-30
Component Cross-Reference Update	6-30
Wire Number and Signal Tag/Retag	6-31
Ladder References	6-31
Sheet (%S value)	6-32
Drawing (%D value)	6-32
Other Configuration Settings	6-32
Title Block Update	6-34
Using Tools for Editing Attributes	6-34
Moving Attributes	6-34
Editing Attributes	6-35
Hiding Attributes	6-36
Unhiding Attributes	6-37
Adding Attributes	6-37
Squeezing an Attribute/Text	6-38
Stretching an Attribute/Text	6-38
Changing the Attribute Size	6-39
Rotating an Attribute	6-40
Changing the Justification of an Attribute	6-40
Changing an Attribute Layer	6-41
Tutorial 1	6-42
Tutorial 2	6-53
Tutorial 3	6-56
Self-Evaluation Test	6-61
Review Questions	6-62

Exercise 1	6-63
Exercise 2	6-63
Exercise 3	6-64

Chapter 7: Connectors, Point-to-Point Wiring Diagrams, and Circuits

Introduction	7-2
Inserting Connectors	7-2
Layout Area	7-3
Orientation Area	7-6
Details	7-7
Type Area	7-7
Display Area	7-8
Size Area	7-9
Insert	7-9
Editing Connectors	7-9
Inserting a Connector from the List	7-10
Adding Pins to a Connector	7-10
Deleting a Connector Pin	7-11
Moving a Connector Pin	7-11
Swapping Connector Pins	7-12
Reversing a Connector	7-12
Rotating a Connector	7-13
Stretching a Connector	7-14
Splitting a Connector	7-15
Editing Pin Numbers of a Connector	7-18
Pin List Area	7-19
Sheet, Reference	7-19
Plug	7-20
Description	7-20
Receptacle	7-20
Wire Numbers	7-20
Pin Numbers Area	7-21
Pin Descriptions	7-21
Using Point-to-point Wiring Diagrams	7-21
Inserting Splices	7-21
Inserting Wires into Connectors	7-23
Inserting Multiple Wire Bus into Connectors	7-24
Bending Wires at Right Angles	7-24
Working with Circuits	7-25
Saving Circuits to an Icon Menu	7-26
Inserting Saved Circuits	7-29
Moving Circuits	7-31
Copying Circuits	7-33
Saving Circuits by Using WBlock	7-35
Inserting the WBlocked Circuit	7-36

Building a Circuit	7-37
Inserting a Circuit	7-37
Configuring a Circuit	7-42
Multiple Phase Circuits	7-45
Adding Multiple Phase Ladders and Wires	7-45
Adding Three-phase Symbols	7-46
Tutorial 1	7-47
Tutorial 2	7-53
Tutorial 3	7-57
Self-Evaluation Test	7-62
Review Questions	7-62
Exercise 1	7-63
Exercise 2	7-64

Chapter 8: Panel Layouts

Introduction	8-2
The WD_PNLM Block File	8-2
Creating Panel Layouts from Schematic List	8-3
Extract Component List for Area	8-4
Browse	8-5
Location Codes to Extract Area	8-5
Selecting Schematic Components for Inserting them into a Panel Drawing	8-5
Annotating and Editing Footprints	8-11
Item Number Area	8-11
Catalog Data Area	8-12
Rating Area	8-14
Component Tag Area	8-15
Description Area	8-16
Installation / Location Codes (for reports) Area	8-17
Switch Positions	8-17
Show/Edit Miscellaneous	8-17
Inserting Footprints from the Icon Menu	8-18
Choice A Area	8-20
Choice B Area	8-20
Choice C Area	8-22
Inserting Footprints Manually	8-24
Inserting Footprints from a Catalog List	8-25
Inserting Footprints from an Equipment List	8-26
Inserting Footprints from Vendor Menus	8-28
Copying a Footprint	8-30
Setting the Panel Drawing Configuration	8-30
Item numbering Area	8-30
Balloon Area	8-31
Footprint Layers Area	8-33
Default Spacing for Multiple Inserts Area	8-35

Footprint insert Area	8-35
Panel Wire Connection Report XYZ Offset Reference Area	8-35
Making the Xdata Visible	8-35
XData	8-36
Value	8-36
Height	8-37
Justify	8-37
Visible	8-37
Ratings	8-37
Style	8-37
Insert	8-37
Done	8-38
Renaming Panel Layers	8-38
Adding a Balloon to a Component	8-38
Adding Multiple Balloons	8-42
Resequencing Item Numbers	8-44
Start	8-44
Process Blank Items only	8-44
Drawings to Process Area	8-44
Manufacturers to Process Area	8-44
Inserting Nameplates	8-45
Inserting DIN Rail	8-49
Rail Type Area	8-50
Origin and Length Area	8-50
Orientation Area	8-50
Scale Area	8-51
Panel Mounting Area	8-51
Editing the Panel Footprint Lookup Database File	8-52
Edit Existing Table	8-52
Create New Table	8-53
Create Empty File	8-53
Tutorial 1	8-54
Tutorial 2	8-58
Tutorial 3	8-60
Tutorial 4	8-63
Tutorial 5	8-66
Self-Evaluation Test	8-69
Review Questions	8-69
Exercise 1	8-70
Exercise 2	8-71
Exercise 3	8-71

Chapter 9: Schematic and Panel Reports

Introduction	9-2
Generating Schematic Reports	9-2
Bill of Material Reports	9-2

Missing Bill of Material Reports	9-5
Component Reports	9-6
From/To Reports	9-7
Component Wire List Reports	9-12
Connector Plug Reports	9-13
PLC I/O Address and Descriptions Reports	9-14
PLC I/O Component Connection Reports	9-14
PLC Modules Used So Far Reports	9-14
Terminal Numbers Reports	9-14
Terminal Plan Reports	9-14
Connector Summary Reports	9-14
Connector Detail Reports	9-14
Cable Summary Reports	9-14
Cable From/To Reports	9-14
Wire Label Reports	9-15
Wire Signal and Stand-alone Reference Reports	9-15
Report Generator Dialog Box	9-16
Header Area	9-17
Breaks Area	9-17
Squeeze	9-18
Add Blanks between Entries	9-18
Sort	9-18
User Post	9-18
Change Report Format	9-19
Edit Mode	9-19
Put on Drawing	9-20
Surf	9-21
Pin chart Area	9-21
Internal/External Codes Left/right	9-23
Plug/Male side, Jack/Female side, Show All	9-23
Edit Wire Label and Edit Cable Label	9-23
Changing Report Formats	9-23
Available Fields Area	9-24
Fields to Report Area	9-24
Change Field Name/Justification Area	9-25
Lines for Description Area	9-25
Adding Fields Using the User Attributes Tool	9-26
Placing Reports in the Drawing	9-28
Table Area	9-28
Text Area	9-28
Column Width Area	9-28
First New Section Placement Area	9-29
Column Labels Area	9-29
Borders Area	9-29
Row Definition Area	9-29
Section Definition Area	9-30
Title Area	9-30

Layer	9-31
Saving the Report to Files	9-32
Editing a Report	9-34
New lines Area	9-35
Edit	9-37
Swap	9-38
Generating Panel Reports	9-38
Bill of Material Reports	9-38
Generating the Cumulative Report	9-40
Report Name Area	9-40
Format File Name Area	9-41
Modify Output	9-42
Selected Reports Area	9-42
Save Report Grouping	9-43
Open Report Grouping	9-43
Drawing Information for Table Output Area	9-43
Setting the Format File for Reports	9-44
Format File Area	9-44
Save Report to File	9-45
Change Report Fields	9-45
Put on Drawing	9-46
Sort Fields	9-46
Tutorial 1	9-47
Tutorial 2	9-53
Self-Evaluation Test	9-56
Review Questions	9-57
Exercise 1	9-58
Exercise 2	9-58

Chapter 10: PLC Modules

Introduction	10-2
Inserting Parametric PLC Modules	10-2
Manufacturer Catalog Tree	10-2
Graphics Style Area	10-3
Scale Area	10-4
Inserting Spacers and Breaks	10-6
Inserting Nonparametric PLC Modules	10-9
Editing a PLC module	10-11
Addressing Area	10-11
I/O Point Description Area	10-13
Installation/Location Codes Area	10-15
Pins Area	10-15
Inserting Individual PLC I/O Points	10-15
Creating and Modifying Parametric PLC Modules	10-18
PLC Module Selection List	10-18
Terminal Grid Area	10-20

Terminal Attributes Area	10-22
New Module	10-22
Module Specifications	10-25
Style Box Dimensions	10-26
Settings	10-26
Using the Spreadsheet to PLC I/O Utility Tool	10-28
Settings	10-29
Setup	10-29
Ladder Reference Numbering Area	10-29
Module Placement Area	10-31
Drawing File Creation Area	10-31
Modifying and Saving the New Setting Configuration	10-32
Mapping the Spreadsheet Information	10-37
Spreadsheet Data Area	10-37
Assign spreadsheet or table column numbers to data categories below Area	10-37
Tagging Based on PLC I/O Address	10-38
Tutorial 1	10-40
Tutorial 2	10-44
Tutorial 3	10-48
Self-Evaluation Test	10-49
Review Questions	10-50
Exercise 1	10-51
Exercise 2	10-51

Chapter 11: Terminals

Introduction	11-2
Inserting Terminal Symbols	11-2
Annotating and Editing Terminal Symbols	11-3
Inserting Terminal from the Schematic List	11-9
Inserting Terminals Manually	11-11
Inserting Terminals from the Panel List	11-12
Adding and Modifying Associations	11-14
Active Association Area	11-15
Select Association Area	11-15
Terminal Block Properties	11-16
Manufacturer	11-17
Catalog Number	11-17
Assembly Code	11-17
Levels	11-17
Terminal Block Property Grid	11-17
Assign Jumper	11-18
Delete Jumper	11-18
Selecting, Creating, Editing, and Inserting Terminal strips	11-18
Editing the Terminal Strip	11-20
Defining the Settings of a Terminal Strip Table	11-37

Generating the Terminal Strip Table	11-40
Editing and Creating the Terminal Properties Database Table	11-41
Editing the Terminal Properties Database Table	11-42
Creating the Terminal Properties Database Table	11-45
Resequencing Terminal Numbers	11-46
First Method	11-46
Second Method	11-46
Copying Terminal Block Properties	11-47
Editing Jumpers	11-48
The Browse Option	11-48
The Edit Option	11-51
The Show Option	11-51
Tutorial 1	11-51
Tutorial 2	11-53
Self-Evaluation Test	11-58
Review Questions	11-59
Exercise 1	11-60
Exercise 2	11-61

Chapter 12: Settings, Configurations, Templates, and Plotting

Introduction	12-2
Setting Project Properties	12-2
Project Settings Tab	12-3
Components Tab	12-5
Wire Numbers Tab	12-10
Cross-References Tab	12-12
Styles Tab	12-14
Drawing Format Tab	12-16
Setting Drawing Properties	12-20
Drawing Settings Tab	12-22
Reference Files	12-23
Project Files (.WDP File)	12-23
Project Description Line Files (.WDL File)	12-24
Component Reference Files	12-26
Mapping the Title Block	12-27
Method 1 Area	12-28
Method 2 Area	12-30
Setting up the Title Block	12-31
Updating Title Blocks	12-34
Select Line(s) to Update (Project Description Lines) Area	12-35
Select line(s) to Update (these are per-drawing values) Area	12-37
Activate Each Drawing to Process	12-38
Creating Templates	12-39
Description Area	12-40

Measurement	12-40
New Layer Notification Area	12-40
Plotting the Project	12-40
Layout Tab to Plot	12-41
Pick list (from active drawing)	12-41
(Optional) For each drawing Area	12-42
Output Device Name Area	12-43
Plot to File Area	12-43
Order Area	12-43
Project Task List	12-44
Tutorial 1	12-45
Tutorial 2	12-47
Tutorial 3	12-49
Tutorial 4	12-52
Self-Evaluation Test	12-54
Review Questions	12-55
Exercise 1	12-56
Exercise 2	12-56
Exercise 3	12-57

Chapter 13: Creating Symbols

Introduction	13-2
Creating Symbols	13-2
Name	13-2
Objects Area	13-2
Insertion Point Area	13-3
Attribute Template Area	13-3
Preview Area	13-4
Common Tools	13-5
Required Rollout	13-8
Optional Rollout	13-11
POS Rollout	13-11
Rating Rollout	13-11
Wire Connection Rollout	13-11
Pins Rollout	13-13
Link Lines Rollout	13-13
Symbol Area	13-14
Base Point Area	13-15
Image Area	13-15
Naming Convention of Symbols	13-16
Schematic Symbols	13-16
Panel Layout Footprint Symbols	13-17
Connector Symbols	13-17
Plug / Jack Connector Pin Symbols	13-17
Splice Symbol	13-18
Parametric Twisted Pair Symbols	13-18

Stand-alone PLC I/O Point Symbols	13-18
PLC I/O Parametric Build Symbols	13-18
Stand-alone Terminal Symbols	13-19
Wire Number Symbols	13-19
Wire Dot Symbols	13-19
Source / Destination Wire Signal Arrow Symbols	13-19
Cable Marker Symbols	13-19
Inline Wire Marker Symbols	13-20
One-line Symbol	13-20
Customizing the Icon Menu	13-20
Miscellaneous Tools	13-26
Marking and Verifying Drawings	13-26
Exporting the Data to Spreadsheets	13-29
Updating the Data from the Spreadsheet	13-33
Tutorial 1	13-34
Tutorial 2	13-40
Self-Evaluation Test	13-44
Review Questions	13-44
Exercise 1	13-45
Exercise 2	13-46

Chapter 14: Projects

Project 1	14-2
Project 2	14-38
Index	1