

Table of Contents

Dedication	iii
Preface	xv

Chapter 1: Introduction

Introduction to NX 6	1-2
System Requirements	1-3
Getting Started with NX	1-4
Important Terms and Definitions	1-4
Understanding the Functions of the Mouse Buttons	1-10
Toolbars	1-11
Hot Keys	1-17
Color Scheme	1-17
Dialog Boxes in NX	1-17
Selecting Objects	1-19
Deselecting Objects	1-19
Selecting Objects Using the QuickPick Dialog Box	1-20
Self-Evaluation Test	1-20

Chapter 2: Drawing Sketches for Solid Models

The Sketcher Task Environment	2-2
Starting NX 6	2-2
Starting a New Document in NX 6	2-3
Invoking Different NX Environments	2-6
Creating Three Fixed Datum planes (XC-YC, YC-ZC, XC-ZC)	2-6
Displaying the WCS (Work Coordinate System)	2-8
Invoking the Sketcher Environment	2-8
Sketching Tools	2-12
Drawing Sketches Using the Profile Tool	2-12
Using Help Lines to Locate Points	2-16
Drawing Individual Lines	2-16
Drawing Arcs	2-17
Drawing Circles	2-18
Drawing Rectangles	2-19
Placing Points	2-21
Drawing Ellipses or Elliptical Arcs	2-24
Drawing Conics	2-25
Drawing Studio Splines	2-26
Filleting Sketched Entities	2-28
The Drawing Display Tools	2-30
Fitting Entities in the Current Display	2-30

Zooming to an Area	2-31
Dynamic Zooming	2-31
Panning Drawings	2-31
Fitting View to Selection	2-32
Restoring the Original Orientation of the Sketching Plane	2-32
Setting Selection Filters in the Sketcher Environment	2-32
Selecting Objects	2-34
Deselecting Objects	2-34
Using Snap Points Options While Sketching	2-34
Deleting Sketched Entities	2-35
Exiting the Sketcher Environment	2-35
Tutorial 1	2-36
Tutorial 2	2-40
Tutorial 3	2-46
Self-Evaluation Test	2-51
Review Questions	2-51
Exercise 1	2-52
Exercise 2	2-53

Chapter 3: Adding Geometric and Dimensional Constraints to Sketches

Constraining Sketches	3-2
Concept of Constrained Sketches	3-2
Under-Constrain	3-2
Fully-Constrain	3-2
Over-Constrain	3-3
Degree of Freedom Arrows	3-3
Geometric Constraints	3-4
Applying Additional Constraints Individually	3-4
Applying Automatic Constraints to the Sketch	3-9
Controlling Inferred Constraints Settings	3-10
Displaying All Constraints in the Sketch	3-11
Turning the Display of All Constraints Off in the Sketch	3-12
Showing/Removing Constraints	3-12
Converting a Sketch Entity to a Reference Entity	3-14
Dimensional Constraints	3-15
Applying Horizontal Dimensions	3-16
Editing the Dimension Value and Other Parameters	3-16
Applying Vertical Dimensions	3-17
Applying Parallel Dimensions	3-17
Applying Perpendicular Dimensions	3-18
Applying Angular Dimensions	3-19
Applying Diameter Dimensions	3-19
Applying Radius Dimensions	3-20
Applying Perimeter Dimensions	3-20
Applying Dimensions Using the Inferred Dimensions Tool	3-20

Animating a Fully Constrained Sketch	3-21
Measuring the Distance Value between the Objects in a Sketch	3-22
Measuring the Distance between Two Objects in a Sketch	3-23
Measuring the Projected Distance between Two Objects	3-24
Measuring the Screen Distance between Two Objects	3-24
Measuring the Length of an Arc or a Line	3-25
Measuring the Angle between Entities	3-25
Measuring the Angle Value Using the By Objects Option	3-25
Measuring the Angle Value Using the By 3 Points Option	3-25
Measuring the Angle Value Using the By Screen Points Option	3-26
Tutorial 1	3-27
Tutorial 2	3-32
Tutorial 3	3-36
Self-Evaluation Test	3-40
Review Questions	3-40
Exercise 1	3-41
Exercise 2	3-42

Chapter 4: Editing, Extruding, and Revolving Sketches

Editing Sketches	4-2
Trimming Sketched Entities	4-2
Extending Sketched Entities	4-3
Making a Corner between Sketched Entities	4-4
Mirroring Sketched Entities	4-4
Copying, Moving, and Rotating Sketched Entities	4-5
Transforming Sketched Entities	4-10
Editing Sketched Entities by Dragging	4-13
Exiting the Sketcher Environment	4-13
Changing the View of the Sketch	4-14
Creating Base Features by Extruding	4-14
Extrude Dialog Box Options	4-14
Creating Solid Revolved Bodies	4-22
Hiding Entities	4-26
Showing Hidden Entities	4-27
Hiding All Entities Using a Single Tool	4-27
Rotating the View of a Model in 3D Space	4-28
Setting Display Modes	4-28
Tutorial 1	4-29
Tutorial 2	4-32
Tutorial 3	4-36
Self-Evaluation Test	4-39
Review Questions	4-39
Exercise 1	4-40
Exercise 2	4-41

Chapter 5: Working with Datum Planes, Coordinate Systems, and Datum Axes

Additional Sketching and Reference Planes	5-2
Types of Datum Planes	5-3
Creating Three Fixed (Principle) Datum Planes	5-3
Creating Relative Datum Planes	5-3
Creating Datum Coordinate Systems	5-9
Creating Fixed and Relative Datum Axes	5-13
Other Extrusion Options	5-16
Specifying the Boolean Operation	5-16
Specifying Other Extrusion Termination Options	5-17
Projecting External Elements	5-20
Tutorial 1	5-22
Tutorial 2	5-27
Tutorial 3	5-30
Self-Evaluation Test	5-34
Review Questions	5-35
Exercise 1	5-36
Exercise 2	5-37

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools	6-2
Creating Holes by using the Pre-NX5 Hole	6-2
Creating Simple Holes	6-2
Creating Counterbore Holes	6-4
Creating Countersink Holes	6-4
Creating Holes by using the Hole tool	6-6
Creating General Holes	6-6
Creating Drill Size Hole	6-7
Creating Screw Clearance Hole	6-8
Creating Threaded Hole	6-8
Creating Hole Series	6-9
Creating Grooves	6-10
Creating Rectangular Grooves	6-10
Creating Ball End Grooves	6-12
Creating U Grooves	6-13
Creating Slots	6-15
Creating Rectangular Slots	6-15
Creating Ball-End Slots	6-17
Creating U Slots	6-19
Creating T Slots	6-20
Creating Dove-Tail Slots	6-21
Creating Chamfers	6-23
Creating a Chamfer Feature Using the Symmetric Method	6-24
Creating a Chamfer Feature Using the Asymmetric Method	6-25

Creating a Chamfer Feature Using the Offset and Angle Method	6-22
Creating an Edge Blend	6-27
Tutorial 1	6-31
Tutorial 2	6-37
Self-Evaluation Test	6-44
Review Questions	6-44
Exercise 1	6-45
Exercise 2	6-46
Exercise 3	6-47

Chapter 7: Advanced Modeling Tools-II

Advanced Modeling Tools	7-2
Instance Feature Tool	7-2
Creating Rectangular Arrays Using the Instance Feature Tool	7-2
Creating Circular Arrays Using the Instance Feature Tool	7-4
Using the Pattern Face Option of the Instance Feature Tool	7-6
Mirror Feature Tool	7-7
Mirror Body Tool	7-8
Sweeping Sketches Along the Guide Curves	7-9
Creating Swept Features	7-11
Creating Tubes or Cables	7-13
Creating Threads	7-14
Creating Symbolic Threads	7-14
Creating Detailed Threads	7-17
Creating Shell Features	7-18
Shelling the Entire Solid Body	7-20
Tutorial 1	7-20
Tutorial 2	7-23
Tutorial 3	7-26
Self-Evaluation Test	7-30
Review Questions	7-31
Exercise 1	7-32
Exercise 2	7-32

Chapter 8: Editing Features and Advanced Modeling Tools-III

Editing Features	8-2
Editing a Hole Feature	8-2
Editing the Positioning a Hole Feature	8-3
Editing the Positioning of a Groove Feature	8-4
Editing the Positioning of a Slot Feature	8-5
Editing the Parameters of Features	8-5
Editing the Parameters of Features with Rollback	8-5
Editing Sketches of the Sketch-based Features	8-5
Reordering Features	8-5
Advanced Modeling Tools	8-6

Creating Boss Features	8-6
Creating Pocket Features	8-7
Creating Pad Features	8-11
Creating Drafts	8-13
Tutorial 1	8-16
Tutorial 2	8-20
Tutorial 3	8-27
Self-Evaluation Test	8-34
Review Questions	8-34
Exercise 1	8-35
Exercise 2	8-36

Chapter 9: Assembly Modeling-I

The Assembly Environment	9-2
Invoking the Assembly Environment	9-2
Invoking the Assembly Environment Using the Assembly Template from the File New Dialog Box	9-2
Invoking the Assembly Environment in the Current Part File	9-2
Types of Assembly Design Approaches	9-3
Creating Bottom-up Assemblies	9-3
Placing Components in the Assembly Environment	9-4
Changing the Reference Set of the Component	9-6
Applying Assembly Constraints to Components	9-6
Points to Remember while Assembling Components	9-15
Creating a Component Array in an Assembly	9-15
Replacing a Component in an Assembly	9-17
Moving a Component in an Assembly	9-19
Repositioning a Component in an Assembly	9-23
Mirroring a Component in an Assembly	9-26
Modifying a Component in the Assembly File	9-28
Tutorial 1	9-29
Tutorial 2	9-42
Self-Evaluation Test	9-54
Review Questions	9-55
Exercise 1	9-56
Exercise 2	9-58
Exercise 3	9-61

Chapter 10: Assembly Modeling-II

The Top-down Assembly Design Approach	10-2
Creating Components Using the Top-down Assembly Design Approach	10-2
Creating Subassemblies	10-4
Editing Assembly Constraints	10-4
Modifying the Assembly Constraints	10-5
Checking the Interference between the Components of an Assembly	10-6

Checking Interference and Clearance	
Using the Check Clearance Analysis	10-6
Checking Interference Using the Assembly Clearance Method	10-8
Checking Interference and Clearance, and Analyzing	
Cross-sections of Components Using the View Section Tool	10-13
Creating Exploded Views of an Assembly	10-18
Automatic Exploded Views	10-19
Manually Exploded Views	10-20
Tutorial 1	10-22
Tutorial 2	10-26
Tutorial 3	10-30
Tutorial 4	10-36
Self-Evaluation Test	10-45
Review Questions	10-46
Exercise 1	10-46

Chapter 11: Surface Modeling

Introduction to Surface Modeling	11-2
Invoking the Sheet Modeling Environment	11-2
Creating an Extruded Surface	11-2
Creating a Revolved Surface	11-3
Creating a Ruled Surface	11-4
Creating a Surface Using the Through Curves Tool	11-6
Creating a Surface Using the Through Curve Mesh Tool	11-6
Creating a Surface Using the Four Point Surface Tool	11-8
Creating a Swoop Surface	11-9
Creating the Planar Surfaces from 2D Sketches and Edges of Solid	11-11
Creating a Transition Surface Using the Transition Tool	11-11
Creating an N-Sided Surface	11-13
Creating a Silhouette Flange Surface	11-16
Extending a Surface Using the Law Extension Tool	11-19
Creating a Surface Offset Using the Offset Surface Tool	11-22
Trimming and Extending a Surface Using the Trim and Extend Tool	11-23
Trimming a Sheet by Using the Trimmed Sheet Tool	11-24
Creating a Surface Using the Studio Surface Tool	11-26
Creating a Surface between Two Walls Using the Styled Blend Tool	11-29
Creating Surfaces Using the Styled Sweep Tool	11-33
Sewing Individual Surfaces into a Single Surface	11-35
Adding Thickness to a Surface	11-36
Tutorial 1	11-37
Tutorial 2	11-42
Self-Evaluation Test	11-48
Review Questions	11-49
Exercise 1	11-50
Exercise 2	11-50

Chapter 12: Advanced Surface Modeling

Creating Curves from Bodies	12-2
Creating Intersection Curves	12-2
Creating Section Curves	12-3
Creating Extract Curves	12-8
Advanced Surface Modeling Tools	12-11
Creating Dart Features	12-11
Creating Emboss Sheet Features	12-12
Creating Face Blend Features	12-13
Creating Soft Blend Features	12-16
Creating Fillet Features	12-18
Creating Bridge Features	12-23
Tutorial 1	12-26
Tutorial 2	12-35
Self-Evaluation Test	12-41
Review Questions	12-41
Exercise 1	12-42
Exercise 2	12-43

Chapter 13: Generating, Editing, and Dimensioning the Drawing Views

The Drafting Environment	13-2
Invoking the Drafting Environment	13-2
Invoking the Drafting Environment Using the Drawing	
Template from the File New Dialog Box	13-2
Invoking the Drafting Environment in the Current Part File	13-4
Editing Drawing Sheet Parameters in the Drafting Environment	13-6
Invoking the Drafting Tools	13-7
Types of Drawing Views in NX	13-7
Base View	13-7
Projected View	13-7
Detail View	13-7
Section View	13-7
Auxiliary View	13-7
Half-Section View	13-8
Revolved Section View	13-8
Break-Out Section View	13-8
Broken View	13-8
Generating Drawing Views	13-8
Generating the Base View	13-8
Generating the Orthographic Drawing Views Using the Projected	
View Tool	13-11
Generating the Detail View Using the Detail View Tool	13-12
Generating Section Views Using the Section View Tool	13-15
Generating the Half Section View using the Half Section View Tool	13-19

Adding the Revolved Section View	13-19
Generating the Break-Out Section for a Drawing View	13-20
Generating the Broken View	13-21
Manipulating the Drawing Views	13-23
Aligning the Drawing Views Using the Align View Tool	13-23
View Boundary	13-25
Displaying the Model Using the Display Sheet Tool	13-26
Inserting a Drawing Sheet Using the New Sheet Tool	13-26
Modifying the Properties of the Generated Drawing View	13-27
Modifying the Scale Value of the Drawing View	13-27
Adding Dimensions to the Drawing Views	13-29
Retrieving Dimensions from the Model	13-29
Adding Dimensions to the Drawing View	13-29
Generating Exploded Views of Assembly	13-32
Creating Parts List and Associative Balloons	13-33
Creating a Parts List for an Assembly	13-33
Creating Associative Balloons	13-33
Creating a Tabular Note (Title Block)	13-35
Adding Multiline text to the Drawing Sheet	13-36
Printing Tools	13-37
Print	13-37
Plot	13-38
Tutorial 1	13-39
Tutorial 2	13-44
Tutorial 3	13-50
Self-Evaluation Test	13-56
Review Questions	13-57
Exercise 1	13-58
Exercise 2	13-59

Chapter 14: Synchronous Modeling

Introduction	14-2
Move Face	14-2
Pull Face	14-4
Offset Region	14-5
Replace Face	14-6
Resize Blend	14-7
Resize Face	14-8
Delete Face	14-9
Copy Face	14-9
Cut Face	14-10
Paste Face	14-11
Mirror Face	14-12
Pattern Face	14-13
Make Coplanar	14-13
Make Coaxial	14-14

Make Tangent	14-16
Make Symmetric	14-17
Make Parallel	14-18
Make Perpendicular	14-19
Linear Dimension	14-20
Angular Dimension	14-21
Radial Dimension	14-22
Shell Body	14-23
Shell Face	14-24
Change Shell Thickness	14-25
Group Face	14-25
Cross Section	14-26
Tutorial 1	14-27
Tutorial 2	14-32
Self-Evaluation Test	14-39
Review Questions	14-40
Exercise 1	14-41
Exercise 2	14-41

Index	1
--------------	----------