

Table of Contents

Dedication	iii
Preface	xxi

Chapter 1: Introduction to AutoCAD Electrical 2011

Introduction	1-2
Installing and Configuring AutoCAD Electrical 2011	1-2
Getting Started with AutoCAD Electrical 2011	1-9
AutoCAD Electrical Screen Components	1-9
Drawing Area	1-9
Command Window	1-10
Application Status Bar	1-10
Navigation Bar	1-13
Drawing Status Bar	1-14
Status Bar Tray Options	1-14
Invoking Commands in AutoCAD Electrical	1-15
Keyboard	1-16
Ribbon	1-16
Application Menu	1-17
Menu Bar	1-18
Toolbar	1-19
Shortcut Menu	1-20
Tool Palettes	1-22
Project Manager	1-23
Components of AutoCAD Electrical Dialog Boxes	1-23
Saving the Work	1-24
Save Drawing As Dialog Box	1-25
Create New Folder	1-27
Up one level	1-27
Search the Web	1-27
Tools	1-27
Auto Save	1-28
Creating Backup Files	1-28
Using the Drawing Recovery Manager to Recover Files	1-28
Closing a Drawing	1-29
Quitting AutoCAD Electrical	1-29
Dynamic Input Mode	1-30
Enable Pointer Input	1-31
Creating and Managing Workspaces	1-32
Creating a New Workspace	1-32
Modifying Workspace Settings	1-32
WD_M Block	1-33

AutoCAD Electrical HELP	1-34
Help Menu	1-35
InfoCenter Bar	1-38
Additional Help Resources	1-39
Self-Evaluation Test	1-40
Review Questions	1-41

Chapter 2: Working with Projects and Drawings

Introduction	2-2
Project Manager	2-2
Creating a New Project in AutoCAD Electrical	2-4
Create Folder with Project Name	2-4
Copy Settings from Project File	2-5
Descriptions	2-5
Working with drawings	2-6
Creating a New Drawing	2-7
Adding a New Drawing to the Current Project	2-10
Adding Existing Drawings to the Current Project	2-11
Working with Project Drawings	2-11
Grouping Drawings within a Project	2-11
Changing the Order of Drawings in a Project	2-12
Removing a Drawing from a Project	2-14
Assigning a Description to a Drawing	2-16
Switching between the Drawings of an Active Project	2-17
Configuring the Drawing List Display	2-18
Copying a Project	2-20
Deleting a Project	2-23
Delete “.wdp” project list file	2-23
Delete project’s AutoCAD drawing files	2-24
Other options in the Project Manager	2-24
Project Selection Drop-down List	2-27
Projects Rollout	2-28
Project Drawing List	2-32
Details/Preview Rollout	2-36
Tutorial 1	2-38
Tutorial 2	2-41
Tutorial 3	2-44
Self-Evaluation Test	2-46
Review Questions	2-47
Exercise 1	2-48
Exercise 2	2-48
Exercise 3	2-48

Chapter 3: Working with Wires

Introduction	3-2
Wires	3-2
Inserting Wires into a Drawing	3-2
Inserting Wires at Angles	3-4
Inserting Multiple Bus Wiring	3-7
Modifying Wires	3-9
Trimming a Wire	3-9
Stretching Wires	3-11
Working with Wire Types	3-12
Creating Wire Types	3-12
Changing and Converting Wire Types	3-21
Setting Wire Types	3-23
Working with Wire Numbers	3-24
Types of Wire Number	3-24
Inserting Wire Numbers	3-24
Copying Wire Numbers	3-30
Deleting Wire Numbers	3-30
Editing Wire Numbers	3-31
Fixing Wire Numbers	3-33
Hiding Wire Numbers	3-34
Unhiding Wire Numbers	3-34
Moving a Wire Number	3-35
Scooting a Wire Number	3-35
Flipping a Wire Number	3-36
Toggling the Wire Number Position	3-36
Swapping Wire Numbers	3-36
Finding/Replacing Wire Numbers	3-37
Positioning Wire Numbers In-line with a Wire	3-38
Repositioning the Wire Number Text with the Attached Leader	3-39
Inserting the Special Wire Numbering in a Drawing	3-39
Inserting In-Line Wire Markers	3-41
Adding source and destination signal Arrows	3-43
Adding Source Signal Arrows	3-44
Adding Destination Signal Arrows	3-46
Inserting Cable Markers	3-47
Showing Source and Destination Markers on Cable Wires	3-50
Troubleshooting Wires	3-55
Bending Wires at Right Angle	3-55
Checking Line Entities	3-56
Checking, Repairing, and Tracing Wires and Gap pointers	3-57
Checking and Repairing Gap Pointers	3-58
Checking/Tracing a Wire	3-58
Manipulating Wire Gaps	3-59
Inserting Wire Gaps	3-59
Removing Wire Gaps	3-60
Flipping Wire Gaps/Loops	3-60

Tutorial 1	3-62
Tutorial 2	3-66
Self-Evaluation Test	3-70
Review Questions	3-70
Exercise 1	3-71

Chapter 4: Creating Ladders

Introduction	4-2
Ladders	4-2
Inserting a New Ladder	4-3
Modifying an Existing Ladder	4-7
Renumbering an Existing Ladder	4-7
Changing the Size of a Ladder	4-9
Repositioning a Ladder	4-11
Changing the Rung Spacing	4-11
Adding Rungs	4-12
Converting Line Reference Numbers	4-12
Renumbering the Ladder Line Reference	4-13
Formatting the Reference Number of a Ladder	4-14
X Zones Setup	4-14
XY Grid Setup	4-17
Tutorial 1	4-19
Tutorial 2	4-23
Tutorial 3	4-27
Self-Evaluation Test	4-29
Review Questions	4-30

Chapter 5: Schematic Components

Exercise 1	4-31
Introduction	5-2
Inserting Schematic Components	5-2
Menu Area	5-2
JIC: Schematic Symbols Area	5-3
Menu	5-3
Up one level	5-3
Views	5-4
Recently Used Area	5-4
Scale schematic	5-5
Scale panel	5-5
Always display previously used menu	5-6
Annotating and Editing the Symbols	5-7
Component Tag Area	5-9
Catalog Data Area	5-10
Ratings Area	5-12
Description Area	5-13
Cross-Reference Area	5-14

Show/Edit Miscellaneous	5-16
Pins Area	5-17
Switch Positions Area	5-17
Selecting an Existing Part Number	Enhanced 5-17
View Web Link	5-18
Clear All Filters	5-18
Edit Catalog Entry	5-19
Database	5-19
Table	5-19
Manufacturer	5-19
Type	5-19
Use Misc_CAT Table	5-20
Show BOM Details	5-20
Filter by WDBLKNAM value: XX	5-20
Display subassembly only for editing	5-20
Creating Parent-Child Relationships	5-21
Component Tag Area	5-22
Inserting Components from the Equipmemt List	5-25
Default settings	5-27
Read settings	5-27
View/Edit Settings Area	5-27
Inserting Components from the Catalog List	5-31
Sort by	5-31
Add	5-32
Edit	5-32
Delete	5-32
Adding a New Record in the Schematic Component or Circuit Dialog Box	5-32
Editing an Existing Record in the Schematic Component or Circuit Dialog Box	5-36
Inserting Components from Panel Lists	5-36
Extract component list for Area	5-37
Installation Codes to extract Area	5-38
Location Codes to extract Area	5-38
Sort List	5-39
Reload	5-39
Mark Existing	5-39
Display	5-39
Catalog Check	5-40
Tag Options Area	5-40
Scale	5-40
Vertical	5-40
Pick File	5-40
Insert	5-41
Swapping and Updating Blocks	5-43
Option A: Swap Block (swap to different block name) Area	5-43
Option B: Update Block (revised or different version of same block name) Area	5-46
Attribute Mapping Area	5-49

Tutorial 1	5-49
Tutorial 2	5-56
Tutorial 3	5-58
Tutorial 4	5-60
Self-Evaluation Test	5-64
Review Questions	5-65
Exercise 1	5-66

Chapter 6: Schematic Editing

Introduction	6-2
Changing the Component Location with Scoot Tool	6-2
Update child cross-references only	6-4
Changing component locations using the move component tool	6-4
Copying a Component	6-5
Aligning Components	6-6
Deleting Components	6-7
Surfing a Reference	6-9
Type	6-9
Sheet,Reference	6-10
Installation	6-10
Location	6-10
Category	6-10
Show more	6-10
Freshen	6-10
Edit	6-10
Catalog Check	6-11
Pick New List	6-11
Toggleing Between the Normally Open and Normally Closed Contacts	6-12
Copying the Catalog Assignment	6-13
Manufacturer	6-14
Catalog	6-14
Assembly	6-14
Catalog Lookup	6-14
Find: Drawing Only	6-14
Multiple Catalog	6-14
Catalog Check	6-14
Copying Installation/Location Code Values	6-15
Pick Master	6-16
Select Installation/Location Codes to Copy Area	6-16
Auditing Drawings	6-17
Electrical Auditing	6-17
Auditing a Drawing	6-21
Retagging Drawings	6-25
Component Retag	6-25
Component Cross-Reference Update	6-25
Wire Number and Signal Tag/Retag	6-26

Ladder References	6-27
Sheet (%S value)	6-27
Drawing (%D value)	6-28
Other Configuration Settings	6-28
Title Block Update	6-29
Using Tools for Editing Attributes	6-29
Moving Attributes	6-30
Editing Attributes	6-30
Hiding Attributes	6-31
Unhiding Attributes	6-32
Adding Attributes	6-32
Squizzing an Attribute/Text	6-33
Stretching an Attribute/Text	6-34
Changing the Attribute Size	6-34
Rotating an Attribute	6-35
Changing the Justification of an Attribute	6-36
Changing an Attribute layer	6-36
Tutorial 1	6-38
Tutorial 2	6-49
Tutorial 3	6-52
Self Evaluation Test	6-57
Review Questions	6-58
Exercise 1	6-59
Exercise 2	6-60
Exercise 3	6-60

Chapter 7: Connectors, Point-to-Point Wiring Diagrams, and Circuits

Introduction	7-2
Inserting Connectors	7-2
Layout Area	7-3
Orientation Area	7-6
Details	7-7
Type Area	7-7
Display Area	7-8
Size Area	7-9
Insert	7-9
Editing Connectors	7-9
Inserting a Connector from the List	7-10
Adding Pins to a Connector	7-10
Deleting a Connector Pin	7-11
Moving a Connector Pin	7-11
Swapping Connector Pins	7-12
Reversing a Connector	7-12
Rotating a Connector	7-13
Stretching a Connector	7-14
Splitting a Connector	7-15

Editing Pin Numbers of a Connector	7-18
Pin List Area	7-19
Sheet, Reference	7-19
Plug	7-20
Description	7-20
Receptacle	7-20
Wire Numbers	7-20
Pin Numbers Area	7-21
Pin Descriptions	7-21
Using Point-to-point Wiring Diagrams	7-21
Inserting Splices	7-21
Inserting Wires into Connectors	7-23
Inserting Multiple Wire Bus into Connectors	7-24
Bending Wires at Right Angles	7-24
Working with Circuits	7-25
Saving Circuits to an Icon Menu	7-25
Inserting Saved Circuits	7-29
Moving Circuits	7-31
Copying Circuits	7-33
Saving Circuits by Using WBlock	7-34
Inserting the WBlocked Circuit	7-35
Multiple Phase Circuits	7-36
Adding Multiple Phase Ladders and Wires	7-36
Adding Three-phase Symbols	7-37
Tutorial 1	7-38
Tutorial 2	7-44
Tutorial 3	7-49
Self-Evaluation Test	7-53
Review Questions	7-54
Exercise 1	7-55
Exercise 2	7-55

Chapter 8: Panel Layouts

Introduction	8-2
The WD_PNLM Block File	8-2
Creating Panel Layouts from Schematic Lists	8-3
Extract component list for Area	8-4
Browse	8-5
Location Codes to extract Area	8-5
Selecting Schematic Components for Inserting them into a Panel Drawing	8-5
Annotating and Editing Footprints	8-10
Item Number Area	8-11
Catalog Data Area	8-12
Rating Area	8-14
Component Tag Area	8-14
Description Area	8-16
Installation / Location codes (for reports) Area	8-17

Switch Positions	8-17
Show/Edit Miscellaneous	8-17
Inserting footprints from the Icon Menu	8-17
Choice A Area	8-20
Choice B Area	8-20
Choice C Area	8-21
Inserting Footprints Manually	8-24
Inserting Footprints from a Catalog List	8-24
Inserting Footprints from an Equipment List	8-26
Inserting footprints from Vendor Menus	8-28
Copying a footprint	8-30
Setting the Panel Drawing Configuration	8-30
Item numbering Area	8-31
Balloon Area	8-31
Footprint Layers Area	8-34
Default Spacing for Multiple Inserts Area	8-35
Footprint Insert Area	8-35
Panel Wire Connection Report XYZ Offset Reference Area	8-35
Making the Xdata Visible	8-36
XData	8-37
Value	8-37
Height	8-37
Justify	8-37
Visible	8-37
Ratings	8-37
Style	8-37
Insert	8-38
Done	8-38
Adding a Balloon to a Component	8-38
Inserting Nameplates	8-43
Inserting Din Rail	8-47
Rail Type Area	8-48
Origin and Length Area	8-48
Orientation Area	8-48
Scale Area	8-49
Panel Mounting Area	8-49
Editing the Panel Footprint Lookup Database File	8-50
Edit Existing Table	8-50
Create New Table	8-51
Create Empty File	8-51
Tutorial 1	8-52
Tutorial 2	8-55
Tutorial 3	8-58
Tutorial 4	8-61
Tutorial 5	8-64
Self-Evaluation Test	8-66
Review Questions	8-67

Exercise 1	8-68
Exercise 2	8-69
Exercise 3	8-69

Chapter 9: Schematic and Panel Reports

Introduction	9-2
Generating Schematic Reports	9-2
Bill of Material Reports	9-2
Missing Bill of Material Reports	9-5
Component Reports	9-6
From/To	9-7
Component Wire List Reports	9-12
Connector Plug Reports	9-13
PLC I/O Address and Descriptions Reports	9-13
PLC I/O Component Connection Reports	9-13
PLC Modules Used So Far Reports	9-14
Terminal Numbers Reports	9-14
Terminal Plan Reports	9-14
Connector Summary Reports	9-14
Connector Detail Reports	9-14
Cable Summary Reports	9-14
Cable From/To Reports	9-14
Wire Label Reports	9-14
Report Generator	9-14
Header Area	9-15
Breaks Area	9-15
Squeeze	9-15
Add blanks between entries	9-16
Sort	9-16
User Post	9-16
Change Report Format	9-17
Edit Mode	9-18
Put on Drawing	9-18
Wide>	9-19
Surf	9-19
Pin chart Area	9-20
Internal/External codes left/right	9-21
Plug/Male side, Jack/Female side, Show All	9-21
Edit Wire Label and Edit Cable Label	9-21
Changing report formats	9-21
Available fields Area	9-21
Fields to report Area	9-22
<<Remove	9-22
Change field name/justification Area	9-22
Lines for DESCRIPTION Area	9-23

Placing Reports in the Drawing	9-23
Table Area	9-24
Column Width Area	9-24
First New Section Placement Area	9-25
Column Labels Area	9-25
Borders Area	9-25
Row Definition Area	9-25
Section Definition Area	9-26
Title Area	9-26
Layer	9-27
Saving the Report to Files	9-28
Editing a Report	9-30
New lines Area	9-31
Swap	9-33
Generating Panel Reports	9-33
Bill of Material Reports	9-34
Generating the Cumulative Report	9-36
Report Name Area	9-36
Format File Name Area	9-37
Add>>	9-37
<<Remove	9-37
Modify Output	9-38
Selected Reports Area	9-38
Save Report Grouping	9-38
Open Report Grouping	9-38
Drawing Information for Table Output Area	9-38
Setting the Format File for Reports	9-39
Format File Area	9-40
Save Report to File	9-41
Change Report Fields	9-41
Put on Drawing	9-41
Sort Fields	9-41
Tutorial 1	9-42
Tutorial 2	9-46
Self-Evaluation Test	9-49
Review Questions	9-50
Exercise 1	9-51
Exercise 2	9-52

Chapter 10: PLC Modules

Introduction	10-2
Inserting Parametric PLC Modules	10-2
Manufacturer Catalog Tree	10-2
Graphics Style Area	10-3
Scale Area	10-4
Inserting Spacers and Breaks	10-6
Inserting Non Parametric PLC Modules	10-9

Editing a PLC module	10-11
Addressing Area	10-11
Tag	10-13
fixed	10-13
Options	10-13
Manufacturer	10-13
Catalog	10-13
Assembly	10-13
Catalog Lookup	10-13
Description	10-13
I/O Point Description Area	10-13
Installation/Location codes Area	10-15
Pins Area	10-15
Inserting Individual PLC I/O Points	10-15
Creating and Modifying Parametric PLC Modules	10-18
PLC Module Selection List	10-18
Terminal Grid Area	10-20
Terminal Attributes Area	10-22
New Module	10-22
Module Specifications	10-25
Style Box Dimensions	10-26
Settings	10-26
Using the Spreadsheet to PLC I/O Utility Tool	10-28
Settings	10-29
Ladder Reference Numbering Area	10-29
Module Placement Area	10-31
Drawing File Creation Area	10-31
Save	10-32
Start	10-32
Modifying and Saving the New Setting Configuration	10-32
Mapping the Spreadsheet Information	10-37
Spreadsheet data Area	10-37
Assign spreadsheet or table column numbers to data categories below Area	10-37
More	10-37
Tagging Based on PLC I/O Address	10-38
Tutorial 1	10-40
Tutorial 2	10-44
Tutorial 3	10-48
Self-Evaluation Test	10-49
Review Questions	10-50
Exercise 1	10-51
Exercise 2	10-51

Chapter 11: Terminals

Introduction	11-2
Inserting Terminal Symbols	11-2

Annotating and Editing Terminal Symbols	11-3
Inserting Terminal from the Schematic List	11-8
Inserting Terminals Manually	11-10
Inserting Terminals from the Panel List	11-11
Adding and Modifying Associations	11-13
Active Association Area	11-13
Select Association Area	11-15
Terminal Block Properties	11-16
Manufacturer	11-16
Catalog Number	11-16
Assembly Code	11-16
Levels	11-16
Terminal Block Property Grid	11-17
Assign Jumper	11-17
Delete Jumper	11-17
Selecting, creating, Editing, and Inserting Terminal strips	11-17
Editing the Terminal Strip	11-19
Defining the Settings of a Terminal Strip Table	11-36
Generating the Terminal Strip Table	11-38
Editing and Creating the Terminal Properties Database Table	11-39
Editing the Terminal Properties Database Table	11-40
Creating the Terminal Properties Database Table	11-43
Resequencing Terminal Numbers	11-44
First Method	11-44
Second Method	11-44
Copying Terminal Block Properties	11-45
Inserting Jumpers	11-46
The Browse Option	11-46
The Edit Option	11-49
The Show Option	11-49
Tutorial 1	11-50
Tutorial 2	11-52
Self-Evaluation Test	11-57
Review Questions	11-57
Exercise1	11-58
Exercise2	11-59

Chapter 12: Settings, Configurations, Templates, and Plotting

Introduction	12-2
Setting Project Properties	12-2
Project Settings Tab	12-3
Components Tab	12-5
Wire Numbers Tab	12-9
Cross-References Tab	12-11
Styles Tab	12-13
Drawing Format Tab	12-15

Setting Drawing Properties	12-19
Drawing Settings Tab	12-21
Reference Files	12-22
Project Files (.WDP File)	12-22
Project Description Line Files (.WDL File)	12-23
Component Reference Files	12-25
Mapping the Title Block	12-26
Method 1 Area	12-27
Method 2 Area	12-29
Setting up the Title Block	12-30
Updating Title Blocks	12-33
Select Line(s) to Update (Project Description Lines) Area	12-34
Select line(s) to update (these are per-drawing values) Area	12-36
Activate each Drawing to Process	12-37
Wide> and Wide<	12-38
Creating Templates	12-38
Description Area	12-39
Measurement	12-39
New Layer Notification Area	12-39
Plotting the Project	12-40
Layout tab to plot	12-41
Pick list (from active drawing)	12-41
(Optional) For each drawing Area	12-41
Output Device Name Area	12-42
Plot to file Area	12-42
Order Area	12-43
Project Task List	12-43
Tutorial 1	12-45
Tutorial 2	12-47
Tutorial 3	12-49
Tutorial 4	12-52
Self Evaluation Test	12-55
Review Questions	12-55
Exercise 1	12-56
Exercise 2	12-56
Exercise 3	12-57

Chapter 13: Creating Symbols and Using Miscellaneous Tools

Introduction	13-2
Creating Symbols	13-2
Name	13-2
Objects Area	13-2
Insertion point Area	13-3
Attribute template Area	13-3
Preview Area	13-4
Common Tools	13-5
Required Rollout	13-8

Optional Rollout	13-11
POS Rollout	13-11
Rating Rollout	13-11
Wire Connection Rollout	13-11
Pins Rollout	13-13
Link Lines Rollout	13-13
Symbol Area	13-14
Base Point Area	13-15
Image Area	13-15
Naming convention of symbols	13-16
Schematic Symbols	13-16
Panel Layout Footprint Symbols	13-17
Connector Symbols	13-17
Plug / Jack Connector Pin Symbols	13-17
Splice Symbol	13-18
Parametric Twisted Pair Symbols	13-18
Stand-alone PLC I/O Point Symbols	13-18
PLC I/O Parametric Build Symbols	13-18
Stand-alone Terminal Symbols	13-19
Wire Number Symbols	13-19
Wire Dot Symbols	13-19
Source / Destination Wire Signal Arrow Symbols	13-19
Cable Marker Symbols	13-19
Inline Wire Marker Symbols	13-20
One-line Symbol	13-20
Customizing the Icon Menu	13-20
Component	13-22
New Circuit	13-23
Add Circuit	13-23
New submenu	13-24
Miscellaneous Tools	13-26
Marking and Verifying Drawings	13-26
Exporting the Data to Spreadsheets	13-29
Updating the Data from the Spreadsheet	13-32
Tutorial 1	13-33
Tutorial 2	13-39
Self-Evaluation Test	13-42
Review Questions	13-42
Exercise 1	13-43
Exercise 2	13-44

Chapter 14: Projects

Project 1	14-2
Project 2	14-36