

Table of Contents

Dedication	iii
Preface	xxi

Chapter 1: Introduction to AutoCAD Electrical 2014

Introduction	1-2
Installing and Configuring AutoCAD Electrical 2014	1-2
Getting Started with AutoCAD Electrical 2014	1-8
AutoCAD Electrical Screen Components	1-8
Drawing Area	1-8
Command Window	Enhanced 1-9
Autocorrect the Command Name	1-9
AutoComplete the Command Name	1-9
Internet Search	1-10
Input Search Options	1-10
Application Status Bar	1-11
Annotation Scale	1-13
Annotation Visibility	1-14
Automatically Add Scale	1-14
Workspace Switching	1-14
Navigation Bar	1-14
Drawing Status Bar	1-14
Status Bar Tray Options	1-15
Invoking Commands in AutoCAD Electrical	1-16
Keyboard	1-16
Ribbon	1-17
Application Menu	1-17
Menu Bar	1-18
Toolbar	1-19
Marking Menu	1-20
Shortcut Menu	1-21
Tool Palettes	1-22
File Tabs	New 1-23
Project Manager	1-26
Components of AutoCAD Electrical Dialog Boxes	1-26
Saving the Work	1-27
Save Drawing As Dialog Box	1-28

Views	1-29
Create New Folder	1-29
Up one level	1-30
Search the Web	1-30
Tools	1-30
Auto Save	1-30
Creating Backup Files	1-30
Using the Drawing Recovery Manager to Recover Files	1-31
Closing a Drawing	1-31
Quitting AutoCAD Electrical	1-31
Dynamic Input Mode	1-32
Enable Pointer Input	1-33
Creating and Managing Workspaces	1-34
Creating a New Workspace	1-34
Modifying Workspace Settings	1-35
WD_M Block	1-36
AutoCAD Electrical Help	1-37
Help Menu	Enhanced 1-37
InfoCenter Bar	Enhanced 1-40
Additional Help Resources	1-47
Other Online options	1-47
Online Options	1-47
Choose Settings	1-48
Sync My Settings	1-48
Share Document and Collaborate Now	1-48
Self-Evaluation Test	1-48
Review Questions	1-49

Chapter 2: Working with Projects and Drawings

Introduction	2-2
Project Manager	2-2
Opening a Project	2-4
Creating a New Project	2-4
Name	2-4
Location	2-4
Create Folder with Project Name	2-4
Copy Settings from Project File	2-5
Descriptions	2-5
Working with Drawings	2-6
Creating a New Drawing	2-7
Adding a New Drawing to the Current Project	2-10
Adding Existing Drawings to the Current Project	2-11
Working with Project Drawings	2-11
Grouping Drawings within a Project	2-12
Changing the Order of Drawings in a Project	2-13
Removing a Drawing from a Project	2-14

Assigning a Description to a Drawing	2-16
Switching between the Drawings of an Active Project	2-17
Configuring the Drawing List Display	2-18
Copying a Project	2-20
Deleting a Project	2-23
Delete “.wdp” project list file	2-23
Delete project’s AutoCAD Drawing Files	2-24
Other Options in the Project Manager	2-24
Buttons	2-24
Project selection Drop-down List	2-27
Projects Rollout	2-28
Project Drawing List	2-32
Details/Preview Rollout	2-37
Tutorial 1	2-38
Tutorial 2	2-43
Tutorial 3	2-45
Self-Evaluation Test	2-46
Review Questions	2-47
Exercise 1	2-48
Exercise 2	2-48
Exercise 3	2-48

Chapter 3: Working with Wires

Introduction	3-2
Wires	3-2
Inserting Wires into a Drawing	3-2
Inserting Wires at Angles	3-4
Inserting Multiple Bus Wiring	3-7
Modifying Wires	3-10
Trimming a Wire	3-10
Stretching Wires	3-11
Working with Wire Types	3-12
Creating Wire Types	3-13
Changing and Converting Wire Types	3-22
Setting Wire Types	3-24
Working with Wire Numbers	3-25
Types of Wire Number	3-25
Inserting Wire Numbers	3-26
Copying Wire Numbers	3-31
Positioning Wire Numbers In-line with a Wire	3-32
Deleting Wire Numbers	3-32
Editing Wire Numbers	3-33
Fixing Wire Numbers	3-35
Hiding Wire Numbers	3-35
Unhiding Wire Numbers	3-36

Swapping Wire Numbers	3-36
Finding/Replacing Wire Numbers	3-37
Moving a Wire Number	3-38
Scooting a Wire Number	3-38
Flipping a Wire Number	3-39
Toggling the Wire Number Position	3-39
Repositioning the Wire Number Text with the Attached Leader	3-39
Inserting In-line Wire Markers	3-40
Inserting Wire Color/Gauge Labels in a Drawing	3-43
Inserting the Special Wire Numbering in a Drawing	3-43
Adding Source and Destination Signal Arrows	3-45
Adding Source Signal Arrows	3-45
Adding Destination Signal Arrows	3-48
Inserting Cable Markers	3-49
Showing Source and Destination Markers on Cable Wires	3-51
Troubleshooting Wires	3-56
Bending Wires at Right Angle	3-56
Checking Line Entities	3-57
Checking, Repairing, and Tracing Wires and Gap pointers	3-58
Checking and Repairing Gap Pointers	3-59
Checking/Tracing a Wire	3-59
Manipulating Wire Gaps	3-60
Inserting Wire Gaps	3-60
Removing Wire Gaps	3-61
Flipping Wire Gaps/Loops	3-61
Tutorial 1	3-63
Tutorial 2	3-67
Tutorial 3	3-70
Self-Evaluation Test	3-72
Review Questions	3-73
Exercise 1	3-74

Chapter 4: Creating Ladders

Introduction	4-2
Ladders	4-2
Inserting a New Ladder	4-3
Modifying an Existing Ladder	4-7
Renumbering an Existing Ladder	4-7
Changing the Size of a Ladder	4-9
Repositioning a Ladder	4-11
Changing the Rung Spacing	4-11
Adding Rungs	4-12
Converting Line Reference Numbers	4-12
Renumbering the Ladder Line Reference	4-13
Changing the Reference Numbering Style of a Ladder	4-14
Inserting X Grid Labels	4-14

Inserting X-Y Grid Labels	4-17
Tutorial 1	4-19
Tutorial 2	4-23
Tutorial 3	4-26
Tutorial 4	4-29
Self-Evaluation Test	4-35
Review Questions	4-35
Exercise 1	4-36
Exercise 2	4-37

Chapter 5: Schematic Components

Introduction	5-2
Inserting Schematic Components	5-2
Menu Area	5-2
JIC: Schematic Symbols Area	5-3
Menu	5-3
Up one level	5-3
Views	5-4
Recently Used Area	5-4
Display	5-5
Vertical	5-5
No Edit Dialog	5-5
No Tag	5-5
Scale schematic	5-5
Scale panel	5-5
Type it	5-5
Always display previously used menu	5-6
Annotating and Editing the Symbols	5-8
Component Tag Area	5-8
Catalog Data Area	5-10
Ratings Area	5-13
Description Area	5-13
Cross-Reference Area	5-14
Show/Edit Miscellaneous	5-16
Pins Area	5-17
Switch Positions Area	5-17
Selecting an Existing Part Number	5-18
View Web Link	5-18
Clear All Filters	5-19
Add Catalog Entry	5-19
Edit Catalog Entry	5-19
Database	5-19
Table	5-19
Manufacturer	5-20
Type	5-20
Style	5-20

Show BOM Details	5-20
Filter by WDBLKNAM value: XX	5-20
Use MISC_CAT table	5-21
Display subassembly entries only for editing	5-21
Creating a Project Specific Catalog Database	5-21
Project	5-21
Existing catalog file Area	5-21
Create project-specific catalog file Area	5-22
Creating Parent-Child Relationships	5-23
Component Tag Area	5-24
Inserting Components from the Equipment List	5-27
Default Settings	5-29
Read Settings	5-29
View/Edit Settings Area	5-29
Inserting Components from the Catalog List	5-32
Sort by	5-33
Add	5-33
Edit	5-33
Delete	5-34
Adding a New Record in the Schematic Component or Circuit Dialog Box	5-34
Editing an Existing Record in the Schematic Component or Circuit Dialog Box	5-37
Inserting Components from Panel Lists	5-38
Extract Component List for Area	5-38
Installation Codes to Extract Area	5-40
Location Codes to Extract Area	5-40
Swapping and Updating blocks	5-45
Option A: Swap Block (swap to different block name) Area	5-46
Option B: Update Block (revised or different version of same block name) Area	5-47
Attribute Mapping Area	5-50
Tutorial 1	5-51
Tutorial 2	5-57
Tutorial 3	5-59
Tutorial 4	5-62
Self-Evaluation Test	5-66
Review Questions	5-67
Exercise 1	5-68

Chapter 6: Schematic Editing

Introduction	6-2
Changing the Component Location with Scoot Tool	6-2
Changing Component Locations using the Move Component Tool	6-4
Copying a Component	6-5
Aligning Components	6-6
Deleting Components	6-7

Updating Components from Catalog Database	6-9
Update Components on Area	6-9
View Previous Report Area	6-11
Settings Area	6-11
Updating a Schematic Component from a One-Line Component	6-12
Surfing a Reference	6-13
Type	6-13
Sheet,Reference	6-14
Installation	6-14
Location	6-14
Category	6-14
Show more	6-14
Freshen	6-14
Edit	6-15
Catalog Check	6-15
Pick New List	6-15
Toggling between the Normally Open and Normally Closed Contacts	6-16
Copying the Catalog Assignment	6-17
Manufacturer	6-18
Catalog	6-18
Assembly	6-18
Catalog Lookup	6-18
Find: Drawing Only	6-18
Multiple Catalog	6-18
Catalog Check	6-19
Copying Installation/Location Code Values	6-20
Pick Master	6-20
Select Installation/Location Codes to Copy Area	6-20
Auditing Drawings	6-21
Electrical Auditing	6-22
Auditing a Drawing	6-26
Retagging Drawings	6-30
Component Retag	6-30
Component Cross-Reference Update	6-30
Wire Number and Signal Tag/Retag	6-31
Ladder References	6-31
Sheet (%S value)	6-32
Drawing (%D value)	6-32
Other Configuration Settings	6-32
Title Block Update	6-34
Using Tools for Editing Attributes	6-34
Moving Attributes	6-34
Editing Attributes	6-35
Hiding Attributes	6-36
Unhiding Attributes	6-37
Adding Attributes	6-37
Squeezing an Attribute/Text	6-38

Stretching an Attribute/Text	6-38
Changing the Attribute Size	6-39
Rotating an Attribute	6-40
Changing the Justification of an Attribute	6-40
Changing an Attribute Layer	6-41
Tutorial 1	6-42
Tutorial 2	6-53
Tutorial 3	6-56
Self-Evaluation Test	6-61
Review Questions	6-62
Exercise 1	6-63
Exercise 2	6-63
Exercise 3	6-64

Chapter 7: Connectors, Point-to-Point Wiring Diagrams, and Circuits

Introduction	7-2
Inserting Connectors	7-2
Layout Area	7-3
Orientation Area	7-6
Details	7-7
Type Area	7-7
Display Area	7-8
Size Area	7-9
Insert	7-9
Inserting a Connector from the List	7-10
Editing Connectors	7-10
Adding Pins to a Connector	7-10
Deleting a Connector Pin	7-11
Moving a Connector Pin	7-11
Swapping Connector Pins	7-12
Reversing a Connector	7-13
Rotating a Connector	7-13
Stretching a Connector	7-15
Splitting a Connector	7-15
Editing Pin Numbers of a Connector	7-19
Pin List Area	7-20
Sheet, Reference	7-20
Plug	7-20
Description	7-20
Receptacle	7-21
Wire Numbers	7-21
Pin Numbers Area	7-21
Pin Descriptions	7-21
Using Point-to-point Wiring Diagrams	7-21
Inserting Splices	7-22

Inserting Wires into Connectors	7-23
Inserting Multiple Wire Bus into Connectors	7-24
Bending Wires at Right Angles	7-25
Working with Circuits	7-25
Saving Circuits to an Icon Menu	7-26
Inserting Saved Circuits	7-29
Moving Circuits	7-31
Copying Circuits	7-33
Saving Circuits by using WBlock	7-35
Inserting the WBlocked Circuit	7-36
Building a Circuit	7-37
Inserting a Circuit	7-37
Configuring a Circuit	7-42
Multiple Phase Circuits	7-45
Adding Multiple Phase Ladders and Wires	7-45
Adding Three-phase Symbols	7-46
Tutorial 1	7-47
Tutorial 2	7-53
Tutorial 3	7-57
Tutorial 4	7-62
Self-Evaluation Test	7-65
Review Questions	7-66
Exercise 1	7-67
Exercise 2	7-67

Chapter 8: Panel Layouts

Introduction	8-2
The WD_PNLM Block File	8-2
Creating Panel Layouts from Schematic List	8-3
Extract Component List for Area	8-4
Browse	8-5
Location Codes to Extract Area	8-5
Selecting Schematic Components for Inserting them into a Panel Drawing	8-5
Annotating and Editing Footprints	8-11
Item Number Area	8-11
Catalog Data Area	8-12
Rating Area	8-14
Component Tag Area	8-15
Description Area	8-16
Installation / Location codes (for reports) Area	8-17
Switch Positions	8-17
Show/Edit Miscellaneous	8-17
Inserting Footprints from the Icon Menu	8-17
Choice A Area	8-20
Choice B Area	8-20

Choice C Area	8-22
Inserting Footprints Manually	8-24
Inserting Footprints from a Catalog List	8-25
Inserting Footprints from an Equipment List	8-26
Inserting Footprints from Vendor Menus	8-28
Copying a Footprint	8-30
Setting the Panel Drawing Configuration	8-30
Item numbering Area	8-30
Balloon Area	8-31
Footprint Layers Area	8-33
Default Spacing for Multiple Inserts Area	8-35
Footprint Insert Area	8-35
Panel Wire Connection Report XYZ Offset Reference Area	8-35
Making the Xdata Visible	8-35
XData	8-36
Value	8-36
Height	8-37
Justify	8-37
Visible	8-37
Ratings	8-37
Style	8-37
Insert	8-37
Renaming Panel Layers	8-38
Adding a Balloon to a Component	8-38
Adding Multiple Balloons	8-42
Resequencing Item Numbers	8-44
Start	8-44
Process blank items only	8-44
Drawings to Process Area	8-44
Manufacturers to Process Area	8-44
Inserting Nameplates	8-45
Inserting DIN Rail	8-49
Rail Type Area	8-50
Origin and Length Area	8-50
Orientation Area	8-50
Scale Area	8-51
Panel Mounting Area	8-51
Editing the Panel Footprint Lookup Database File	8-52
Edit Existing Table	8-52
Create New Table	8-53
Create Empty File	8-53
Tutorial 1	8-54
Tutorial 2	8-57
Tutorial 3	8-60
Tutorial 4	8-63
Tutorial 5	8-66
Self-Evaluation Test	8-69

Review Questions	8-69
Exercise 1	8-70
Exercise 2	8-71
Exercise 3	8-72

Chapter 9: Schematic and Panel Reports

Introduction	9-2
Generating Schematic Reports	9-2
Bill of Material Reports	9-2
Missing Bill of Material Reports	9-5
Component Reports	9-6
From/To Reports	9-7
Component Wire List Reports	9-12
Connector Plug Reports	9-13
PLC I/O Address and Descriptions Reports	9-14
PLC I/O Component Connection Reports	9-14
PLC Modules Used So Far Reports	9-14
Terminal Numbers Reports	9-14
Terminal Plan Reports	9-14
Connector Summary Reports	9-14
Connector Detail Reports	9-14
Cable Summary Reports	9-14
Cable From/To Reports	9-14
Wire Label Reports	9-15
Wire Signal and Stand-alone Reference Reports	9-15
Report Generator Dialog Box	9-16
Header Area	9-17
Breaks Area	9-17
Squeeze	9-18
Add Blanks between Entries	9-18
Sort	9-18
User Post	9-18
Change Report Format	9-19
Edit Mode	9-19
Put on Drawing	9-20
Save to File	9-21
Print	9-21
Wide>	9-21
Surf	9-21
Pin chart Area	9-21
Internal/External Codes Left/right	9-23
Plug/Male side, Jack/Female side, Show All	9-23
Edit Wire Label and Edit Cable Label	9-23
Changing Report Formats	9-23
Available Fields Area	9-24
Fields to Report Area	9-24

Change field name/justification Area	9-25
Lines for Description Area	9-25
Adding Fields using the User Attributes Tool	9-26
Placing Reports in the Drawing	9-28
Table Area	9-28
Text Area	9-28
Column Width Area	9-28
First New Section Placement Area	9-29
Column Labels Area	9-29
Borders Area	9-29
Row Definition Area	9-29
Section Definition Area	9-30
Title Area	9-30
Layer	9-31
Saving the Report to Files	9-32
Editing a Report	9-34
New lines Area	9-35
Edit	9-37
Swap	9-38
Generating Panel Reports	9-38
Bill of Material Reports	9-38
Generating the Cumulative Report	9-40
Report Name Area	9-40
Format File Name Area	9-41
Modify Output	9-42
Selected Reports Area	9-42
Save Report Grouping	9-43
Open Report Grouping	9-43
Drawing Information for Table Output Area	9-43
Setting the Format File for Reports	9-44
Format File Area	9-44
Save Report to File	9-45
Change Report Fields	9-45
Put on Drawing	9-46
Sort Fields	9-46
Tutorial 1	9-47
Tutorial 2	9-53
Self-Evaluation Test	9-56
Review Questions	9-57
Exercise 1	9-58
Exercise 2	9-58

Chapter 10: PLC Modules

Introduction	10-2
Inserting Parametric PLC Modules	10-2
Manufacturer Catalog Tree	10-2

Graphics Style Area	10-3
Scale Area	10-4
List	10-4
Inserting Spacers and Breaks	10-6
Inserting Nonparametric PLC Modules	10-9
Editing a PLC Module	10-10
Addressing Area	10-11
I/O Point Description Area	10-13
Installation/Location Codes Area	10-14
Pins Area	10-14
Inserting Individual PLC I/O Points	10-15
Creating and Modifying Parametric PLC Modules	10-17
PLC Module Selection List	10-17
Terminal Grid Area	10-19
Terminal Attributes Area	10-21
New Module	10-22
Module Specifications	10-24
Style Box Dimensions	10-25
Settings	10-25
Using the Spreadsheet to PLC I/O Utility Tool	10-28
Settings	10-29
Setup	10-29
Ladder Reference Numbering Area	10-29
Module Placement Area	10-30
Drawing File Creation Area	10-31
Modifying and Saving the New Setting Configuration	10-32
Mapping the Spreadsheet Information	10-36
Spreadsheet Data Area	10-36
Assign Spreadsheet or Table Column Numbers to Data Categories below Area	10-36
Tagging based on PLC I/O Address	10-38
Tutorial 1	10-39
Tutorial 2	10-43
Tutorial 3	10-47
Self-Evaluation Test	10-49
Review Questions	10-49
Exercise 1	10-50
Exercise 2	10-51

Chapter 11: Terminals

Introduction	11-2
Inserting Terminal Symbols	11-2
Annotating and Editing Terminal Symbols	11-3
Inserting Terminal from the Schematic List	11-8
Inserting Terminals Manually	11-10
Inserting Terminals from the Panel List	11-11

Adding and Modifying Associations	11-13
Active Association Area	11-14
Select Association Area	11-15
Terminal Block Properties	11-16
Manufacturer	11-16
Catalog Number	11-17
Assembly Code	11-17
Levels	11-17
Terminal Block Property Grid	11-17
Assign Jumper	11-17
Delete Jumper	11-17
Selecting, Creating, Editing, and Inserting Terminal Strips	11-18
Editing the Terminal Strip	11-19
Defining the Settings of a Terminal Strip Table	11-36
Generating the Terminal Strip Table	11-39
Editing and Creating the Terminal Properties Database Table	11-40
Editing the Terminal Properties Database Table	11-41
Creating the Terminal Properties Database Table	11-44
Resequencing Terminal Numbers	11-45
First Method	11-45
Second Method	11-45
Copying Terminal Block Properties	11-46
Editing Jumpers	11-47
The Browse Option	11-47
The Edit Option	11-50
The Show Option	11-50
Tutorial 1	11-50
Tutorial 2	11-52
Self-Evaluation Test	11-57
Review Questions	11-58
Exercise 1	11-59
Exercise 2	11-59

Chapter 12: Settings, Configurations, Templates, and Plotting

Introduction	12-2
Setting Project Properties	12-2
Project Settings Tab	12-3
Components Tab	12-5
Wire Numbers Tab	12-10
Cross-References Tab	12-12
Styles Tab	12-14
Drawing Format Tab	12-16
Setting Drawing Properties	12-20
Drawing Settings Tab	12-22
Reference Files	12-23

Project Files (.WDP File)	12-23
Project Description Line Files (.WDL File)	12-24
Component Reference Files	12-26
Mapping the Title block	12-27
Method 1 Area	12-28
Method 2 Area	12-30
Setting up the Title Block	12-31
Updating Title Blocks	12-34
Select Line(s) to Update (Project Description Lines) Area	12-35
Select Line(s) to update (these are per-drawing values) Area	12-37
Activate each drawing to process	12-38
Creating Templates	12-39
Description Area	12-40
Measurement	12-40
New Layer Notification Area	12-40
Plotting the Project	12-40
Layout Tab to Plot	12-41
Pick List (from active drawing)	12-41
(Optional) For Each Drawing Area	12-42
Output device name Area	12-43
Plot to File Area	12-43
Order Area	12-43
Project Task List	12-44
Tutorial 1	12-45
Tutorial 2	12-47
Tutorial 3	12-49
Tutorial 4	12-51
Self-Evaluation Test	12-54
Review Questions	12-55
Exercise 1	12-56
Exercise 2	12-56
Exercise 3	12-57

Chapter 13: Creating Symbols

Introduction	13-2
Creating symbols	13-2
Name	13-2
Objects Area	13-2
Insertion Point Area	13-3
Attribute Template Area	13-3
Preview Area	13-4
Common Tools	13-5
Required Rollout	13-8
Optional Rollout	13-11
POS Rollout	13-11
Rating Rollout	13-11

Wire Connection Rollout	13-11
Pins Rollout	13-13
Link Lines Rollout	13-13
Symbol Area	13-14
Base Point Area	13-15
Image Area	13-15
Naming Convention of Symbols	13-16
Schematic Symbols	13-16
Panel Layout Footprint Symbols	13-17
Connector Symbols	13-17
Plug / Jack Connector Pin Symbols	13-17
Splice Symbol	13-18
Parametric Twisted Pair Symbols	13-18
Stand-alone PLC I/O Point Symbols	13-18
PLC I/O Parametric Build Symbols	13-18
Stand-alone Terminal Symbols	13-19
Wire Number Symbols	13-19
Wire Dot Symbols	13-19
Source / Destination Wire Signal Arrow Symbols	13-19
Cable Marker Symbols	13-19
Inline Wire Marker Symbols	13-20
One-line Symbol	13-20
Customizing the Icon Menu	13-20
Add	13-22
Miscellaneous Tools	13-26
Marking and Verifying Drawings	13-26
Exporting the Data to Spreadsheets	13-29
Updating the Data from the Spreadsheet	13-33
Using Project-Wide Utilities	13-34
Tutorial 1	13-37
Tutorial 2	13-42
Self-Evaluation Test	13-46
Review Questions	13-46
Exercise 1	13-47
Exercise 2	13-48

Chapter 14: Projects

Project 1	14-2
Project 2	14-39

Index	I-1
--------------	------------