

Table of Contents

Dedication	iii
Preface	xix

Chapter 1: Introduction

Introduction to Autodesk Inventor 2011	1-2
Part Module	1-2
Assembly Module	1-2
Presentation Module	1-3
Drawing Module	1-3
Sheet Metal Module	1-3
Getting Started with Autodesk Inventor	1-3
Quick Access Toolbar	1-7
Ribbon and Tabs	1-7
Sketch Tab	1-8
Model Tab	1-8
Sheet Metal Tab	1-9
Assemble Tab	1-9
Place Views Tab	1-9
Presentation Tab	1-10
Tools Tab	1-10
View Tab	1-10
Navigation Bar	1-11
Browser Bar	1-11
Units for Dimensions	1-12
Important terms and their definitions	1-12
Feature-based Modeling	1-12
Parametric Modeling	1-12
Bidirectional Associativity	1-12
Adaptive	1-13
Design Doctor	1-13
Constraints	1-13
Consumed Sketch	1-15
Cycling Through Entities	1-16
Hotkeys	1-16
Part Module	1-16
Assembly Module	1-17
Drawing Module	1-18
Customizing Hotkeys	1-18
Creating the Sketch	1-20
Color Scheme	1-20
Self-Evaluation Test	1-21
Review Questions	1-22

Chapter 2: Drawing Sketches for Solid Models

The Sketching Environment	2-2
The Open Dialog Box	2-2
Starting a New File	2-5
Introduction to the Sketching Environment	2-7
Setting Up The Sketching Environment	2-7
Modifying the Document Settings of a Sketch	2-8
Understanding the Drawing Display Tools	2-9
Zoom All	2-10
Zoom Window	2-10
Zoom	2-10
Zoom Selected	2-10
Pan	2-11
Sketching Entities	2-11
Specifying the Position of Entities Dynamically by Using the Dynamic Input <i>New</i>	2-11
Drawing Lines <i>Enhanced</i>	2-12
Drawing Circles	2-15
Drawing Ellipses	2-16
Drawing Arcs <i>Enhanced</i>	2-17
Drawing Rectangles <i>Enhanced</i>	2-19
Drawing Polygons	2-20
Placing Points	2-21
Creating Fillets	2-21
Creating Chamfers	2-22
Drawing Splines	2-24
Creating a Smooth Curve between Two Existing Curves <i>New</i>	2-25
Deleting Sketched Entities	2-26
Deleting Entities by Using a Window	2-26
Deleting Entities by Using a Crossing	2-26
Finishing a Sketch <i>New</i>	2-26
Tutorial 1	2-27
Tutorial 2	2-31
Tutorial 3	2-34
Tutorial 4	2-38
Self-Evaluation Test	2-41
Review Questions	2-42
Exercise 1	2-43
Exercise 2	2-43
Exercise 3	2-44

Chapter 3: Adding Constraints and Dimensions to Sketches

Adding Geometric Constraints to a Sketch	3-2
Perpendicular Constraint	3-2
Parallel Constraint	3-2
Tangent Constraint	3-3
Coincident Constraint	3-3

Concentric Constraint	3-3
Collinear Constraint	3-4
Horizontal Constraint	3-4
Vertical Constraint	3-4
Equal Constraint	3-5
Fix Constraint	3-5
Symmetric Constraint	3-5
Smooth Constraint	3-6
Viewing the Constraints Applied to a Sketched Entity	3-6
Controlling Constraints and Applying them Automatically While Sketching	3-7
Selecting Constraints	3-7
Applying Constraints	3-8
Deleting Geometric Constraints	3-8
Adding Dimensions to Sketches	3-9
Linear Dimensioning	3-9
Aligned Dimensioning	3-11
Angular Dimensioning	3-11
Diameter Dimensioning	3-12
Radius Dimensioning	3-13
Linear Diameter Dimensioning	3-14
Creating Driven Dimensions	3-15
Understanding the Concept of Fully-Constrained Sketches	3-16
Measuring Sketched Entities	3-17
Measuring Distances	3-17
Measuring Angles	3-19
Measuring Loops	3-20
Measuring the Area	3-20
Adding Linear Measurements	3-20
Clearing Accumulated Dimensions	3-21
Evaluating Region Properties	3-21
Tutorial 1	3-22
Tutorial 2	3-26
Tutorial 3	3-31
Tutorial 4	3-36
Self-Evaluation Test	3-39
Review Questions	3-39
Exercise 1	3-41
Exercise 2	3-41
Exercise 3	3-41
Exercise 4	3-42
Exercise 5	3-42

Chapter 4: Editing, Extruding, and Revolving the Sketches

Editing Sketched Entities	4-2
Extending Sketched Entities	4-2
Trimming Sketched Entities	4-2

Splitting Sketched Entities	4-3
Offsetting Sketched Entities	4-4
Mirroring Sketched Entities	4-5
Moving Sketched Entities	4-5
Rotating Sketched Entities	4-9
Creating Patterns	4-10
Creating Rectangular Patterns	4-10
Creating Circular Patterns	4-13
Writing Text in the Sketching Environment	4-16
Writing Regular Text	4-16
Writing Text Aligned to a Geometry	4-19
Inserting Images and Documents in Sketches	4-20
Editing Sketched Entities by Dragging	4-21
Tolerances	4-22
Adding Tolerances to the Dimensions in the Sketching Environment	4-22
Converting the Base Sketch into a Base Feature	4-23
Extruding the Sketch <i>Enhanced</i>	4-24
Revolving the Sketch <i>Enhanced</i>	4-28
Direct Manipulation of Features by Using the Mini Toolbar <i>New</i>	4-30
Selection tag	4-30
Command Options	4-31
Manipulators	4-31
Rotating the View of a Model in 3D Space	4-32
Rotating the View of a Model Using the Orbit	4-32
Changing the View Using the ViewCube	4-33
Navigating the Model	4-36
Controlling the Display of Models	4-37
Setting the Visual Styles <i>Enhanced</i>	4-37
Setting the Shadow Options <i>Enhanced</i>	4-39
Setting the Camera Type	4-40
Tutorial 1	4-40
Tutorial 2	4-45
Tutorial 3	4-47
Tutorial 4	4-51
Self-Evaluation Test	4-54
Review Questions	4-54
Exercise 1	4-56
Exercise 2	4-56
Exercise 3	4-57
Exercise 4	4-57
Exercise 5	4-58

Chapter 5: Other Sketching and Modeling Options

Need for other Sketching Planes	5-2
Defining a New Sketching Plane	5-2
Work Features <i>Enhanced</i>	5-3

Creating Work Planes	5-3
Creating Work Axes	5-13
Creating Work Points	5-16
Other Extrusion Options	5-20
Other Revolution Options	5-25
Operations Area	5-25
Match shape	5-26
The Concept of Sketch Sharing	5-27
Sharing Sketches	5-27
Tutorial 1	5-28
Tutorial 2	5-33
Tutorial 3	5-37
Self-Evaluation Test	5-42
Review Questions	5-43
Exercise 1	5-44
Exercise 2	5-44
Exercise 3	5-45
Exercise 4	5-46

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools	6-2
Creating Holes <i>Enhanced</i>	6-2
Creating Fillets <i>Enhanced</i>	6-12
Creating Edge Fillets	6-12
Creating Face Fillets	6-19
Creating Full Round Fillets	6-20
Creating Chamfers <i>Enhanced</i>	6-22
Mirroring Features and Models	6-24
Creating Rectangular Patterns	6-26
Creating Circular Patterns	6-29
Creating Rib Features	6-31
Thickening or Offsetting the Faces of Features	6-33
Creating the Embossed and Engraved Features	6-37
Applying Images on a Feature	6-39
Assigning Different Colors/styles to a Model	6-40
Tutorial 1	6-40
Tutorial 2	6-46
Tutorial 3	6-53
Tutorial 4	6-59
Self-Evaluation Test	6-63
Review Questions	6-63
Exercise 1	6-64
Exercise 2	6-65

Chapter 7: Editing Features and Adding Automatic Dimensions to Sketches

Concept of Editing Features	7-2
Editing Features of a Model	7-2
Updating Edited Features	7-4
Editing Features Dynamically by Using 3D Grips	7-5
Editing the Sketches of Features	7-6
Redefining the Sketching Plane of a Sketched Feature	7-8
Suppressing Features	7-9
Unsuppressing the Suppressed Features	7-9
Moving the Faces of a Solid <i>Enhanced</i>	7-10
Free Move Method	7-10
Direction and Distance Method	7-11
Points and Plane Method	7-11
Deleting Features	7-11
Copying and Pasting Features	7-12
Adding Automatic Dimensions to Sketches	7-15
Projecting Entities in the Sketching Environment	7-16
Projecting Edges or Faces	7-16
Projecting Cutting Edges	7-17
Tutorial 1	7-17
Tutorial 2	7-24
Tutorial 3	7-28
Self-Evaluation Test	7-34
Review Questions	7-35
Exercise 1	7-36
Exercise 2	7-37
Exercise 3	7-38
Exercise 4	7-38
Exercise 5	7-39

Chapter 8: Advanced Modeling Tools-II

Advanced Modeling Tools	8-2
Creating Sweep Features	8-2
Creating Lofted Features	8-8
Creating Coil Features	8-18
Creating Threads	8-22
Creating Shell Features	8-25
Applying Drafts	8-27
Creating Split Features	8-29
Trimming Surfaces	8-31
Extending Surfaces	8-33
Deleting Faces	8-34
Replacing Faces with Surfaces	8-36
Creating Planar Boundary Patches	8-37
Stitching Surfaces	8-39

Working with the Sculpt Tool	8-40
Working with the Bend Part Tool	8-41
Reordering the Features	8-44
Using the Sketch Doctor	8-45
Using the Design Doctor	8-46
Tutorial 1	8-47
Tutorial 2	8-51
Tutorial 3	8-53
Tutorial 4	8-55
Tutorial 5	8-58
Self-Evaluation Test	8-61
Review Questions	8-61
Exercise 1	8-62
Exercise 2	8-63

Chapter 9: Assembly Modeling-I

Assembly Modeling	9-2
Types of Assemblies	9-2
Top-down Assemblies	9-3
Bottom-up Assemblies	9-3
Creating Top-down Assemblies	9-4
Creating Components in the Assembly Module	9-4
Creating Bottom-Up Assemblies	9-7
Placing Components in the Assembly File	9-7
Assembling Components by Using the Constrain Tool	9-8
Mate Constraint	9-9
Angle Constraint	9-11
Tangent Constraint	9-13
Insert Constraint	9-13
Rotation Constraint	9-14
Rotation-Translation Constraint	9-15
Transitional Constraint	9-16
Specifying the Limits for Constraining <i>New</i>	9-16
Name	9-16
Use Offset As Resting Position	9-16
Maximum	9-17
Minimum	9-17
Assembling Parts by Using the Assemble Tool <i>New</i>	9-17
Using ALT+Drag to Apply Assembly Constraints	9-18
Moving Individual Components	9-19
Rotating Individual Components in 3D Space	9-19
Tutorial 1	9-20
Tutorial 2	9-35
Tutorial 3	9-42
Self-Evaluation Test	9-51
Review Questions	9-52
Exercise 1	9-53

Chapter 10: Assembly Modeling-II

Editing Assembly Constraints	10-2
Editing Components	10-3
Editing Components in the Assembly File	10-3
Editing Components by Opening their Part Files	10-5
Creating Subassemblies	10-5
Creating a Subassembly Using the Bottom-up Design Approach	10-6
Creating a Subassembly Using the Top-down Design Approach	10-6
Checking Degrees of Freedom of a Component	10-6
Creating the Pattern of Components in an Assembly	10-7
Component	10-8
Associative Tab	10-8
Rectangular Tab	10-9
Circular Tab	10-9
Replacing a Component From the Assembly File with another Component	10-10
Replacing a Single Instance of the Selected Component	10-10
Replacing all Instances of the Selected Component	10-11
Mirroring Subassemblies or Components of An Assembly	10-12
Components	10-12
Mirror Plane	10-12
List Box	10-13
More	10-13
List Box	10-13
Naming Scheme Area	10-14
Component Destination Area	10-15
Return to Selection	10-15
Copying Subassemblies or Components of an Assembly	10-15
Deleting Components	10-16
Editing the Pattern of Components	10-16
Making a Pattern Instance Independent	10-16
Deleting Assembly Constraints	10-17
Creating Assembly Section Views in the Assembly File	10-17
Analyzing Assemblies for Interference	10-18
Creating Design View Representations	10-20
Design View Representation Area	10-21
Simulating the Motion of Components of an Assembly by Driving	
Assembly Constraints	10-21
Start	10-22
End	10-22
Pause Delay	10-22
Forward	10-23
Reverse	10-23
Pause	10-23
Minimum	10-23
Reverse Step	10-23
Forward Step	10-23

Maximum	10-23
Record	10-23
More	10-24
Creating Positional Representations	10-25
Viewing the Bill of Material of the Current Assembly	10-26
Working with Assembly Features	10-27
Tutorial 1	10-28
Tutorial 2	10-30
Tutorial 3	10-32
Self-Evaluation Test	10-38
Review Questions	10-38
Exercise 1	10-39

Chapter 11: Working with Drawing Views-I

The Drawing Module	11-2
Types of Views	11-3
Base View	11-3
Projected View	11-3
Auxiliary View	11-4
Section View	11-4
Detail View	11-4
Broken View	11-4
Break Out View	11-4
Overlay View	11-4
Slice View	11-4
Generating Drawing Views	11-5
Generating the Base View <i>Enhanced</i>	11-5
Generating Projected Views	11-10
Generating Auxiliary Views	11-12
Generating Section Views	11-13
Generating Detail Views	11-14
Generating Broken Views	11-16
Generating Break Out Views	11-18
Generating Overlay Views	11-20
Generating Slice Views	11-22
Drafting Drawing Views	11-23
Editing Drawing Views	11-23
Deleting Drawing Views	11-24
Moving Drawing Views	11-25
Copying Drawing Views	11-25
Rotating Drawing Views	11-25
By Area	11-26
Counter clockwise	11-26
Clockwise	11-26
Assigning Different Hatch Patterns to the Components in Assembly Section Views	11-26

By Material	11-27
Angle	11-27
Line Weight	11-28
Scale	11-28
Shift	11-28
Color	11-28
Double	11-28
Editing the Default Hatch Style of the Sectioned Objects <i>New</i>	11-29
Excluding the Components from Assembly Section Views	11-30
Tutorial 1	11-31
Tutorial 2	11-37
Self-Evaluation Test	11-42
Review Questions	11-42
Exercise 1	11-43

Chapter 12: Working with Drawing Views-II

Modifying Drawing Standards	12-2
Inserting Additional Sheets into Drawing	12-3
Activating a Drawing Sheet	12-3
Displaying Dimensions in Drawing Views	12-3
Retrieving Parametric Dimensions in Drawing Views	12-4
Adding Reference Dimensions	12-5
Modifying the Model Dimensions	12-5
Editing Drawing Sheets	12-5
Format Area	12-6
Revision	12-6
Orientation Area	12-6
Options Area	12-6
Creating Dimension Styles	12-7
Applying Dimension Styles	12-8
Modifying a Dimension and its Appearance using the Shortcut Menu	12-8
Adding the Parts List	12-8
Source Area	12-8
BOM Settings and Properties Area	12-10
Table Wrapping Area	12-10
Editing the Parts List	12-11
Column Chooser	12-12
Group Settings	12-12
Filter Settings	12-13
Sort	12-13
Export	12-13
Table Layout	12-13
Renumber Items	12-13
Save Item Overrides to BOM	12-14
Member Selection	12-14
Adding/Removing Custom Parts	12-14

Shortcut Menu Options	12-14
Setting the Standard for the Parts List	12-15
Adding Balloons to Assembly Drawing Views	12-15
Adding Balloons to Selected Components	12-16
Adding Automatic Balloons	12-16
Adding Text to a Drawing Sheet	12-18
Adding Multiline Text without a Leader	12-19
Adding Multiline Text with Leader	12-20
Tutorial 1	12-21
Tutorial 2	12-26
Tutorial 3	12-31
Self-Evaluation Test	12-36
Review Questions	12-36
Exercise 1	12-37

Chapter 13: Presentation Module

The Presentation Module	13-2
Creating the Presentation View	13-3
Assembly Area	13-3
Explosion Method Area	13-4
Defining Units for Presentation Files	13-6
Tweaking Components in the Presentation View	13-6
Create Tweak Area	13-6
Transformations Area	13-8
Clear	13-9
Animating an Assembly	13-9
Rotating the Presentation View Precisely	13-15
Increment	13-15
Rotate Down	13-15
Rotate Up	13-15
Rotate Left	13-15
Rotate Right	13-15
Roll Counter Clockwise	13-15
Roll Clockwise	13-15
Reset	13-15
Tutorial 1	13-16
Tutorial 2	13-23
Self-Evaluation Test	13-30
Review Questions	13-30
Exercise 1	13-31

Chapter 14: Working with Special Design Tools

Adaptive Parts	14-2
Defining Parameters <i>Enhanced</i>	14-2
Model Parameters	14-2

User Parameters	14-4
Update	14-5
Immediate Update	14-5
Link	14-5
Filter	14-6
Working with iParts	14-7
Types of iPart Factories	14-7
Creating iPart Factories	14-7
Procedure to Create an iPart	14-13
Inserting an iPart into an Assembly	14-14
Changing the iParts in the Assembly File	14-17
Creating 3D Sketches	14-18
Line	14-18
Spline	14-19
Bend	14-19
Include Geometry	14-19
Intersection Curve	14-19
Helical Curve	14-19
Tutorial 1	14-21
Tutorial 2	14-25
Tutorial 3	14-29
Tutorial 4	14-33
Tutorial 5	14-36
Self-Evaluation Test	14-43
Review Questions	14-44
Exercise 1	14-45

Chapter 15: Working with Sheet Metal Components

The Sheet Metal Module	15-2
Setting Sheet Metal Component Parameters	15-4
Setting the Sheet Metal Rule	15-4
Setting the Material Style	15-12
Setting the Unfolding Rule	15-12
Creating Sheet Metal Components	15-14
Shape Tab	15-16
Unfold Options Tab	15-18
Bend Tab	15-18
Folding Sheet Metal Components	15-18
Adding Flanges to Sheet Metal Components	15-20
Creating Cuts in Sheet Metal Components	15-25
Creating Seams at the Corners of Sheet Metal Components	15-26
Bending the Faces of a Sheet Metal Component	15-30
Rounding the Corners of Sheet Metal Components	15-33
Corner	15-33
Radius	15-33
Select Mode Area	15-33

Chamfering the Corners of Sheet Metal Components	15-34
One Distance	15-34
Distance and Angle	15-35
Two Distances	15-35
Punching 3D shapes into Sheet Metal Components	15-35
Preview Tab	15-36
Geometry Tab	15-37
Size Tab	15-37
Creating Hems	15-38
Creating Contour Flanges	15-40
Creating the Flat Patterns of Sheet Metal Components	15-42
Adding or Removing Material from the Flat Pattern	15-43
Tutorial 1	15-44
Tutorial 2	15-50
Self-Evaluation Test	15-56
Review Questions	15-57
Exercise 1	15-58

Chapter 16: Introduction to Weldments

Understanding Weldment Assemblies	16-2
Main Types of Welds in Autodesk Inventor	16-3
Cosmetic Welds	16-3
Fillet Welds	16-4
Groove Welds	16-5
Adding Welds to Assemblies	16-5
Assembling the Components of Weldment Assemblies	16-6
Preparing Assemblies for Weldments	16-6
Adding Welds	16-6
Creating Fillet Welds	16-6
Bead Area	16-6
Contour Area	16-7
Intermittency Area	16-7
Extents Area	16-7
Create Welding Symbol	16-8
Creating Cosmetic Welds	16-8
Bead Area	16-9
Creating Groove Welds	16-10
Bead Area	16-10
Tutorial 1	16-11
Tutorial 2	16-16
Self-Evaluation Test	16-20
Review Questions	16-21
Exercise 1	16-22

Chapter 17: Miscellaneous Tools

Introduction	17-2
Copying the Sketches	17-2
Scaling the Sketches	17-3
Finding the Center of Gravity	17-3
Extracting the iFeature	17-4
Type Area	17-4
Selected Features Area	17-5
Size Parameters Area	17-5
Position Geometry Area	17-5
Manufacturing Area	17-5
Depth Area	17-6
Inserting the iFeature	17-6
Select	17-6
Position	17-6
Size	17-7
Precise Pos.	17-7
Creating iMates	17-7
Name Area	17-8
Limits Tab	17-8
Matching Tab	17-8
Applying iMates in the Assembly Environment	17-9
Interactively place with iMates	17-9
Automatically generate iMates on place	17-9
Viewing the iProperties	17-9
General Tab	17-9
Summary Tab	17-10
Project Tab	17-10
Status Tab	17-10
Custom Tab	17-11
Save Tab	17-11
Physical Tab	17-11
Creating User-Defined Drawing Sheets	17-11
Sheet Formats	17-11
Borders	17-11
Title Blocks	17-13
Creating Sketch Symbols	17-17
Importing AutoCAD Blocks into Inventor	17-18
Tutorial 1	17-20
Tutorial 2	17-25
Self-Evaluation Test	17-28
Review Questions	17-29
Exercise 1	17-30