

Table of Contents

Dedication	iii
Preface	xxi

Chapter 1: Introduction

Introduction to Autodesk Inventor 2017	1-2
Part Module	1-2
Assembly Module	1-2
Presentation Module	1-3
Drawing Module	1-3
Sheet Metal Module	1-3
Mold Design Module	1-3
Getting Started with Autodesk Inventor	1-3
Quick Access Toolbar	1-7
Ribbon and Tabs	1-8
Sketch Tab	1-8
3D Model Tab	1-9
Sheet Metal Tab	1-9
Assemble Tab	1-10
Place Views Tab	1-10
Presentation Tab	1-10
Tools Tab	1-10
View Tab	1-10
Navigation Bar	1-11
Browser Bar	1-11
Units for Dimensions	1-12
Important Terms and Their Definitions	1-12
Feature-based Modeling	1-12
Parametric Modeling	1-12
Bidirectional Associativity	1-12
Adaptive	1-13
Design Doctor	1-13
Constraints	1-13
Consumed Sketch	1-16
Stress Analysis Environment	1-16
Select Other Behavior	1-17
Hotkeys	1-17
Part Module	1-17
Assembly Module	1-18
Drawing Module	1-19
Customizing Hotkeys	1-19
Creating the Sketch	1-21
Marking Menu	1-21
Color Scheme	1-22
Self-Evaluation Test	1-23
Review Questions	1-24

Enhanced

Chapter 3: Adding Constraints and Dimensions to Sketches

Adding Geometric Constraints to a Sketch	3-2
Perpendicular Constraint	3-2
Parallel Constraint	3-2
Tangent Constraint	3-3
Coincident Constraint	3-3
Concentric Constraint	3-3
Collinear Constraint	3-4
Horizontal Constraint	3-4
Vertical Constraint	3-4
Equal Constraint	3-5
Fix Constraint	3-5
Symmetric Constraint	3-5
Smooth Constraint	3-6
Viewing the Constraints Applied to a Sketched Entity	3-6
Controlling Constraints and Applying them Automatically while Sketching	3-7
Constraints Settings Dialog Box	3-7
Scope of Constraint Inference	3-8
Deleting Geometric Constraints	3-9
Adding Dimensions to Sketches	3-9
Linear Dimensioning	3-10
Aligned Dimensioning	3-11
Angular Dimensioning	3-12
Diameter Dimensioning	3-14
Radius Dimensioning	3-15
Linear Diameter Dimensioning	3-16
Setting the Scale of a Sketch	3-17
Creating Driven Dimensions	3-18
Understanding the Concept of Fully-Constrained Sketches	3-18
Measuring Sketched Entities	3-19
Measuring Distances	3-19
Measuring Angles	3-21
Measuring Loops	3-22
Measuring the Area	3-22
Adding Linear Measurements	3-22
Clearing Accumulated Dimensions	3-23
Evaluating Region Properties	3-23
Tutorial 1	3-24
Tutorial 2	3-29
Tutorial 3	3-34
Tutorial 4	3-39
Self-Evaluation Test	3-43
Review Questions	3-44
Exercise 1	3-45
Exercise 2	3-45
Exercise 3	3-46
Exercise 4	3-47

Exercise 5	3-47
Exercise 6	3-48

Chapter 4: Editing, Extruding, and Revolving the Sketches

Editing Sketched Entities	4-2
Extending Sketched Entities	4-2
Trimming Sketched Entities	4-2
Splitting Sketched Entities	4-3
Offsetting Sketched Entities	4-4
Mirroring Sketched Entities	4-5
Moving Sketched Entities	4-7
Rotating Sketched Entities	4-9
Creating Patterns	4-11
Creating Rectangular Patterns	4-11
Creating Circular Patterns	4-15
Writing Text in the Sketching Environment	4-17
Writing Regular Text	4-17
Writing Text Aligned to a Geometry	4-20
Inserting Images and Documents in Sketches	4-22
Editing Sketched Entities by Dragging	4-23
Tolerances	4-23
Converting the Base Sketch into a Base Feature	4-25
Extruding the Sketch	4-26
Revolving the Sketch	4-30
Direct Manipulation of Features by Using the Mini Toolbar	4-33
Command Options	4-33
Manipulators	4-33
Rotating the View of a Model in 3D Space	4-34
Rotating the View of a Model Using the Orbit	4-34
Changing the View Using the ViewCube	4-36
Navigating the Model	4-39
Controlling the Display of Models	4-40
Setting the Visual Styles	4-40
Setting the Shadow Options	4-42
Setting the Camera Type	4-43
Creating Freeform Shapes	4-43
Creating Predefined Solid Primitives	4-47
Tutorial 1	4-48
Tutorial 2	4-52
Tutorial 3	4-54
Tutorial 4	4-59
Self-Evaluation Test	4-62
Review Questions	4-62
Exercise 1	4-63
Exercise 2	4-64
Exercise 3	4-65
Exercise 4	4-65

Exercise 5	4-66
Exercise 6	4-66

Chapter 5: Other Sketching and Modeling Options

Need for other Sketching Planes	5-2
Work Features	5-3
Creating Work Planes	5-3
Creating Work Axes	5-13
Creating Work Points	5-17
Other Extrusion Options	5-21
Other Revolution Options	5-27
The Concept of Sketch Sharing	5-29
Tutorial 1	5-30
Tutorial 2	5-36
Tutorial 3	5-40
Self-Evaluation Test	5-45
Review Questions	5-45
Exercise 1	5-47
Exercise 2	5-48
Exercise 3	5-49
Exercise 4	5-49

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools	6-2
Creating Holes	6-2
Creating Fillets	6-12
Creating Chamfers	6-23
Mirroring Features and Models	6-26
Creating Rectangular Patterns	6-29
Creating Circular Patterns	6-32
Creating Sketch Driven Patterns New	6-34
Creating Rib Features	6-35
Thickening or Offsetting the Faces of Features	6-40
Creating the Embossed and Engraved Features	6-44
Applying Images on a Feature	6-46
Assigning Different Colors/Styles to a Model	6-47
Assigning Different Material to a Model	6-48
Modifying the Properties of an Existing Material	6-48
Tutorial 1	6-49
Tutorial 2	6-55
Tutorial 3	6-62
Tutorial 4	6-69
Tutorial 5	6-74
Self-Evaluation Test	6-81
Review Questions	6-82
Exercise 1	6-83

Exercise 2	6-84
Exercise 3	6-85

Chapter 7: Editing Features and Adding Automatic Dimensions to Sketches

Concept of Editing Features	7-2
Editing Features of a Model	7-2
Updating Edited Features	7-4
Editing Features Dynamically by Using 3D Grips	7-4
Editing the Sketches of Features	7-6
Redefining the Sketching Plane of a Sketched Feature	7-8
Suppressing and Unsuppressing the Features	7-9
Editing of a feature using the Direct Tool	7-10
Deleting Features	7-12
Copying and Pasting Features	7-12
Manipulating Features by EOP	7-15
Adding Automatic Dimensions to Sketches	7-15
Projecting Entities in the Sketching Environment	7-17
Projecting Edges or Faces	7-17
Projecting Cutting Edges	7-18
Projecting 2D Sketch on 3D Face	7-18
Projecting DWG Geometry	7-19
Tutorial 1	7-20
Tutorial 2	7-27
Tutorial 3	7-32
Self-Evaluation Test	7-39
Review Questions	7-39
Exercise 1	7-40
Exercise 2	7-41
Exercise 3	7-42
Exercise 4	7-43
Exercise 5	7-44

Chapter 8: Advanced Modeling Tools-II

Advanced Modeling Tools	8-2
Creating Sweep Features	8-2
Creating Lofted Features	8-10
Creating Coil Features	8-20
Creating Threads	8-24
Creating Shell Features	8-27
Applying Drafts	8-29
Creating Split Features	8-32
Trimming Surfaces	8-35
Extending Surfaces	8-36
Deleting Faces	8-37
Replacing Faces with Surfaces	8-39
Creating Planar Boundary Patches	8-40

Stitching Surfaces	8-42
Working with the Sculpt Tool	8-43
Working with the Bend Part Tool	8-44
Reordering the Features	8-47
Understanding the Parent-Child Relationship	8-49
Using the Sketch Doctor	8-49
Using the Design Doctor	8-50
Tutorial 1	8-51
Tutorial 2	8-56
Tutorial 3	8-58
Tutorial 4	8-61
Self-Evaluation Test	8-65
Review Questions	8-65
Exercise 1	8-66
Exercise 2	8-68

Chapter 9: Assembly Modeling-I

Assembly Modeling	9-2
Types of Assemblies	9-2
Top-down Assemblies	9-3
Bottom-up Assemblies	9-3
Creating Top-down Assemblies	9-4
Creating Components in the Assembly Module	9-4
Creating Bottom-Up Assemblies	9-7
Placing Components in the Assembly File	9-7
Assembling Components by Using the Constrain Tool	9-8
Assembly Tab	9-9
Motion Tab	9-16
Transitional Tab	9-19
Constraint Set Tab	9-19
Specifying the Limits for Constraining	9-20
Assembling Parts by Using the Assemble Tool	9-21
Using ALT+Drag to Apply Assembly Constraints	9-22
Applying Joints to the Assembly	9-23
Joint Tab	9-23
Limits Tab	9-27
Showing and Hiding Relationships	9-28
Show Relationship	9-28
Hide Relationship	9-28
Show Sick Relationship	9-29
Moving Individual Components	9-29
Rotating Individual Components in 3D Space	9-29
Tutorial 1	9-30
Tutorial 2	9-47
Tutorial 3	9-56
Tutorial 4	9-67
Self-Evaluation Test	9-77

Review Questions	9-78
Exercise 1	9-79

Chapter 10: Assembly Modeling-II

Editing Assembly Constraints	10-2
Editing Components	10-3
Editing Components in the Assembly File	10-3
Editing Components by Opening their Part Files	10-5
Creating Subassemblies	10-5
Creating a Subassembly Using the Bottom-up Design Approach	10-6
Creating a Subassembly Using the Top-down Design Approach	10-6
Checking Degrees of Freedom of a Component	10-6
Creating Pattern of Components in an Assembly	10-7
Replacing a Component from the Assembly File with Another Component	10-10
Replacing a Single Instance of the Selected Component	10-10
Replacing all Instances of the Selected Component	10-11
Mirroring Subassemblies or Components of an Assembly	10-12
Copying Subassemblies or Components of an Assembly	10-15
Deleting Components	10-16
Editing the Pattern of Components	10-16
Making a Pattern Instance Independent	10-17
Deleting Assembly Constraints	10-17
Creating Assembly Section Views in the Assembly File	10-17
Analyzing Assemblies for Interference	10-19
Creating Design View Representations	10-20
Design View Representation Area	10-21
Positional Representation Area	10-21
Level of Detail Representation	10-22
Simulating the Motion of Components of an Assembly by Driving Assembly Constraint	10-22
Creating Positional Representations	10-25
Viewing the Bill of Material of the Current Assembly	10-26
Working with Assembly Features	10-27
Tutorial 1	10-28
Tutorial 2	10-30
Tutorial 3	10-32
Self-Evaluation Test	10-39
Review Questions	10-40
Exercise 1	10-41

Chapter 11: Working with Drawing Views-I

The Drawing Module	11-2
Types of Views	11-3
Generating Drawing Views	11-5
Generating the Base View	11-5
Generating Projected Views	11-10
Generating Auxiliary Views	11-11

Enhanced

Generating Section Views	11-12
Generating Detail Views	11-14
Generating Broken Views	11-16
Generating Break Out Views	11-18
Generating Overlay Views	11-20
Generating Slice Views	11-22
Drafting Drawing Views	11-23
Editing Drawing Views	11-23
Deleting Drawing Views and Drawing Sheet	11-24
Moving Drawing Views	11-26
Copying Drawing Views	11-26
Rotating Drawing Views	11-26
Changing the Orientation of Drawing Views	11-27
Assigning Different Hatch Patterns to Components in Assembly Section Views	11-29
Editing the Default Hatch Style of the Sectioned Objects	11-32
Excluding Components from Assembly Section Views	11-33
Tutorial 1	11-35
Tutorial 2	11-40
Self-Evaluation Test	11-45
Review Questions	11-46
Exercise 1	11-47

Chapter 12: Working with Drawing Views-II

Modifying Drawing Standards	12-2
Inserting Additional Sheets into Drawing	12-3
Activating a Drawing Sheet	12-3
Displaying Dimensions in Drawing Views	12-3
Retrieving Parametric Dimensions in Drawing Views	12-4
Adding Reference Dimensions	12-5
Modifying the Model Dimensions	12-5
Editing Drawing Sheets	12-5
Creating Dimension Styles	12-7
Applying Dimension Styles	12-8
Modifying a Dimension and its Appearance Using the Shortcut Menu	12-8
Adding the Parts List	12-9
BOM Settings and Properties Area	12-10
Table Wrapping Area	12-10
Editing the Parts List	12-11
Column Chooser	12-12
Group Settings	12-12
Filter Settings	12-13
Sort	12-13
Export	12-13
Table Layout	12-13
Renummer Item	12-13
Save Item Overrides to BOM	12-14
Member Selection	12-14
Adding/Removing Custom Parts	12-14

Shortcut Menu Options	12-14
Setting the Standard for the Parts List	12-14
Adding Balloons to Assembly Drawing Views	12-15
Adding Balloons to Selected Components	12-16
Adding Automatic Balloons	12-16
Adding Text to a Drawing Sheet	12-19
Adding Multiline Text without a Leader	12-19
Adding Multiline Text with Leader	12-20
Tutorial 1	12-21
Tutorial 2	12-25
Tutorial 3	12-31
Self-Evaluation Test	12-35
Review Questions	12-36
Exercise 1	12-37

Chapter 13: Presentation Module

The Presentation Module	Enhanced	13-2
Inserting Assembly in the Presentation Module		13-3
Animating an Assembly		13-5
Tweaking Components in the Presentation Module		13-6
Changing the Opacity of a Component		13-8
Editing the Tweaked components		13-9
Creating Snapshot Views in a Presentation		13-9
Editing Snapshot View		13-10
Defining Units in the Presentation Files		13-10
Creating Storyboard		13-10
Creating Drawing Views of the Snapshot View		13-11
Creating Video of the Presentation Files		13-12
Creating Raster Images of the Presentation Files		13-13
Tutorial 1		13-15
Tutorial 2		13-21
Self-Evaluation Test		13-26
Review Questions		13-27
Exercise 1		13-28

Chapter 14: Working with Sheet Metal Components

The Sheet Metal Module	14-2
Setting Sheet Metal Component Parameters	14-4
Setting the Sheet Metal Rule	14-4
Setting the Material	14-12
Setting the Unfolding Rule	14-13
Creating Sheet Metal Components	14-15
Folding Sheet Metal Components	14-19
Adding Flanges to Sheet Metal Components	14-20
Creating Cuts in Sheet Metal Components	14-25
Creating Seams at the Corners of Sheet Metal Components	14-27
Bending the Faces of a Sheet Metal Component	14-30

Rounding the Corners of Sheet Metal Components	14-33
Chamfering the Corners of Sheet Metal Components	14-34
Punching 3D Shapes into Sheet Metal Components	14-35
Creating Hems	14-38
Creating Contour Flanges	14-40
Creating the Flat Patterns of Sheet Metal Components	14-42
Adding or Removing Material from the Flat Pattern	14-43
Tutorial 1	14-43
Tutorial 2	14-51
Self-Evaluation Test	14-57
Review Questions	14-58
Exercise 1	14-59

Chapter 15: Introduction to Stress Analysis

Introduction to FEA	15-2
Types of Engineering Analysis	15-3
Structural Analysis	15-3
Thermal Analysis	15-4
Fluid Flow Analysis	15-5
Electromagnetic Field Analysis	15-5
Coupled Field Analysis	15-5
General Procedure to Conduct Finite Element Analysis	15-5
FEA through Software	15-6
Important Terms and Definitions	15-7
Stress Analysis Using Autodesk Inventor Professional 2017	15-10
Creating Study Enhanced	15-10
Using the Guide Tool	15-13
Applying Stress Analysis Settings	15-13
Study Browser Bar	15-14
Assigning Material	15-14
Assign Material	15-15
Applying Constraints	15-17
Fixed	15-17
Pin	15-18
Frictionless	15-18
Applying Loads	15-19
Force	15-19
Pressure	15-21
Bearing Load	15-21
Moment	15-22
Gravity	15-22
Remote Force	15-23
Body	15-24
Meshing the Component	15-24
Mesh View	15-24
Mesh Settings	15-25
Local Mesh Control	15-26
Convergence Settings	15-27

Solution Phase of Analysis	15-27
Postprocessing the Solutions	15-28
Generating Report	15-28
Animating the Results	15-29
Material Optimization using Shape Generator New	15-30
Tutorial 1	15-35
Tutorial 2	15-40
Tutorial 3	15-45
Self-Evaluation Test	15-53
Review Questions	15-53
Exercise 1	15-54
Exercise 2	15-55

CHAPTERS AVAILABLE FOR FREE DOWNLOAD

In this textbook, four chapters have been given for free download. You can download these chapters from our website www.cadcim.com. To download these chapters, follow the path: *Textbooks > CAD/CAM > Inventor > Autodesk Inventor Professional 2017 for Designers > Chapters for Free Download* and then select the chapter name from the **Chapters for Free Download** drop-down. Click the **Download** button to download the chapter in the PDF format.

Chapter 16: Introduction to Weldments

Understanding Weldment Assemblies	16-2
Main Types of Welds in Autodesk Inventor	16-3
Cosmetic Welds	16-3
Fillet Welds	16-4
Groove Welds	16-4
Adding Welds to Assemblies	16-5
Assembling the Components of Weldment Assemblies	16-5
Preparing Assemblies for Weldments	16-5
Adding Welds	16-6
Creating Fillet Welds	16-6
Creating Cosmetic Welds	16-8
Creating Groove Welds	16-9
Creating Symbols	16-11
Generating Report	16-12
Tutorial 1	16-12
Tutorial 2	16-17
Self-Evaluation Test	16-21
Review Questions	16-22
Exercise 1	16-22

Chapter 17: Miscellaneous Tools

Introduction	17-2
Copying the Sketches	17-2
Scaling the Sketches	17-3
Finding the Center of Gravity	17-3

Extracting the iFeature	17-4
Inserting the iFeature	17-6
Creating iMates	17-7
Applying iMates in the Assembly Environment	17-9
Interactively place with iMates	17-9
Automatically generate iMates on place	17-9
Viewing the iProperties	17-9
Creating User-Defined Drawing Sheets	17-11
Importing AutoCAD Blocks into Inventor	17-18
Tutorial 1	17-21
Tutorial 2	17-26
Self-Evaluation Test	17-30
Review Questions	17-31
Exercise 1	17-32

Chapter 18: Working with Special Design Tools

Adaptive Parts	18-2
Defining Parameters	18-2
Working with iParts	18-7
Types of iPart Factories	18-7
Creating iPart Factories	18-7
Procedure to Create Standard iPart	18-13
Procedure to Create Custom iPart	18-14
Inserting an iPart into an Assembly	18-14
Changing the iParts in the Assembly File	18-17
Creating 3D Sketches	18-17
Line	18-18
Spline	18-18
Bend	18-19
Include Geometry	18-19
Intersection Curve	18-19
Helical Curve	18-20
Tutorial 1	18-20
Tutorial 2	18-25
Tutorial 3	18-31
Tutorial 4	18-35
Tutorial 5	18-38
Self-Evaluation Test	18-46
Review Questions	18-47
Exercise 1	18-48

Chapter 19: Introduction to Plastic Mold Design

Introduction to Plastic Mold Design	19-2
Invoking the Mold Environment	19-2
Methods of Designing Core and Cavity	19-2
Importing Plastic Part in Mold Environment	19-3

Adding Core and Cavity by using Individual Models	19-4
Adjusting Orientation and Position of the Part	19-5
Adjusting Orientation of a Part	19-5
Adjusting Position of the Part	19-6
Selecting Material	19-8
Commonly used material	19-8
Specific Material	19-8
Details	19-9
Report	19-10
Creating Core and Cavity for the Part	19-11
Adjusting Orientation	19-11
Specifying Gate Location	19-11
Analyzing Part for Filling	19-16
Specifying Shrinkage Allowance	19-17
Defining Workpiece	19-19
Creating Patching Surface	19-21
Creating Planar Patches	19-22
Creating Runoff Surface	19-22
Generating Core and Cavity	19-23
Creating Pattern of the Mold	19-26
Creating a Rectangular Pattern	19-26
Creating a Circular Pattern	19-26
Creating a Variable Pattern	19-27
Creating Runner of the Mold	19-28
Creating Runner Sketch	19-28
Creating Runner	19-30
Creating Gates for the Molds	19-31
Type	19-32
Placement	19-32
Copy of all Pockets	19-33
Adding Cold Wells	19-33
Adding Mold Base to the Assembly	19-33
Standard Area	19-34
Placement Area	19-35
Layout Information Area	19-35
Adding Sprue Bushing	19-36
Adding Cooling Channel	19-37
Generating Drawing Views	19-38
Tutorial 1	19-39
Self-Evaluation Test	19-60
Review Questions	19-60
Exercise 1	19-60

This page is intentionally left blank