

Table of Contents

Dedication	iii
Preface	xv
Introduction	xvii

Chapter 1: Drawing Sketches for Solid Models

The Sketcher Task Environment	1-2
Starting NX 3	1-3
Starting a New Document in NX 3	1-4
Starting the Modeling Environment for Creating Models	1-5
Invoking the Sketcher Task Environment	1-7
The Drawing Display Tools	1-10
Fitting all Entities in the Current Display	1-10
Zooming to an Area	1-10
Dynamic Zooming	1-10
Panning Drawings	1-10
Fitting View to Selection	1-11
Restoring the Original Orientation of the Sketching Plane	1-11
Setting Selection Filters in the Sketching Environment	1-11
Selecting Sketch Objects	1-11
Selecting General Objects	1-11
Selecting Constraints	1-11
Selecting Objects	1-12
Deselecting Objects	1-12
Sketching Tools	1-12
Drawing Sketches Using the Profile Tool	1-12
Drawing Individual Lines	1-16
Drawing Arcs	1-16
Drawing Circles	1-18
Drawing Rectangles	1-19
Placing Points	1-21
Drawing Ellipses or Elliptical Arcs	1-23
Drawing General Conics	1-24
Drawing Studio Splines	1-24
Filleting Sketched Entities	1-27
Using Snap Points While Sketching	1-28
Deleting the Sketched Entities	1-29
Exiting the Sketcher Task Environment	1-29
Tutorial 1	1-29
Tutorial 2	1-36
Tutorial 3	1-40

Self-Evaluation Test	1-45
Review Questions	1-45
Exercise 1	1-46
Exercise 2	1-47
Exercise 3	1-47

Chapter 2: Adding Constraints and Dimensions to Sketches

Geometric Constraints	2-2
Applying Additional Constraints Individually	2-2
Applying Automatic Constraints to the Sketch	2-6
Controlling Infer Constraints Settings	2-8
Showing All Constraints in the Sketch	2-8
Turning Off the Display of All Constraints in the Sketch	2-9
Showing/Removing Constraints	2-9
Converting a Sketch Entity to a Reference Entity	2-11
Animating a Fully Constrained Sketch	2-12
Dimensioning Sketched Objects	2-13
Applying Horizontal Dimensions	2-13
Editing the Dimension Value and Other Parameters	2-14
Applying Vertical Dimensions	2-14
Applying Parallel Dimensions	2-15
Applying Perpendicular Dimensions	2-16
Applying Angular Dimensions	2-16
Applying Diameter Dimensions	2-17
Applying Radius Dimensions	2-18
Applying Perimeter Dimensions	2-18
Applying Dimensions Using the Inferred Dimensions Tool	2-19
Measuring the Distance value between the Objects in a Sketch	2-19
Measuring the Distance Between Two Objects in a Sketch	2-20
Measuring the Projected Distance Between Two Objects	2-20
Measuring the Screen Distance Between Two Objects	2-21
Measuring the Length of an Arc or a Line	2-22
Measuring the Angle Between the Entities	2-22
Measuring the Angle Value Using the By 3 Points Tool	2-22
Measuring the Angle Value Using the By Objects Tool	2-23
Measuring the Angle Value Using the By Screen Points Tool	2-23
Tutorial 1	2-24
Tutorial 2	2-30
Tutorial 3	2-34
Self-Evaluation Test	2-37
Review Questions	2-38
Exercise 1	2-39
Exercise 2	2-40

Chapter 3: Editing, Extruding, and Revolving Sketches

Editing Sketches	3-2
Trimming Sketched Entities	3-2
Extending Sketched Entities	3-3
Mirroring Sketched Entities Using the Mirror Tool	3-4
Transforming Sketched Entities	3-5
Editing Sketched Entities by Dragging	3-10
Writing Text in the Sketching Environment	3-10
Exiting the Sketching Environment	3-11
Changing the View of the Sketch	3-12
Creating Solid Base Features by Extruding	3-12
Creating Thin Base Features by Extruding	3-17
Creating Solid Revolved Bodies	3-19
Creating Thin Revolved Bodies	3-23
Hiding Entities	3-23
Rotating the View of a Model in 3D Space	3-25
Setting Display Modes	3-25
Tutorial 1	3-26
Tutorial 2	3-31
Tutorial 3	3-35
Self-Evaluation Test	3-38
Review Questions	3-38
Exercise 1	3-39
Exercise 2	3-40

Chapter 4: Working with Fixed and Relative Datum Planes, Coordinate Systems, and Datum Axes

Additional Sketching and Reference Planes	4-2
Types of Datum Planes	4-3
Creating the Fixed (Principle) Datum Planes	4-3
Creating Relative Datum Planes	4-4
Creating Associative Datum Coordinate Systems	4-13
Creating Fixed and Relative Datum Axes	4-17
Other Extrusion Options	4-21
Specifying the Boolean Operation	4-21
Specifying Other Extrusion Termination Options	4-22
Other Revolution Options	4-25
Revolving Sketches Using the Trim to Face Method	4-25
Revolving Sketches Using the Trim Between Two Faces Method	4-26
Projecting External Elements	4-28
Tutorial 1	4-30
Tutorial 2	4-35
Tutorial 3	4-41
Self-Evaluation Test	4-45

Review Questions	4-46
Exercise 1	4-47
Exercise 2	4-48

Chapter 5: Advanced Modeling Tools-I

Advanced Modeling Tools	5-2
Creating Holes	5-2
Creating Simple Holes	5-2
Creating Counterbore Holes	5-4
Creating Countersink Holes	5-6
Creating Grooves	5-7
Creating Rectangular Grooves	5-8
Creating Ball End Grooves	5-10
Creating U Grooves	5-11
Creating Slots	5-13
Creating Rectangular Slots	5-13
Creating Ball-End Slots	5-15
Creating U Slots	5-17
Creating T Slots	5-19
Creating Dove-Tail Slots	5-21
Creating Edge Chamfers	5-23
Creating an Edge Chamfer Feature Using the Single Offset Option	5-24
Creating an Edge Chamfer Feature Using the Double Offset Option	5-25
Creating an Edge Chamfer Feature Using the Offset Angle Option	5-26
Creating an Edge Blend	5-27
Creating a Constant Radius Edge Blend	5-27
Creating a Variable Radius Edge Blend	5-28
Creating an Edge Blend Using the Stop Short Tool	5-29
Creating a Corner Blend Using the Setback Tool	5-30
Tutorial 1	5-31
Tutorial 2	5-40
Self-Evaluation Test	5-49
Review Questions	5-50
Exercise 1	5-51
Exercise 2	5-51
Exercise 3	5-53

Chapter 6: Advanced Modeling Tools-II

Advanced Modeling Tools	6-2
Working with the Instance Feature Tool	6-2
Creating Rectangular Arrays Using the Instance Feature Tool	6-2
Creating Circular Arrays Using the Instance Feature Tool	6-5
Mirroring Selected Features Using the Instance Feature Tool	6-7
Mirroring Bodies Using the Instance Feature Tool	6-8
Using the Pattern Face Option of the Instance Feature Tool	6-9

Sweeping Sketches Along Guide Curves	6-10
Creating Swept Features	6-11
Other Swept Options	6-14
Creating Tubes or Cables	6-14
Creating Threads	6-16
Creating Symbolic Threads	6-17
Creating Detailed Threads	6-19
Creating Hollow Features	6-20
Creating Hollow Models Using the Face Method	6-22
Creating Hollow Models Using Regions	6-23
Hollowing the Entire Body	6-25
Tutorial 1	6-26
Tutorial 2	6-30
Tutorial 3	6-34
Self-Evaluation Test	6-37
Review Questions	6-38
Exercise 1	6-39
Exercise 2	6-40
Exercise 3	6-41

Chapter 7: Editing Features and Advanced Modeling Tools-III

Editing Features	7-2
Editing a Hole Feature	7-2
Editing the Positioning of a Hole Feature	7-3
Editing the Positioning of a Groove Feature	7-4
Editing the Positioning of a Slot Feature	7-5
Editing the Parameters of Features	7-5
Editing the Parameters of Features with the Rollback	7-5
Editing Sketches of the Sketch-based Features	7-5
Reordering Features	7-5
Advanced Modeling Tools	7-6
Creating Boss Features	7-6
Creating Pocket Features	7-7
Creating Pad Features	7-12
Creating Tapers	7-15
Tutorial 1	7-19
Tutorial 2	7-24
Tutorial 3	7-33
Self-Evaluation Test	7-43
Review Questions	7-44
Exercise 1	7-45
Exercise 2	7-46

Chapter 8: Assembly Modeling-I

The Assembly Application	8-2
Starting a New File in the Assembly Application of NX	8-2
Types of Assembly Design Approaches	8-3
Creating Bottom-up Assemblies	8-4
Placing Components in the Assembly	8-4
Changing the Reference Set of the Component	8-6
Applying Assembly Constraints to Components	8-6
Using the Options in the Mating Conditions Dialog Box	8-14
Points to Remember while Assembling Components	8-14
Creating a Component Array in an Assembly	8-15
Replacing a Component in an Assembly	8-16
Repositioning a Component in an Assembly	8-18
Mirroring a Component in an Assembly	8-21
Modifying a Component in the Assembly File	8-23
Tutorial 1	8-24
Tutorial 2	8-38
Self-Evaluation Test	8-54
Review Questions	8-54
Exercise 1	8-55

Chapter 9: Assembly Modeling-II

The Top-down Assembly Design Approach	9-2
Creating Components Using the Top-down Assembly Design Approach	9-2
Creating Subassemblies	9-4
Editing Assembly Constraints	9-4
Modifying Angle and Distance Values	9-5
Replacing Assembly Constraints	9-6
Checking for Interference between the Components in an Assembly	9-7
Interference and Clearance Check Using the Check Clearance Analysis	9-7
Interference Check Using the Assembly Clearance Method	9-9
Creating Exploded Views of an Assembly	9-15
Automatic Explosion Views	9-15
Manual Explosion Views	9-18
Tutorial 1	9-20
Tutorial 2	9-24
Tutorial 3	9-28
Tutorial 4	9-35
Self-Evaluation Test	9-46
Review Questions	9-47
Exercise 1	9-47

Chapter 10: Generating, Editing, and Dimensioning the Drawing Views

The Drafting Application	10-2
Editing the Drawing Sheet Parameters in the Drawing Environment	10-4
Invoking the Drafting Tools	10-4
Types of Drawing Views in NX	10-4
Base View	10-4
View from Part	10-4
Projected View	10-4
Detail View	10-5
Section View	10-5
Auxiliary View	10-5
Half Section View	10-5
Revolved Section	10-5
Align View	10-5
Break-Out Section	10-5
Broken View	10-5
Generating Drawing Views	10-6
Generating the Base View	10-6
Generating the Drawing View using the Add View from Part Tool	10-7
Generating the Orthographic Drawing Views using the Add Projected View Tool	10-7
Generating the Detail View using the Add Detail View Tool	10-8
Generating Section Views using the Add Section View Tool	10-11
Generating the Half Section View using the Add Half Section View Tool	10-14
Adding the Revolved Section View	10-15
Generating the Break-Out Section for a Drawing View	10-16
Generating the Broken View	10-17
Manipulating the Drawing Views	10-19
Aligning the Drawing Views using the Align View Tool	10-19
View Boundary	10-21
Displaying the Model using the Display Sheet Tool	10-22
Inserting a Drawing Sheet using the Insert Sheet Tool	10-23
Modifying the Properties of the Generated Drawing View	10-23
Modifying the Scale Value of the Drawing View	10-23
Displaying the Symbolic Thread Feature	10-24
Adding Dimensions to the Drawing views	10-25
Retrieving Dimensions from the Model	10-25
Adding Dimensions to the Drawing View	10-26
Generating Exploded Views of the Assembly	10-29
Creating the Parts List and Associative Balloons	10-29
Creating a Parts List for an Assembly	10-29
Creating Associative Balloons	10-30
Creating a Tabular Note (Title Block)	10-31
Adding Text to the Drawing Sheet	10-32
Editing the Multiline Text	10-33

Tutorial 1	10-34
Tutorial 2	10-39
Tutorial 3	10-44
Self-Evaluation Test	10-51
Review Questions	10-52
Exercise 1	10-53
Exercise 2	10-53

Chapter 11: Surface Modeling

Introduction to the Surface Modeling	11-2
Invoking the Sheet Modeling Environment in the Modeling Application	11-2
Creating an Extruded Surface	11-2
Creating a Revolved Surface	11-3
Creating a Ruled Surface	11-3
Creating a Surface Using the Through Curve Mesh Tool	11-7
Creating a Surface by 4 Points	11-9
Creating a Swoop Surface	11-9
Creating the Planar Surfaces from 2D Sketches and Solid Edges	11-10
Creating a Transition Surface Using the Transition Tool	11-12
Creating an N-Sided Surface	11-13
Creating a Silhouette Flange Surface	11-14
Extending a Surface Using the Law Extension Tool	11-17
Creating a Surface Offset Using the Offset Surface Tool	11-19
Trimming and Extending a Surface using the Trim and Extend Tool	11-20
Trimming a Sheet by using the Trimmed Sheet Tool	11-21
Creating a Surface Using the Studio Surface Tools	11-23
Creating a Surface Between Two Walls Using the Styled Blend Tool	11-28
Creating Surfaces Using the Styled Sweep Tool	11-31
Sewing Individual Surfaces Into a Single Surface	11-33
Adding Thickness to a Surface	11-33
Tutorial 1	11-34
Tutorial 2	11-41
Self-Evaluation Test	11-49
Review Questions	11-50
Exercise 1	11-51
Exercise 2	11-51

Chapter 12: Advanced Surface Modeling

Creating Curves from Bodies	12-2
Creating Intersection Curves	12-2
Creating Section Curves	12-3
Creating Extract Curves	12-8
Advanced Surface Modeling Tools	12-11
Creating Dart Features	12-11
Creating Emboss Sheet Features	12-13

Table of Contents

ix

Creating Face Blend Features	12-14
Creating Soft Blend Features	12-17
Creating Fillet Features	12-19
Creating Bridge Features	12-24
Tutorial 1	12-28
Tutorial 2	12-39
Self-Evaluation Test	12-46
Review Questions	12-47
Exercise 1	12-48
Exercise 2	12-49
Student Projects	1
Index	1

Evaluation Chapter. Do not copy. Visit www.cadclm.com for details