

# Table of Contents

<b>Dedication</b>	iii
<b>Preface</b>	xiii
<b>Introduction</b>	xvii

## Chapter 1: Creating Sketches in the Sketch Mode-I

The Sketch Mode	1-2
Using the Sketch Mode	1-2
Invoking the Sketch Mode	1-3
The Sketcher Environment	1-3
Working With the Sketch in the Sketch Mode	1-4
Drawing a Sketch Using the Sketcher Tools Toolbar	1-5
Placing a Point	1-5
Drawing a Line	1-5
Drawing a Rectangle	1-7
Drawing a Circle	1-7
Drawing an Arc	1-10
Dimensioning the Sketch	1-13
Dimensioning a Sketch Using the Create defining dimension Button or the Normal option	1-13
Dimensioning the Basic Sketched Entities	1-13
Linear Dimensioning of a Line	1-14
Angular Dimensioning of an Arc	1-14
Diameter Dimensioning	1-14
Radial Dimensioning	1-15
Dimensioning Revolved Sections	1-15
Working With Constraints	1-16
Explain Option	1-17
Disabling Constraints	1-17
Converting a Weak Constraint into a Strong Constraint	1-17
Modifying Dimensions of a Sketch	1-18
Using the Modify the values of dimensions, geometry of splines, or text entities Tool	1-18
Using the Edit Menu	1-19
Modifying Dimensions by Double-Clicking	1-19
Modifying Dimensions Dynamically	1-19
Resolve Sketch Dialog Box	1-19
Deleting the Sketched Entities	1-20
Trimming the Sketched Entities	1-21
Mirroring the Sketched Entities	1-22
Inserting Foreign Data into the Sketch	1-22
Drawing Display Options	1-24

Tutorial 1	1-25
Tutorial 2	1-31
Tutorial 3	1-35
Self-Evaluation Test	1-40
Review Questions	1-40
Exercise 1	1-41
Exercise 2	1-42
Exercise 3	1-42
Exercise 4	1-43
Exercise 5	1-43

## Chapter 2: Creating Sketches in the Sketch Mode-II

Dimensioning the Sketch	2-2
Dimensioning a Sketch using the Baseline Option	2-2
Replacing the Dimensions of a Sketch using the Replace Option	2-3
Creating Fillets	2-3
Creating Circular Fillets	2-3
Creating Elliptical Fillets	2-6
Creating a Reference Coordinate System	2-7
Working With Splines	2-7
Creating a Spline	2-7
Dimensioning Splines	2-8
Modifying a Spline	2-9
Writing Text in the Sketcher Environment	2-11
Scaling and Rotating Entities	2-12
Importing 2D Drawings in the Sketch Mode	2-13
Tutorial 1	2-14
Tutorial 2	2-19
Tutorial 3	2-24
Self-Evaluation Test	2-28
Review Questions	2-29
Exercise 1	2-30
Exercise 2	2-30
Exercise 3	2-31
Exercise 4	2-31

## Chapter 3: Creating Base Features

Creating Base Features	3-2
Invoking the Part Mode	3-2
The Default Datum Planes	3-3
Creating a Protrusion	3-5
Extruding a Sketch	3-5
Revolving a Sketch	3-15
Understanding the Orientation of Datum Planes	3-16
Parent-Child Relationship	3-22

Implicit Relationship	3-22
Explicit Relationship	3-22
Nesting of Sketches	3-23
Tutorial 1	3-24
Tutorial 2	3-31
Tutorial 3	3-37
Tutorial 4	3-42
Self-Evaluation Test	3-52
Review Questions	3-52
Exercise 1	3-53
Exercise 2	3-54
Exercise 3	3-54
Exercise 4	3-55

## Chapter 4: Datums

Datums	4-2
Default Datum Planes	4-2
Need for Datums in Modeling	4-2
Selection Method in Pro/ENGINEER Wildfire 3.0	4-3
Datum Options	4-5
Datum Planes	4-5
Creating Datum Planes	4-8
Embedded Datum Planes	4-14
Datum Axes	4-15
Datum Points	4-21
Creating Cuts	4-28
Removing Material by Extruding a Sketch	4-28
Removing Material by Revolving a Sketch	4-29
Tutorial 1	4-30
Tutorial 2	4-40
Tutorial 3	4-48
Self-Evaluation Test	4-54
Review Questions	4-55
Exercise 1	4-56
Exercise 2	4-56
Exercise 3	4-57
Exercise 4	4-59

## Chapter 5: Options Aiding Construction of Parts-I

Options Aiding Construction of Parts	5-2
Creating Holes	5-2
The Hole Dashboard	5-2
Important Points to Remember While Creating a Hole	5-10
Creating Rounds	5-11
Creating Basic Rounds	5-11

Creating a Variable Radius Round	5-19
Points to Remember While Creating Rounds	5-20
Creating Chamfers	5-21
Corner Chamfer	5-21
Edge Chamfer	5-22
Understanding Ribs	5-27
Creating Ribs	5-27
Editing Features of a Model	5-29
Editing Definition or Redefining Features	5-29
Reordering Features	5-30
Rerouting Features	5-31
Suppressing Features	5-32
Deleting a Feature	5-33
Modifying a Feature	5-33
Tutorial 1	5-34
Tutorial 2	5-44
Tutorial 3	5-49
Tutorial 4	5-54
Self-Evaluation Test	5-62
Review Questions	5-63
Exercise 1	5-64
Exercise 2	5-65
Exercise 3	5-65

## Chapter 6: Options Aiding Construction of Parts-II

Creating Feature Patterns	6-2
Uses of Patterns	6-2
Creating Patterns	6-2
Deleting a Pattern	6-15
Copying Features	6-15
Mirror	6-16
Move	6-17
Mirroring a Geometry	6-18
Creating a Section of the Solid Model	6-19
Work Region Method	6-19
Tutorial 1	6-21
Tutorial 2	6-27
Tutorial 3	6-38
Tutorial 4	6-44
Self-Evaluation Test	6-60
Review Questions	6-60
Exercise 1	6-61
Exercise 2	6-63
Exercise 3	6-63
Exercise 4	6-64

## Chapter 7: Advanced Modeling Tools-I

Other Protrusion Options	7-2
Sweep Features	7-2
Creating Swept Protrusions	7-2
Sketching a Trajectory Aligned to an Existing Geometry	7-4
Creating a Sweep Feature by Selecting a Trajectory	7-5
Creating a Thin Sweep Protrusion	7-7
Creating a Sweep Cut	7-7
Blend Features	7-8
Parallel Blend	7-8
Rotational Blend	7-10
General Blend	7-12
Using the Blend Vertex	7-12
Shell Option	7-12
Creating a Constant Thickness Shell	7-14
Creating a Variable Thickness Shell	7-14
Datum Curves	7-16
Creating a Datum Curve Using the Insert a datum curve Button	7-16
Creating a Datum Curve by Sketching	7-19
Intersect Option	7-19
Project Option	7-20
Wrap Option	7-23
Creating Draft Features	7-24
Tutorial 1	7-34
Tutorial 2	7-42
Tutorial 3	7-48
Tutorial 4	7-54
Self-Evaluation Test	7-59
Review Questions	7-59
Exercise 1	7-60
Exercise 2	7-61
Exercise 3	7-62
Exercise 4	7-64

## Chapter 8: Advanced Modeling Tools-II

Advanced Feature Creation Tools	8-2
Variable Section Sweep Option	8-2
Swept Blend	8-6
Helical Sweep	8-9
Blend Section to Surfaces	8-12
Blend Between Surfaces	8-12
Tutorial 1	8-13
Tutorial 2	8-19
Tutorial 3	8-30
Tutorial 4	8-37

Self-Evaluation Test	8-39
Review Questions	8-40
Exercise 1	8-41
Exercise 2	8-41

### Chapter 9: Advanced Modeling Tools-III

Advanced Modeling Tools	9-2
Toroidal Bend	9-2
Spinal Bend	9-3
Warp Tool	9-5
Using the Start the transform tool	9-7
Using the Start the warp tool	9-9
Using the Start the spine tool	9-11
Using the Start the stretch tool	9-12
Using the Start the bend tool	9-13
Using the Start the twist tool	9-15
Using the Start the sculpt tool	9-16
Tutorial 1	9-18
Tutorial 2	9-23
Tutorial 3	9-27
Self-Evaluation Test	9-33
Review Questions	9-34
Exercise 1	9-35
Exercise 2	9-35

### Chapter 10: Assembly Modeling

Assembly Modeling	10-2
Important Terms Related to the Assembly Mode	10-2
Top-down Approach	10-2
Bottom-up Approach	10-3
Creating Top-down Assemblies	10-4
Creating Components in the Assembly Mode	10-4
Creating Bottom-up Assemblies	10-5
Inserting Components in the Assembly	10-5
Placement Constraints	10-5
Automatic	10-5
Mate	10-6
Align	10-7
Insert	10-9
Coord Sys	10-9
Tangent	10-10
Pnt On Line	10-10
Pnt On Srf	10-10
Edge On Srf	10-10
Fix	10-10

Default	10-10
Assembly Datum Planes	10-10
Assembling the Components	10-11
Packaging the Components	10-14
Creating Simplified Representations	10-16
Redefining the Components of the Assembly	10-20
Reordering the Components	10-20
Suppressing/Resuming the Components	10-21
Replacing Components	10-21
Assembling Repeated Copies of a Component	10-22
Modifying the Components of the Assembly	10-23
Modifying the Dimensions of a Feature of a Component	10-24
Redefining a Feature of a Component	10-24
Creating the Exploded State	10-24
Offset Lines	10-27
Creating the Offset Lines	10-27
Modifying the Offset Lines	10-28
The Bill Of Material	10-29
Tutorial 1	10-30
Tutorial 2	10-44
Self-Evaluation Test	10-53
Review Questions	10-54
Exercise 1	10-55

## **Chapter 11: Generating, Editing, and Modifying the Drawing Views**

The Drawing Mode	11-2
Generating Drawing Views	11-4
Generating the General View	11-5
Generating the Projection View	11-6
Generating the Detailed View	11-7
Generating the Auxiliary View	11-7
Generating the Revolved Section View	11-8
Generating the Copy and Align View	11-19
3D Cross-section	11-20
Editing the Drawing Views	11-23
Moving the Drawing View	11-23
Erasing the Drawing View	11-23
Deleting the Drawing View	11-23
Adding New Parts or Assemblies to the Current Drawing	11-24
Modifying the Drawing Views	11-24
Changing the View Type	11-24
Changing the View Scale	11-24
Reorienting the Views	11-25
Modifying the Cross-sections	11-25
Modifying the Boundaries of Views	11-25
Adding or Removing the Cross-section Arrows	11-26

Modifying the Perspective Views	11-26
Modifying Other Parameters	11-26
Editing the Cross-section Hatching	11-26
Tutorial 1	11-27
Tutorial 2	11-36
Self-Evaluation Test	11-42
Review Questions	11-43
Exercise 1	11-44

## Chapter 12: Dimensioning the Drawing Views

Dimensioning the Drawing Views	12-2
Show / Erase Dialog box Options	12-2
Modifying and Editing Dimensions	12-6
Modifying the Dimensions Using the Dimension Properties Dialog Box	12-7
Modifying the Drawing Items Using the Shortcut Menu	12-11
Cleaning Up the Dimensions	12-12
Adding Reference Datums to the Drawing Views	12-14
Adding Tolerances in the Drawing Views	12-16
Dimensional Tolerances	12-17
Geometric Tolerances	12-17
Editing the Geometric Tolerances	12-21
Adding Notes to the Drawing	12-21
Adding Balloons to the Assembly Views	12-22
Tutorial 1	12-22
Tutorial 2	12-29
Self-Evaluation Test	12-34
Review Questions	12-34
Exercise 1	12-36

## Chapter 13: Other Drawing Options

Sketching in the Drawing Mode	13-2
Modifying the Sketched Entities	13-3
User-Defined Drawing Formats	13-8
Retrieving the User-Defined Formats in the Drawings	13-9
Adding and Removing Sheets in the Drawing	13-10
Creating Tables in the Drawing Mode	13-11
Generating the BOM and Balloons in Drawings	13-12
Tutorial 1	13-15
Tutorial 2	13-26
Self-Evaluation Test	13-36
Review Questions	13-36
Exercise 1	13-37



## Chapter 14: Surface Modeling

Surface Modeling	14-2
Creating Surfaces in Pro/ENGINEER Wildfire 3.0	14-2
Creating an Extruded Surface	14-2
Creating a Revolved Surface	14-3
Creating a Sweep Surface	14-4
Creating a Blended Surface	14-4
Creating a Swept Blend Surface	14-5
Creating a Helical Sweep Surface	14-5
Creating a Surface by Blending the Boundaries	14-5
Creating a Surface Using the Variable Section Sweep	14-8
Creating Surfaces Using the Style Environment of Pro/ENGINEER Wildfire 3.0	14-9
Style Tools Toolbar	14-9
Surface Editing Tools	14-16
Mirroring Surfaces	14-16
Merging Surfaces	14-17
Trimming Surfaces	14-19
Creating the Fill Surfaces	14-19
Creating the Intersect Curves	14-20
Creating the Offset Surfaces	14-21
Giving Thickness to a Surface	14-23
Converting a Surface to a Solid	14-24
Creating a Round at the Vertex of a Surface	14-24
Tutorial 1	14-25
Tutorial 2	14-35
Self-Evaluation Test	14-43
Review Questions	14-44
Exercise 1	14-45
Exercise 2	14-46

## Chapter 15: Working with Sheetmetal Components

Introduction to Pro/Sheetmetal	15-2
Invoking the Sheetmetal Mode	15-2
Introduction to Sheetmetal Walls	15-3
Creating the Unattached Flat Wall	15-4
Creating the Unattached Revolve Wall	15-5
Creating the Unattached Blend Wall	15-5
Creating the Unattached Offset Wall	15-9
Creating Reliefs in Sheetmetal Components	15-10
Creating a Flat Wall	15-12
Creating a Twist Wall	15-15
Creating the Extend Wall	15-16
Creating the Flange Wall	15-18
Creating the Bend	15-21
Regular Bend	15-23

w/Transition Bend	15-24
Planar Bend	15-26
Creating the Unbend	15-27
Creating the Bend Back	15-28
Creating the Conversion	15-29
Creating Cuts in the Sheetmetal Components	15-32
Creating the Flat Pattern	15-32
Tutorial 1	15-33
Tutorial 2	15-42
Self-Evaluation Test	15-49
Review Questions	15-50
Exercise 1	15-50

<b>Index</b>	I-1
--------------	-----