

Table of Contents

Dedication	iii
Preface	xv

Chapter 1: Introduction to Pro/Engineer Wildfire 4.0

Introduction to Pro/Engineer Wildfire 4.0	1-2
Feature-Based Nature	1-2
Bidirectional Associative Property	1-3
Parametric Nature	1-6
System Requirements	1-6
Getting Started with Pro/Engineer Wildfire 4.0	1-7
Important Terms and Definitions	1-8
File Menu Options	1-9
Managing Files	1-20
Menu Manager	1-21
Model Tree	1-22
Understanding the Functions of the Mouse Buttons	1-22
Toolbars	1-24
Navigator	1-28
Browser	1-29

Chapter 2: Creating Sketches in the Sketch Mode-I

The Sketch Mode	2-2
Using the Sketch Mode	2-2
Invoking the Sketch Mode	2-3
The Sketcher Environment	2-3
Working with the Sketch in the Sketch Mode	2-4
Drawing a Sketch Using the Sketcher Tools Toolbar	2-5
Placing a Point	2-5
Drawing a Line	2-5
Drawing a Rectangle	2-7
Drawing a Circle	2-7
Drawing an Arc	2-10
Dimensioning the Sketch	2-12
Converting a Weak Dimension into a Strong Dimension	2-13
Dimensioning a Sketch Using the Normal Button or the Normal Option	2-13
Dimensioning the Basic Sketched Entities	2-14
Linear Dimensioning of a Line	2-14
Angular Dimensioning of an Arc	2-14
Diameter Dimensioning	2-14
Radial Dimensioning	2-15
Dimensioning Revolved Sections	2-15

Working With Constraints	2-16
Explain Option	2-17
Disabling Constraints	2-17
Modifying the Dimensions of a Sketch	2-17
Using the Modify Button	2-18
Using the Edit Menu	2-18
Modifying Dimensions by Double-Clicking	2-19
Modifying Dimensions Dynamically	2-19
Resolve Sketch Dialog Box	2-19
Deleting the Sketcher Entities	2-20
Trimming the Sketcher Entities	2-20
Mirroring the Sketcher Entities	2-21
Palette Button	2-22
Drawing Display Options	2-23
Tutorial 1	2-24
Tutorial 2	2-30
Tutorial 3	2-35
Self-Evaluation Test	2-39
Review Questions	2-40
Exercise 1	2-40
Exercise 2	2-41
Exercise 3	2-41

Chapter 3: Creating Sketches in the Sketch Mode-II

Dimensioning the Sketch	3-2
Dimensioning a Sketch Using the Baseline Option	3-2
Replacing the Dimensions of a Sketch Using the Replace Option	3-3
Creating Fillets	3-3
Creating Circular Fillets	3-3
Creating Elliptical Fillets	3-6
Creating a Reference Coordinate System	3-7
Working with Splines	3-7
Creating a Spline	3-7
Dimensioning of Splines	3-8
Modifying a Spline	3-9
Writing Text in the Sketcher Environment	3-11
Scaling and Rotating Entities	3-12
Importing 2D Drawings in the Sketch Mode	3-13
Tutorial 1	3-14
Tutorial 2	3-19
Tutorial 3	3-23
Self-Evaluation Test	3-27
Review Questions	3-28
Exercise 1	3-29
Exercise 2	3-29
Exercise 3	3-30

Chapter 4: Creating Base Features

Creating Base Features	4-2
Invoking the Part Mode	4-2
The Default Datum Planes	4-3
Creating a Protrusion	4-4
Extruding a Sketch	4-5
Revolving a Sketch	4-15
Understanding the Orientation of Datum Planes	4-16
Parent-Child Relationship	4-22
Implicit Relationship	4-22
Explicit Relationship	4-22
Nesting of Sketches	4-23
Tutorial 1	4-24
Tutorial 2	4-31
Tutorial 3	4-36
Tutorial 4	4-41
Self-Evaluation Test	4-51
Review Questions	4-51
Exercise 1	4-52
Exercise 2	4-53
Exercise 3	4-53
Exercise 4	4-54

Chapter 5: Datums

Datums	5-2
Default Datum Planes	5-2
Need for Datums in Modeling	5-2
Selection Method in Pro/ENGINEER Wildfire 4.0	5-3
Datum Options	5-5
Datum Planes	5-5
Creating Datum Planes	5-8
Datum Planes Created On-The-Fly	5-14
Datum Axes	5-15
Datum Points	5-20
Creating Cuts	5-27
Removing Material by Extruding a Sketch	5-27
Removing Material by Revolving a Sketch	5-28
Tutorial 1	5-29
Tutorial 2	5-39
Tutorial 3	5-47
Self-Evaluation Test	5-53
Review Questions	5-54
Exercise 1	5-55
Exercise 2	5-56
Exercise 3	5-56
Exercise 4	5-58

Chapter 6: Options Aiding Construction of Parts-I

Options Aiding Construction of Parts	6-2
Creating Holes	6-2
The Hole Dashboard	6-2
Important Points to Remember While Creating a Hole	6-13
Creating Rounds	6-14
Creating Basic Rounds	6-14
Creating a Variable Radius Round	6-22
Points to Remember While Creating Rounds	6-23
Creating Chamfers	6-23
Corner Chamfer	6-24
Edge Chamfer	6-25
Understanding Ribs	6-30
Creating Ribs	6-30
Editing Features of a Model	6-32
Editing Definition or Redefining Features	6-33
Reordering Features	6-33
Rerouting Features	6-35
Suppressing Features	6-35
Deleting a Feature	6-36
Modifying a Feature	6-36
Tutorial 1	6-37
Tutorial 2	6-47
Tutorial 3	6-52
Tutorial 4	6-58
Self-Evaluation Test	6-66
Review Questions	6-67
Exercise 1	6-68
Exercise 2	6-68
Exercise 3	6-69

Chapter 7: Options Aiding Construction of Parts-II

Creating Feature Patterns	7-2
Uses of Patterns	7-2
Creating Patterns	7-2
Deleting a Pattern	7-14
Copying Features	7-14
New Refs	7-15
Same Refs	7-15
Mirror	7-15
Move	7-16
Select	7-16
Mirroring a Geometry	7-17
Creating a Section of the Solid Model	7-18
Work Region Method	7-19

Tutorial 1	7-20
Tutorial 2	7-26
Tutorial 3	7-37
Tutorial 4	7-43
Self-Evaluation Test	7-58
Review Questions	7-59
Exercise 1	7-60
Exercise 2	7-61
Exercise 3	7-62
Exercise 4	7-63

Chapter 8: Advanced Modeling Tools-I

Other Protrusion Options	8-2
Sweep Features	8-2
Creating Sweep Protrusions	8-2
Sketching a Trajectory Aligned to an Existing Geometry	8-4
Creating Sweep Feature by Selecting a Trajectory	8-5
Creating Thin Sweep Protrusion	8-7
Creating a Sweep Cut	8-7
Blend Features	8-8
Parallel Blend	8-8
Rotational Blend	8-10
General Blend	8-12
Using Blend Vertex	8-12
Shell Option	8-13
Creating Constant Thickness Shell	8-14
Creating Variable Thickness Shell	8-14
Datum Curves	8-16
Creating Datum Curve Using the Curve Button	8-16
Creating Datum Curve by Sketching	8-19
Intersect Option	8-19
Project Option	8-20
Wrap Option	8-23
Creating Draft Features	8-25
Tutorial 1	8-34
Tutorial 2	8-42
Tutorial 3	8-48
Tutorial 4	8-54
Self-Evaluation Test	8-59
Review Questions	8-59
Exercise 1	8-60
Exercise 2	8-61
Exercise 3	8-62
Exercise 4	8-63

Chapter 9: Advanced Modeling Tools-II

Advanced Feature Creation Tools	9-2
Variable Section Sweep Option	9-2
Swept Blend	9-6
Helical Sweep	9-9
Blend Section To Surfaces	9-12
Blend Between Surfaces	9-12
Tutorial 1	9-13
Tutorial 2	9-19
Tutorial 3	9-30
Tutorial 4	9-36
Self-Evaluation Test	9-39
Review Questions	9-39
Exercise 1	9-40
Exercise 2	9-41

Chapter 10: Advanced Modeling Tools-III

Advanced Modeling Tools	10-2
Toroidal Bend	10-2
Spinal Bend	10-3
Warp	10-5
Transform Button	10-7
Warp Button	10-9
Spine Button	10-11
Stretch Button	10-12
Bend Button	10-13
Twist Button	10-14
Sculpt Button	10-15
Tutorial 1	10-18
Tutorial 2	10-23
Tutorial 3	10-27
Self-Evaluation Test	10-33
Review Questions	10-34
Exercise 1	10-34
Exercise 2	10-35

Chapter 11: Assembly Modeling

Assembly Modeling	11-2
Important Terms Related to the Assembly Mode	11-2
Top-down Approach	11-2
Bottom-up Approach	11-3
Placement Constraints	11-4
Package	11-4

Creating Top-down Assemblies	11-4
Creating Components in the Assembly Mode	11-4
Creating Bottom-up Assemblies	11-5
Inserting Components in the Assembly	11-5
Placement Constraints	11-5
Automatic	11-5
Mate	11-6
Align	11-7
Insert	11-9
Coord Sys	11-9
Tangent	11-9
Pnt On Line	11-10
Pnt On Srf	11-10
Edge On Srf	11-10
Fix	11-10
Default	11-10
Assembly Datum Planes	11-10
Assembling Components	11-10
Packaging Components	11-14
Creating Simplified Representations	11-16
Redefining Components of the Assembly	11-20
Reordering Components	11-20
Suppressing/Resuming Components	11-21
Replacing Components	11-21
Assembling Repeated Copies of a Component	11-22
Modifying Components of the Assembly	11-23
Modifying Dimensions of a Feature of a Component	11-23
Redefining a Feature of a Component	11-23
Creating the Exploded State	11-24
Offset Lines	11-26
Creating Offset Lines	11-26
Modifying Offset Lines	11-27
The Bill of Materials	11-28
Tutorial 1	11-29
Tutorial 2	11-43
Self-Evaluation Test	11-53
Review Questions	11-54
Exercise 1	11-55

Chapter 12: Generating, Editing, and Modifying the Drawing Views

The Drawing Mode	12-2
Generating Drawing Views	12-4
Generating the General View	12-4
Generating the Projection View	12-7
Generating the Detailed View	12-7
Generating the Auxiliary View	12-8

Generating the Revolved Section View	12-8
Generating the Copy and Align View	12-19
Generating the 3D Cross-Section View	12-20
Editing the Drawing Views	12-22
Moving the Drawing View	12-22
Erasing the Drawing View	12-23
Deleting the Drawing View	12-23
Adding New Parts or Assemblies to the Current Drawing	12-23
Modifying the Drawing Views	12-24
Changing the View Type	12-24
Changing the View Scale	12-25
Reorienting the Views	12-25
Modifying the Cross-sections	12-25
Modifying Boundaries of Views	12-25
Adding or Removing the Cross-section Arrows	12-25
Modifying the Perspective Views	12-25
Modifying Other Parameters	12-26
Editing the Cross-section Hatching	12-26
Tutorial 1	12-27
Tutorial 2	12-35
Self-Evaluation Test	12-41
Review Questions	12-42
Exercise 1	12-43

Chapter 13: Dimensioning the Drawing Views

Dimensioning the Drawing Views	13-2
Show / Erase Dialog Box	13-2
Modifying and Editing Dimensions	13-6
Modifying the Dimensions Using the Dimension Properties Dialog Box	13-7
Modifying the Drawing Items Using the Shortcut Menu	13-11
Cleaning Up the Dimensions	13-12
Adding Reference Datums to the Drawing Views	13-14
Adding Tolerances in the Drawing Views	13-15
Dimensional Tolerances	13-16
Geometric Tolerances	13-16
Editing the Geometric Tolerances	13-21
Adding Notes to the Drawing	13-21
Adding Balloons to the Assembly Views	13-22
Tutorial 1	13-23
Tutorial 2	13-30
Self-Evaluation Test	13-34
Review Questions	13-35
Exercise 1	13-36

Chapter 14: Other Drawing Options

Sketching in the Drawing Mode	14-2
Modifying the Sketched Entities	14-3
User-Defined Drawing Formats	14-8
Retrieving the User-Defined Formats in the Drawings	14-9
Adding and Removing Sheets in the Drawing	14-10
Creating Tables in the Drawing Mode	14-11
Generating the BOM and Balloons in Drawings	14-12
Tutorial 1	14-15
Tutorial 2	14-26
Self-Evaluation Test	14-35
Review Questions	14-36
Exercise 1	14-37

Chapter 15: Surface Modeling

Surface Modeling	15-2
Creating Surfaces in Pro/ENGINEER Wildfire 4.0	15-2
Creating an Extruded Surface	15-2
Creating a Revolved Surface	15-3
Creating a Sweep Surface	15-4
Creating a Blended Surface	15-4
Creating a Swept Blend Surface	15-5
Creating a Helical Sweep Surface	15-5
Creating a Surface by Blending the Boundaries	15-5
Creating a Surface Using the Variable Section Sweep	15-8
Creating Surfaces Using the Style Environment of Pro/ENGINEER Wildfire 4.0	15-9
Style Tools Toolbar	15-9
Surface Editing Tools	15-16
Mirroring Surfaces	15-16
Merging Surfaces	15-17
Trimming Surfaces	15-18
Creating the Fill Surfaces	15-19
Creating the Intersect Curves	15-20
Creating the Offset Surfaces	15-21
Giving Thickness to a Surface	15-23
Converting a Surface to a Solid	15-24
Creating a Round at the Vertex of a Surface	15-24
Tutorial 1	15-25
Tutorial 2	15-35
Self-Evaluation Test	15-43
Review Questions	15-43
Exercise 1	15-44
Exercise 2	15-45

Chapter 16: Working with Sheetmetal Components

Introduction to Pro/Sheetmetal	16-2
Invoking the Sheetmetal Mode	16-2
Introduction to Sheetmetal Walls	16-3
Creating the Unattached Flat Wall	16-4
Creating the Unattached Revolve Wall	16-5
Creating the Unattached Blend Wall	16-6
Creating the Unattached Offset Wall	16-9
Creating Reliefs in Sheetmetal Components	16-10
Creating a Flat Wall	16-11
Creating a Twist Wall	16-14
Creating an Extend Wall	16-16
Creating a Flange Wall	16-17
Creating the Bend	16-21
Creating the Unbend	16-26
Creating the Bend Back	16-27
Creating the Conversion	16-28
Creating Cuts in the Sheetmetal Components	16-30
Creating the Flat Pattern	16-32
Tutorial 1	16-32
Tutorial 2	16-41
Self-Evaluation Test	16-48
Review Questions	16-49
Exercise 1	16-49
Student Projects	1
Index	1